IEC 61850 User Feedback Task Force - Support #548

The start-up behaviour of Boundary Clocks

02/03/2021 02:07 PM - Herbert Falk

Status: Resolved

Priority: Normal

Assignee: Fred Steinhauser

Category: Standard clarification required

Target version:

ID: 29

Source: IOP 2017/50

TF Unique ID: 29 # IOP_2017/50

WG10 Proposal:

Estimated Completion:

Discuss in Upcoming No

Meeting:

To discuss in WG10:

Estimated time:

To send to Hubert for next 9-3 revision **Short Proposal:**

0%

0.00 hour

IEC 61850-9-3 Standard(s):

Needs More No

Information:

Start date: Due date:

% Done:

Assigned TF:

Description

The start-up behaviour of BCs is unsatisfactory.

A BC in holdover (i.e. grandmaster with no time reference), should not return to BC mode when the time reference is restored before its clock oscillator stabilizes to the new grandmaster. The tested BC when connected to the time reference (GPS) immediately forward the GrandMaster time advertising the accuracy of the grandmaster.

Otherwise, all slave clocks below the BC will be subject to the additional jitter of the BC's clock resynchronizing to the GM. This can be tested by disconnecting the BC for some minutes and then reconnect it to the grandmaster.

Proposal descriptions

Assigned to IEC 61850-9-3

History

#1 - 02/15/2021 12:14 PM - Vladan Cvejic

- Subject changed from The start-up behaviour of BCs is unsatisfactory.

A BC in holdover (i.e. grandmaster with no time reference), should not return t to The start-up behaviour of Boundary Clocks

- Category set to Standard clarification required
- Status changed from New to In Progress
- Standard(s) changed from 3-Sep to IEC 61850-9-3
- Discuss in Upcoming Meeting set to No

Checking done.

#2 - 06/21/2022 09:26 AM - Carlos Rodriguez del Castillo

- Status changed from In Progress to Resolved
- Assignee set to Fred Steinhauser
- Proposal descriptions updated

#3 - 05/09/2023 09:32 AM - Carlos Rodriguez del Castillo

- Needs More Information set to No

04/10/2024 1/1