

Issues

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|--------------|----|---------------|---------------------|----------|-------------|---|---------------------|
| 6699 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Behavior of a function while being dynamically blocked | 02/07/2024 04:55 AM |
| 6555 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Behaviour of output contacts when LN is in blocked mode | 02/07/2024 03:14 AM |
| 5968 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | | Change the diagrams in 7-500 to not use yellow lines | 06/05/2023 01:58 AM |
| 6395 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | Waiting for Release | Normal | | Figure 15 SelOpn and SelCIs are incorrect | 02/29/2024 08:06 AM |
| 6482 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Figures 36, 37, 38 | 09/14/2023 07:56 AM |
| 6556 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | How to impact the data quality of a data with respect to the communication links, the intermediate processing, the device hosting it. | 10/26/2023 04:00 AM |
| 6558 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | How to model composed functions | 10/26/2023 04:01 AM |
| 6687 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | SEL | Waiting for Release | Normal | | Incorrect signal direction for GOOSE messages between CSWI and XCBR | 02/29/2024 08:10 AM |
| 6698 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Integrate work from AHTF Control Between Functions | 02/07/2024 02:29 AM |
| 6562 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6155 | New | Normal | | Missing LN for Miniature Circuit Breaker (MCB) | 10/26/2023 05:17 AM |
| 6559 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | Modelling of a Lockout/trip seal-in relay | 04/19/2024 09:19 AM |
| 6557 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | Modelling of various MCB trips | 10/26/2023 04:00 AM |
| 6560 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | Multiple information sources | 10/26/2023 04:02 AM |
| 6554 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | Waiting for Release | Normal | | SwModKey seems to overwrite the CheckCondition.interlockCheck | 02/29/2024 07:52 AM |
| 6496 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Typo in section 13.3 | 08/02/2023 08:54 AM |