

Issues

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-------------|----|--------|--------|----------|---------------------------------|---|---------------------|
| 613 | IEC 61850 User Feedback Task Force | Support | 13 | RTE | Closed | Normal | IEC 61850-7-4 | Clarification of representation of tap changer (LN ATTC, YLTC). | 11/09/2021 02:13 PM |
| 628 | IEC 61850 User Feedback Task Force | Bug | 30 | RTE | Closed | Normal | | Enum type reduction in ICD/SSD file | 03/02/2021 09:54 AM |
| 660 | IEC 61850 User Feedback Task Force | Support | 1 | WG10 | Closed | Normal | IEC 61850-6, TR IEC 61850-90-30 | IED model documentation | 11/21/2023 09:00 AM |
| 606 | IEC 61850 User Feedback Task Force | Bug | 5 | H30 | Closed | Normal | | LGOS/LSVS mandatory | 02/09/2022 07:48 AM |
| 5077 | IEC 61850 User Feedback Task Force | Feature | 1 | MH | Closed | Normal | IEC61850 7-1 | Location of SGCB in LD structures | 03/14/2023 09:10 AM |
| 5090 | IEC 61850 User Feedback Task Force | Feature | 9 | H30 | Closed | Normal | IEC 61850-7-1 Ed2.1 | Mod inheritance when multiple root LD's (GrRef's) exist | 12/07/2021 08:19 AM |
| 620 | IEC 61850 User Feedback Task Force | Feature | 16 | RTE | Closed | Normal | TR 61850-90-29 | New LN LPDO / LPDI in IEC 61850-7-5 | 10/25/2022 08:45 AM |
| 622 | IEC 61850 User Feedback Task Force | Feature | 18 | RTE | Closed | Normal | IEC 61850-7-4 | Parameters not available in standardized LN | 01/17/2023 09:04 AM |
| 664 | IEC 61850 User Feedback Task Force | Improvement | 9 | H30 | Closed | Normal | | Recommended improvements to TISSUE Process | 07/13/2021 04:05 PM |
| 609 | IEC 61850 User Feedback Task Force | Bug | 1 | RTE | Closed | Normal | | The value of the DO LLN0.Health of a LD should inherit from the alarm status of LPHD0.PhyHealth of the IED nesting the LD | 03/02/2021 08:37 AM |