## IEC 61850 User Feedback Task Force - Bug #446

# The actual format required for an ClientLN (used for ReportControl Block reservation) is not specified fully or in an understand

02/03/2021 02:07 PM - Herbert Falk

Status: Closed

Priority: High

Assignee: Category:

Standard clarification required

According to Cathedral City meeting (ref.

Target version:

ID:

Source: IOP 2013

TF Unique ID: 3 # IOP 2013

to UFTF-CathedralMOM20160219) this

issue is closed.

Ed2.1 part6

Estimated Completion:

WG10 Proposal:

Discuss in Upcoming No

Meeting:

Start date:

Due date:

% Done: 100%

Estimated time: 0.00 hour

To discuss in WG10:

**Short Proposal:** Change in part 6 from arbitrary value and

recommended LD0 to "shall be LD0".

Standard(s): IEC 61850-6

Needs More Information:

**Assigned TF:** 

## Description

The actual format required for an ClientLN (used for ReportControl Block reservation) is not specified fully or in an understandable way.

LDInst is required, but for Client only IEDs, there is no LD. The standard indicates to select a random LDInst and provides some guidance. However, in order to insure that there is interoperability and that importers understand that there is NO LDInst, the value to indicate this needs to be standardized. Recommend the use of "none".

### History

## #1 - 02/03/2021 03:58 PM - Herbert Falk

- Priority changed from Normal to High

#### #2 - 02/11/2021 06:30 AM - Carlos Rodriguez del Castillo

- Status changed from New to Closed
- % Done changed from 0 to 100
- Standard(s) set to IEC 61850-6
- Discuss in Upcoming Meeting set to No

Checking done.

04/16/2024 1/1