

## IEC 61850 User Feedback Task Force - Improvement #5970

### SCT behavior needs to be specified regarding mismatch between substation section and IED section

09/20/2022 07:26 AM - Herbert Falk

<b>Status:</b>	In Progress	<b>Start date:</b>	09/20/2022
<b>Priority:</b>	Normal	<b>Due date:</b>	03/20/2023
<b>Category:</b>	Standard clarification required	<b>% Done:</b>	0%
<b>Target version:</b>		<b>Estimated time:</b>	0.00 hour
<b>ID:</b>		<b>To discuss in WG10:</b>	Yes
<b>Source:</b>	2022 f2F IOP	<b>Short Proposal:</b>	
<b>TF Unique ID:</b>		<b>Standard(s):</b>	IEC 61850-6
<b>WG10 Proposal:</b>		<b>Needs More Information:</b>	
<b>Estimated Completion:</b>		<b>Assigned TF:</b>	
<b>Discuss in Upcoming Meeting:</b>	No		
<b>Description</b>			
During the 2022 F2F IOP, a problem with ICD import was found in a SCT tool (other tools did not have an issue with the import). See attached file for description			

#### History

##### #1 - 10/25/2022 09:19 AM - Vladan Cvejic

- Discuss in Upcoming Meeting changed from No to Yes

##### #2 - 11/08/2022 08:24 AM - Carlos Rodriguez del Castillo

- Due date set to 03/20/2023

- Status changed from New to In Progress

- Discuss in Upcoming Meeting changed from Yes to No

- To discuss in WG10 changed from No to Yes

- Standard(s) set to IEC 61850-6

To be discussed at next WG10 plenary meeting.

Substation section in ICD is not forbidden.

The SCT does not know what to do with the ICD substation section. SCT could ignore it, but we need to discuss it.

#### Files

20220711_SCL_Chris_Dyer_SCD_UFTF.docx	174 KB	09/20/2022	Herbert Falk
---------------------------------------	--------	------------	--------------