

## Client - Issues #6172

### client check bits must be tested

11/01/2022 08:36 AM - IEC 61850 TPWG

<b>Status:</b> Resolved	<b>Due date:</b> 12/13/2022
<b>Priority:</b> Normal	
<b>Assignee:</b> Thierry Dufaure	
<b>Category:</b>	
<b>Target version:</b>	
<b>Discuss in Upcoming Meeting:</b> No	<b>Updated Test Document:</b>
<b>Clause Reference:</b>	<b>Test Case ID:</b>
<b>61850 Standard:</b>	<b>Closed Reason:</b> --Not Set--
<b>Triggering Tissue:</b> 1782	<b>Triggering Tissue 2:</b>
<b>Final Decision:</b>	<b>Triggering Tissue 3:</b>
<b>Initial Test Document:</b>	
<b>Description</b>	
per resolution of <a href="https://redmine.ucaiug.org/issues/5319">https://redmine.ucaiug.org/issues/5319</a> client check bits must meet the operational condition of the IED. PIXIT ct15 to be updated	

### History

#### #1 - 11/29/2022 08:23 AM - IEC 61850 TPWG

- Due date changed from 11/15/2022 to 12/13/2022

#### #2 - 12/01/2022 04:46 AM - Thierry Dufaure

- File Solution to redmine 6172 client check bits must be tested (1dec).docx added

- Triggering Tissue set to 1782

See proposal that verifies that according to tissue resolution "the Clients shall provide a means so that the check conditions are appropriately set."

#### #3 - 12/13/2022 08:34 AM - Herbert Falk

- Status changed from In Progress to Resolved

Agreed with the proposed test procedure revision.

### Files

Solution to redmine 6172 client check bits must be tested (1dec).docx 21.6 KB	12/01/2022	Thierry Dufaure
---	------------	-----------------