## Issues

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6411 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Urgent | TR IEC 61850-7-500, TR IEC 61850-90-3 | Update the Model of Circuit Breaker/Disconnector Switch | 10/26/2023 03:08 AM |
| 6422 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Urgent | IEC 61850-7-4xx | Consistent Handling of Abbreviations for Data Object Names Within/Across All Domains and Namespaces | 10/26/2023 02:52 AM |
| 6428 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Urgent | IEC 61850-6 | Next Steps with IEC 61850-90-11 (Publish versus Corrigenda) | 10/26/2023 02:47 AM |
| 6448 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Urgent | TR IEC 61850-7-5 | GOOSE treatment as a command | 02/08/2024 01:53 AM |
| 6143 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | High | TR IEC 61850-7-500, TR IEC 61850-90-3 | Update the Switchgear / Breaker Model | 10/26/2023 03:50 AM |
| 6267 | CIM Joint Issues | CIM Issues | | | New | High | IEC61968-11 | Person and Organization Relationships | 02/15/2023 09:31 AM |
| 6368 | WG14 Part 9 Issues | CIM Issues | | | New | High | 61968-9 | The interplay between events and status measurements should be supported more cleanly | 06/01/2023 11:03 AM |
| 6372 | CIM Joint Issues | CIM Issues | | | New | High | | Inconsistencies in Nameplate data for DERs | 06/12/2023 08:18 AM |
| 6377 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | High | | Update the Switchgear / Breaker Model | 06/14/2023 08:17 AM |
| 6437 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | High | TR IEC 61850-7-5 | Logical Device Inheritance Rules for LocSta | 10/26/2023 03:43 AM |
| 6439 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | High | | Inter-substation GOOSE Naming convention (90-1) | 10/26/2023 03:42 AM |
| 6549 | WG14 Part 9 Issues | CIM Issues | | | New | High | 61968-3, 61968-5, 61968-9 | Switch Contention Issue | 03/07/2024 10:38 AM |
| 6579 | IEC TC57 WG10 Future Work | WG10 Future Work | | Vattenfall | New | High | IEC 61850-6 | How to add utility process name to DOs | 02/19/2024 10:43 AM |
| 6584 | CIM Joint Issues | CIM Issues | | | New | High | | Handling unit multiplier needs joint WG concensus on approach | 11/08/2023 07:03 AM |
| 6619 | CIM Joint Issues | CIM Issues | | | New | High | IEC61968-3 thru IEC61968-11, IEC61970-301, IEC62325-301 | Renaming the CIM UML Model Packages | 12/05/2023 12:37 PM |
| 6620 | WG14 Issues | CIM Issues | | | New | High | | Enterprise Package Name Related Model Updates | 12/05/2023 01:07 PM |
| 6752 | WG14 Part 5 Issues | CIM Issues | | | New | High | | Deprecate Part 5 Modelling | 06/12/2024 07:03 PM |
| 6757 | CIM Joint Issues | CIM Issues | | | New | High | | BasicIntervalSchedule and RegularIntervalSchedule | 05/09/2024 11:49 AM |
| 757 | WG14 Issues | CIM Issues | | | New | Normal | | test | 08/11/2021 11:29 AM |
| 3102 | IEC TC57 WG10 Future Work | WG10 Future Work | | TissueDB | New | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/1744 Clarification of Start Times in StrTm.setCal | 02/08/2024 05:09 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5103 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEEE H27 | New | Normal | IEC 61850-7-3 | Modified/new CDC for IEEE H27 | 02/09/2024 03:21 AM |
| 5104 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG 17 | New | Normal | IEC 61850-6 | Add a type code 'INV' | 02/08/2024 05:14 AM |
| 5121 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-2 | sFt2ab does not verify that the LastModified value is consistent or changes when file is modified | 02/08/2024 05:18 AM |
| 5161 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Refer to methodology document | 01/12/2022 02:43 PM |
| 5162 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Missing actor AM-MAM in Part-1 | 01/12/2022 02:43 PM |
| 5163 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Mobile Workforce Management | 01/12/2022 02:43 PM |
| 5164 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Recommendation / direction on foreign language support | 01/12/2022 02:43 PM |
| 5165 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Message type comment | 01/12/2022 02:43 PM |
| 5166 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Should the section refer to IEC/PAS 62559 ? | 01/12/2022 02:43 PM |
| 5167 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Typo | 01/12/2022 02:43 PM |
| 5168 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Modify "enables a non-compliant software application to use the services." | 01/12/2022 02:43 PM |
| 5169 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Describe the meaning of "DAC" "VRU" | 01/12/2022 02:43 PM |
| 5170 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Comments on Web Services (WS) | 01/12/2022 02:43 PM |
| 5171 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | 61968 RDF statement | 01/12/2022 02:43 PM |
| 5172 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Are profiles related to grammar/syntax or only to an abstract definition of CIM subset ? | 01/12/2022 02:43 PM |
| 5173 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Consider to specify "automated geographical mapping" | 01/12/2022 02:43 PM |
| 5174 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Change "61968-1" to "61968" so "...Figure 1 clarifies the scope of IEC 61968 graphically in terms of" | 01/12/2022 02:43 PM |
| 5175 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Re-organize Figure 1 | 01/12/2022 02:43 PM |
| 5176 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Update Section A.6 / Table A.2 | 01/12/2022 02:43 PM |
| 5177 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Update Section 5.6 / Last paragraph | 01/12/2022 02:43 PM |
| 5178 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Update Section 3.3 / Table 2 | 01/12/2022 02:43 PM |
| 5179 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | To clarify interoperability | 01/12/2022 02:43 PM |
| 5180 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Business functions on HAN / DER / EV | 01/12/2022 02:43 PM |
| 5181 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer support (Part-8) on Demand Response | 01/12/2022 02:43 PM |
| 5182 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Needs a centralized repository for common profiles of entire WG14 | 01/12/2022 02:43 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5183 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Use SGIP actor list and TC8 actor list by reference | 01/12/2022 02:43 PM |
| 5184 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | SGIP Function/Services missing in the Part-1 IRM | 01/12/2022 02:44 PM |
| 5185 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Use case harmonisation between SGIP and EPRI | 01/12/2022 02:44 PM |
| 5186 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Incomplete IEC 61968 Data Model, Profiles and Messages | 01/12/2022 02:44 PM |
| 5187 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | IRM sub-function issues from the Part 4 work | 01/12/2022 02:44 PM |
| 5188 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Key ADMS functionalities: | 01/12/2022 02:44 PM |
| 5189 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Merge EPRI / SGIP Use Case Actors list into Part-1 IRM | 01/12/2022 02:44 PM |
| 5190 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | IoT functions to be accommodated | 01/12/2022 02:44 PM |
| 5191 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Discussion on the IEC 62913 Ed 1 SGAM to identify any gaps for Part-1 IRM | 01/12/2022 02:44 PM |
| 5192 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Move message header (including verbs) and other structures into Part-100 | 01/12/2022 02:44 PM |
| 5193 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | First Responder Outage Data Distribution | 01/12/2022 02:44 PM |
| 5194 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Public Outage Data Distribution | 01/12/2022 02:44 PM |
| 5195 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Typos in Annex A | 01/12/2022 02:44 PM |
| 5196 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | A consolidated IRM for WG13, WG14 and WG16 | 01/12/2022 02:44 PM |
| 5197 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | To align IRM with Archimate 2.x | 01/12/2022 02:44 PM |
| 5198 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Merge EXT business functions to individual Parts | 01/12/2022 02:44 PM |
| 5199 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Need to include functions relevant to Transactive Energy | 01/12/2022 02:44 PM |
| 5200 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Add an activity diagram example in Appendix A.5 | 01/12/2022 02:44 PM |
| 5201 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Document the process on using IEC 62913 series business / system use cases | 01/12/2022 02:44 PM |
| 5202 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Function decomposition | 01/12/2022 02:44 PM |
| 5203 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | IRM team to review SyC work for 61850 actors | 01/12/2022 02:44 PM |
| 5204 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Use of IEC Cloud server for IRM model | 01/12/2022 02:44 PM |
| 5205 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Asset Decision Support (ADS) | 01/12/2022 02:44 PM |
| 5206 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | TC57 WG13 / 14 scope | 01/12/2022 02:44 PM |
| 5207 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Add Business Roles into IRM Model (for Ed.4) | 01/12/2022 02:44 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5208 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | To link ArchiMate to UML on how to use IRM for Part teams | 01/12/2022 02:44 PM |
| 5209 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Outage Management Business Function | 01/12/2022 02:44 PM |
| 5210 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Consider to add Business Actor & Role into the IRM for Ed.4 | 01/12/2022 02:44 PM |
| 5211 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Missing structural analysis function | 01/12/2022 02:44 PM |
| 5212 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | CompatibleUnit association to Conceptual Design Development | 01/12/2022 02:44 PM |
| 5213 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer Account Management (ACT) not following naming convention | 01/12/2022 02:44 PM |
| 5214 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer Installation Management (CIM) rename | 01/12/2022 02:44 PM |
| 5235 | WG14 Issues | CIM Issues | | | New | Normal | | Need to model Vehicles and Tools | 09/13/2022 02:14 AM |
| 5295 | CIM Joint Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4, 61970-301, 61968-13 | Joint issue on ACLineSegment physical modeling clarification | 06/13/2023 09:06 AM |
| 5310 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG 18 | New | Normal | IEC 61850-7-3 | New CDC for IEC/TC 57/WG 18 | 02/08/2024 05:19 AM |
| 5315 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Rename Customer Site Installation Management to CSIM | 02/12/2022 01:08 PM |
| 5379 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | 61968-1 | Construction Planning revision | 11/04/2023 01:04 PM |
| 5380 | WG14 Part 7 Issues | CIM Issues | | | New | Normal | | Customer Installation Management | 10/16/2023 01:17 PM |
| 5878 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-4 | Technical reports to be considered in edition 3 of IEC 61850-7-4 | 02/08/2024 05:20 AM |
| 5882 | CIM Issues | CIM Issues | | | New | Normal | IEC 61970-301 | Model fans, motors, battery systems and similar auxiliary equipment with terminals | 07/13/2022 10:24 AM |
| 5883 | CIM Issues | CIM Issues | | | New | Normal | IEC 61970-301 | Define a standard way to define IEC 61850 data object names for MeasurementTypes and ControlTypes | 07/13/2022 10:31 AM |
| 5884 | CIM Issues | CIM Issues | | | New | Normal | | Modify control model - create DiscreteCommand for enumerations such as raise/lower | 07/13/2022 10:45 AM |
| 5885 | CIM Issues | CIM Issues | | | New | Normal | IEC 61970-301 | Consider CIM measurement classes that can hold multiple measured values with the same timestamp and quality. | 07/13/2022 10:50 AM |
| 5904 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 | New | Normal | IEC 61850-7-4 | Introduce alarm and counter DOs in 7-4 | 02/08/2024 05:22 AM |
| 5927 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC 62361-102 R15 | New | Normal | IEC 61850-7-4 | CIM-61850 Harmonization - Add PosFlwIn data object to measurement classes | 02/08/2024 05:22 AM |
| 5928 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC 62361-102 R9 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - extend tPhaseEnum to match CIM PhaseCode | 02/08/2024 05:23 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5929 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC 62361-102 R8 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - allow Terminals with no connections - use explicit ConnectivityNode.name = None | 02/08/2024 05:08 AM |
| 5930 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC 62361-102 R6 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - mRID attribute in SCL for Equipment, Terminals, ConnectivitNodes | 02/08/2024 05:08 AM |
| 5931 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC 62361-102 R3 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - Add string attribute psrType to tPowerSystemResource. | 02/08/2024 05:08 AM |
| 5932 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC 62361-102 R2 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - Extend list of equipment type codes | 02/08/2024 05:07 AM |
| 5933 | IEC TC57 WG10 Future Work | WG10 Future Work | | FNN Germany | New | Normal | IEC 61850-7-4 | Proposal of a new LN class ASWI | 02/08/2024 05:06 AM |
| 5934 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | TR IEC 61850-10-3, TR IEC 61850-90-20 | Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation | 02/08/2024 05:02 AM |
| 5935 | IEC TC57 WG10 Future Work | WG10 Future Work | | MH | New | Normal | IEC 61850-7-3 | Extension of CDC ASG | 02/08/2024 04:51 AM |
| 5936 | IEC TC57 WG10 Future Work | WG10 Future Work | | TissueDB | New | Normal | IEC 61850-7-4 | IEC61850.Tissue #1756 Event driven schedules – Extend description | 02/08/2024 04:49 AM |
| 5937 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 | New | Normal | IEC 61850-7-4 | Report of current active setting group | 02/08/2024 04:46 AM |
| 5938 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | IEC 61850-7-4 | LN RADR evolution | 02/08/2024 04:44 AM |
| 5939 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | IEC 61850-6 | Mapping of another phases system description to the generic phases phsA, phsB, phsC | 02/08/2024 04:43 AM |
| 5941 | IEC TC57 WG10 Future Work | WG10 Future Work | | TissueDB | New | Normal | IEC 61850-7-4 | IEC61850.Tissue #1755 Event driven schedules – Add DO to stop schedule by event | 02/08/2024 04:39 AM |
| 5942 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | IEC 61850-7-4 | Activation and deactivation of a function by configuration. | 02/08/2024 04:37 AM |
| 5943 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | IEC 61850-7-4 | New LN of group L (as "LTED") to represent the dynamic topology of the substation. | 02/08/2024 04:35 AM |
| 5944 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | IEC 61850-7-4 | Need to create a new LN of group P (Protection), as "PCDP" to represent the Pole Discrepancy Protection. | 02/08/2024 04:27 AM |
| 5950 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9, 61968-11 | How is readCycle used, should the definition be updated? | 05/31/2023 07:13 PM |
| 5964 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-2 | Incorrect Attribute type of TrgOp | 02/08/2024 04:24 AM |
| 5965 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-4 | Schedules - allow updates to single values while schedules are running | 02/08/2024 05:31 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5966 | IEC TC57 WG10 Future Work | WG10 Future Work | | EDF | New | Normal | | Indicate typical SIUnit for every DO with CDC MV would help users + Add a dedicated attribute in NSD files instead of having it in the description ? | 02/09/2024 04:02 AM |
| 5979 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | IEC 61968-9 and others | Meter to UsagePoint relationship should be many-to-many | 06/15/2023 09:32 AM |
| 6144 | IEC TC57 WG10 Future Work | WG10 Future Work | | IOP 2022 | New | Normal | IEC 61850-6 | Need to add SCL mechanism to define a minimum MinTime | 10/26/2023 05:21 AM |
| 6151 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-3 | Use and configuration of ORG within the scope of InRef 7 BlkRef | 10/26/2023 05:20 AM |
| 6153 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/1691 Contradictory statement for Mod.stVal | 10/26/2023 05:19 AM |
| 6154 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/1698 AnOut in GAPC | 10/26/2023 05:19 AM |
| 6155 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-7-500 | https://iec61850.tissue-db.com/tissue/1706 Missing LN for Miniature Circuit Breaker (MCB) | 10/26/2023 05:19 AM |
| 6156 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-3 | https://iec61850.tissue-db.com/tissue/1748 Arrays of CDC | 10/26/2023 05:15 AM |
| 6158 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/1760 - OMulti for MMET data objects | 10/26/2023 05:14 AM |
| 6159 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-90-3 | https://iec61850.tissue-db.com/tissue/1789 SCBR - Coilxxx-Data-Objects shall be Omulti | 10/26/2023 05:14 AM |
| 6160 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-90-29 | https://iec61850.tissue-db.com/tissue/1796 LPHD.PwrSupAlm as Omulti | 10/26/2023 05:13 AM |
| 6161 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-7-5 | https://iec61850.tissue-db.com/tissue/1797 - SwModKey dependency of CSWI from LLN0 | 10/26/2023 05:08 AM |
| 6162 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-7-500 | https://iec61850.tissue-db.com/tissue/1803 - Mechanical Blocking of 3 way switches | 10/26/2023 05:07 AM |
| 6163 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-7-5 | https://iec61850.tissue-db.com/tissue/1804 - When e.g. LocSta = false, result of command to switch DO Mod with "station-control" not clear. | 10/26/2023 05:06 AM |
| 6164 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/1825 - Permission mode for control/setting of a scheduled entity from a client | 10/26/2023 05:03 AM |
| 6165 | IEC TC57 WG10 Future Work | WG10 Future Work | | Tissue DB | New | Normal | TR IEC 61850-7-500 | https://iec61850.tissue-db.com/tissue/1844 - Implementation of SumSwARs in 3-phase circuit breaker inaccurate | 10/26/2023 05:01 AM |
| 6185 | IEC TC57 WG10 Future Work | WG10 Future Work | | 2022 IOP | New | Normal | IEC 61850-6 | SCL Need to differentiate the difference in the number of GOOSE vs R-GOOSE | 10/26/2023 05:01 AM |
| 6194 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | PlannedOutageNotifications needs to support energize/de-energize time/date per UsagePoint. | 11/29/2022 12:50 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6220 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-4 | Parameters not available in standardized GAPC LN - opDITmms, DITmms | 10/26/2023 05:00 AM |
| 6231 | Market Management | CIM Issues | | | New | Normal | | Add the new datatype ESMPDataTypes / SettlementMethodType_String and enumeration | 01/30/2023 10:21 AM |
| 6239 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | UnplannedOutages profile needs ability to capture de-energized and energized times per UsagePoint | 01/31/2023 02:26 PM |
| 6240 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | UnplannedOutages has no way to indicate that the outage should be excluded from reliability reporting. | 01/31/2023 02:59 PM |
| 6241 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | UnplannedOutages does not provide a way to capture affected kVA for IEEE load-based indices | 01/31/2023 03:23 PM |
| 6242 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | OutageArea has nowhere to put the name of the outage area | 01/31/2023 03:26 PM |
| 6243 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | UnplannedOutages is missing OutageArea and AreaKind | 01/31/2023 03:29 PM |
| 6244 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | Part 3 should specify that you can use 'updated' verb | 01/31/2023 03:32 PM |
| 6245 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | | It is not possible to convey that an UnplannedOutage is frozen (prediction is suspended). | 02/01/2023 02:29 PM |
| 6249 | CIM Issues | CIM Issues | | | New | Normal | | Update CIM namespace | 02/06/2023 01:17 PM |
| 6265 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-6 | track changes in SCL to know when a device needs to be updated based on new SCD version | 02/19/2024 10:56 AM |
| 6266 | CIM Issues | CIM Issues | | | New | Normal | IEC61968-11 | Person and Person Role Modeling | 02/15/2023 09:21 AM |
| 6294 | WG14 Issues | CIM Issues | | | New | Normal | 61968-9 | IRM | 03/21/2023 03:46 PM |
| 6295 | WG14 Issues | CIM Issues | | | New | Normal | 61968-9 | Publication of meter firmware versions from Part 9 to Part 4. | 03/21/2023 03:54 PM |
| 6296 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | New "Transformer Compensated" Quality Code needed in Part 9 | 06/01/2023 08:10 AM |
| 6297 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | New Event code needed in Part 9 for DC Voltage | 04/20/2023 09:54 AM |
| 6298 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | New Event codes needed in Part 9 for overvoltage and undervoltage | 03/22/2023 08:48 AM |
| 6316 | IEC TC57 WG10 Future Work | WG10 Future Work | | RTE | New | Normal | IEC 61850-6 | Clarification of using of ValKind, ValImport. | 10/26/2023 04:58 AM |
| 6319 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-6 | maxAttributes - conflicting requirements between GOOSE and reporting | 10/26/2023 04:58 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6321 | CIM Issues | CIM Issues | | | New | Normal | | Update the description of MktActivityRecord | 04/20/2023 03:46 AM |
| 6322 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | New "Low Loss Potential" Quality Code needed in Part 9 | 06/01/2023 08:37 AM |
| 6358 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850 | IEC 61850-7-4 list of abbreviations | 10/26/2023 04:56 AM |
| 6366 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Ground as a phase | 08/17/2023 10:29 AM |
| 6367 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Prepay Metering | 06/01/2023 08:51 AM |
| 6369 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Support EVSE by adding new ReadingTypeID and EndDeviceEvent codes | 10/24/2023 05:09 PM |
| 6376 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | LN PDIF – setting for nominal current | 02/13/2024 05:59 AM |
| 6379 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Clarification on the ctlModel 3/3 | 06/14/2023 08:17 AM |
| 6380 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Clarification on the ctlModel 2/3 | 06/14/2023 08:18 AM |
| 6382 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Clarification on the ctlModel 1/3 | 06/14/2023 08:18 AM |
| 6383 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Single phase and multi phase trip indication for the autorecloser | 06/14/2023 08:19 AM |
| 6384 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | New controllable DO in RREC to define the mode of the recloser of the circuit breaker | 06/14/2023 08:19 AM |
| 6385 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Voltage protection: Undervoltage protection - 3ph operate | 06/14/2023 08:19 AM |
| 6386 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Voltage protection: Overvoltage protection - 3ph operate | 06/14/2023 08:20 AM |
| 6387 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | S/S related applications: Auxiliary circuit supervision | 06/14/2023 08:20 AM |
| 6405 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Schedules - allow updates to single values while schedules are running | 06/20/2023 08:35 AM |
| 6406 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Schedules - add optional data objects to support irregular interval schedules | 06/20/2023 08:36 AM |
| 6407 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Schedules - allow 3 values per time point | 06/20/2023 08:36 AM |
| 6408 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Clarification of addCause | 06/20/2023 08:37 AM |
| 6410 | IEC TC57 WG10 Future Work | WG10 Future Work | | UCA Test. Committee | New | Normal | IEC 61850-7-2 | SBOns to be deprecated in future. | 10/26/2023 04:42 AM |
| 6412 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | IEC 61850-7-3 | Improved SCL Modelling of Function Inputs (InRef/ExtRef) | 10/26/2023 04:41 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6417 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | TR IEC 61850-90-4 | SCL Modelling of the Communication Network and All its Components | 10/26/2023 04:40 AM |
| 6419 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | | Logical Nodes for SLD/Topology Aware Functions | 02/09/2024 04:55 AM |
| 6423 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | TS IEC 61850-80-7 | SCL Control Block | 10/26/2023 04:32 AM |
| 6427 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | TR IEC 61850-90-3 | New Logical Nodes - Battery Charger | 10/26/2023 04:31 AM |
| 6429 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | IEC 61850-7-4xx | Logical Node Groups with Dedicated Namespaces | 10/26/2023 04:28 AM |
| 6432 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | TR IEC 61850-90-30 | SCL Engineering Lifecycle, Types and Security for SCL files and Elements | 10/26/2023 04:26 AM |
| 6441 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Normal | TR IEC 61850-90-14 | Extensions to "Z" Logical Nodes (e.g. ZBAT) | 10/26/2023 04:10 AM |
| 6454 | CIM Issues | CIM Issues | | | New | Normal | 61970-301 | RemoteUnit minor typo in 301 description | 06/28/2023 04:27 PM |
| 6497 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Explanation text of IEC/TR 61850-7-500 clause 10.1.1.2 | 08/02/2023 10:43 AM |
| 6507 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Support IoT sensors by adding durations of time in the seconds range. | 09/21/2023 02:11 PM |
| 6508 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Support the means to identify the accuracy of the measurement in <MeterReadings> | 10/19/2023 11:28 AM |
| 6510 | Market Management | CIM Issues | | | New | Normal | | Add an association between MarketEvaluationPoint and MktPSRType | 08/21/2023 10:11 AM |
| 6511 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Support gas metering with additional event codes and measurements | 08/29/2023 03:29 PM |
| 6512 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Support measurements of configuration status | 09/21/2023 03:05 PM |
| 6524 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/670 - enable/disable LN via setting / new DO SetMod | 10/26/2023 03:54 AM |
| 6529 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Load Control Capabilities | 10/19/2023 08:32 AM |
| 6533 | Market Management | CIM Issues | | | New | Normal | | Add ChargeType to IEC 62325-351 | 09/28/2023 10:56 AM |
| 6534 | Market Management | CIM Issues | | | New | Normal | | Add an association from Series to ChargeType | 12/19/2023 10:32 AM |
| 6535 | Market Management | CIM Issues | | | New | Normal | | Add ChargeComponent to IEC 62325-351 | 09/28/2023 10:58 AM |
| 6536 | Market Management | CIM Issues | | | New | Normal | | Add an association from ChargeType to MarketParticipant | 09/28/2023 10:17 AM |
| 6537 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Harmonizing expressions in 7-500 Ed.1 | 06/13/2024 08:20 AM |
| 6542 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 and 61968-5 | Group Management | 10/19/2023 08:48 AM |
| 6543 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | IEC 61968-9 and others | AccuracyClass for sensors | 10/19/2023 09:43 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6544 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9, 61968-4 | Meter Asset Accuracy Class | 11/16/2023 11:17 AM |
| 6555 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Behaviour of output contacts when LN is in blocked mode | 02/07/2024 03:14 AM |
| 6556 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | How to impact the data quality of a data with respect to the communication links, the intermediate processing, the device hosting it. | 10/26/2023 04:00 AM |
| 6557 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | Modelling of various MCB trips | 06/13/2024 08:25 AM |
| 6558 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | How to model composed functions | 10/26/2023 04:01 AM |
| 6559 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | Modelling of a Lockout/trip seal-in relay | 06/13/2024 07:47 AM |
| 6560 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6443 | New | Normal | | Multiple information sources | 10/26/2023 04:02 AM |
| 6561 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-4 | Modeling of primary equipment | 10/26/2023 04:20 AM |
| 6562 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Redmine: 6155 | New | Normal | | Missing LN for Miniature Circuit Breaker (MCB) | 10/26/2023 05:17 AM |
| 6572 | WG14 Part 11 Issues | CIM Issues | | | New | Normal | | IEC61968CIMVersion class is in triplicate | 11/02/2023 04:07 PM |
| 6573 | CIM Joint Issues | CIM Issues | | | New | Normal | | Profile class duplicates | 11/03/2023 03:34 AM |
| 6578 | IEC TC57 WG10 Future Work | WG10 Future Work | | TF 61850-80-6 | New | Normal | IEC 61850-7-2; IEC 61850-8-1, 80-6 | Extension of the AddCause required to reflect communication issues in multi level control | 02/08/2024 01:50 AM |
| 6582 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | May need to add "kind" attribute to OverheadStructure to be consistent with UndergroundStructure.kind | 11/07/2023 02:04 PM |
| 6583 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Inheritance of Tower and Pole | 11/07/2023 02:05 PM |
| 6597 | CIM Joint Issues | CIM Issues | | | New | Normal | | MarketManagement::Quantity has attribute and relation with the same name "quantity" | 11/14/2023 08:00 AM |
| 6600 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Multipliers | 11/16/2023 11:33 AM |
| 6601 | WG14 Part 11 Issues | CIM Issues | | | New | Normal | 61968-Common | Revise TimeSchedule class | 11/16/2023 11:46 AM |
| 6604 | IEC TC57 WG10 Future Work | WG10 Future Work | | TissueDB | New | Normal | IEC 61850-7-4 | IEC61850.Tissue #1754 Event driven schedules - Type of InSyn missing | 02/08/2024 01:42 AM |
| 6606 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | RTE | New | Normal | | CPU monitoring | 11/21/2023 08:40 AM |
| 6607 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | RTE | New | Normal | | Create DO indicating the source of synchronisation | 11/21/2023 08:49 AM |
| 6611 | WG14 Part 9 Issues | CIM Issues | | | New | Normal | 61968-9 | Formulaic UOMs | 11/27/2023 07:09 PM |
| 6613 | IEC TC57 WG10 Future Work | WG10 Future Work | | TissueDB | New | Normal | IEC 61850-6 | IEC61850 Tissue 1833: Service SettingGroups.ConfSG clarification | 02/08/2024 01:38 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6636 | WG14 Issues | CIM Issues | | | New | Normal | 61968-3;61968-4;61968-5;61968-6 | Update Name model for all XSD based profiles | 12/13/2023 07:27 AM |
| 6656 | CIM Joint Issues | CIM Issues | | | New | Normal | | Add altitudeCompensation to EndDeviceInfo | 12/21/2023 10:20 AM |
| 6664 | Market Management | CIM Issues | | | New | Normal | | Add an association from MktActivityRecord to ChargeGroup | 01/05/2024 06:44 AM |
| 6665 | Market Management | CIM Issues | | | New | Normal | | Add ChargeGroup to ESMP and move ChargeGroup to MarketCommon | 01/05/2024 07:08 AM |
| 6666 | Market Management | CIM Issues | | | New | Normal | | Add PhaseCount to ESMP | 01/05/2024 07:27 AM |
| 6667 | Market Management | CIM Issues | | | New | Normal | | Add an association from ChargeType to Period | 01/05/2024 07:58 AM |
| 6668 | Market Management | CIM Issues | | | New | Normal | | Add VATObliged attribute to ChargeType | 01/05/2024 09:03 AM |
| 6669 | Market Management | CIM Issues | | | New | Normal | | Add VATLevel attribute to ChargeType | 01/05/2024 09:17 AM |
| 6677 | CIM Joint Issues | CIM Issues | | | New | Normal | IEC61968-11 Edition 4, IEC62325-301 Edition 4 | Document Class Generalization Refinement | 02/08/2024 10:33 AM |
| 6678 | WG14 Part 11 Issues | CIM Issues | | | New | Normal | | Refactoring Outage Class Modeling | 01/16/2024 11:45 AM |
| 6684 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | discussion | New | Normal | | Proposal to deprecate 'LocSta' in X and Y group LN classes | 01/22/2024 02:50 AM |
| 6686 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | Tissue #1892 | New | Normal | | Description of the different control methods to change position of OLTC (in automatic, manual modes) | 01/23/2024 11:02 AM |
| 6698 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Integrate work from AHTF Control Between Functions | 02/07/2024 02:29 AM |
| 6699 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Behavior of a function while being dynamically blocked | 06/13/2024 08:28 AM |
| 6700 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-6 | Investigate to align to the new CIM model of transformers | 02/08/2024 05:26 AM |
| 6701 | IEC TC57 WG10 Future Work | WG10 Future Work | | | New | Normal | IEC 61850-7-3 | Integration of proposed and canceled amendment 2 of part 7-3 | 02/08/2024 05:25 AM |
| 6703 | IEC TC57 WG10 Future Work | WG10 Future Work | | Ed 3 review | New | Normal | IEC 61850-7-4, IEC TS 61850-80-4 | Part 80-4 Mapping to COSEM : add reactive and apparent energy data objects to MMTR and MMTN | 02/09/2024 02:43 PM |
| 6714 | IEC TC57 WG10 Future Work | WG10 Future Work | | IEC PAS 61850-90-3 | New | Normal | | Improve the models used for power regulation | 02/20/2024 11:04 AM |
| 6729 | CIM Joint Issues | CIM Issues | | | New | Normal | | Multi-commodity Support | 03/07/2024 11:10 AM |
| 6730 | CIM Joint Issues | CIM Issues | | | New | Normal | | Evaluation of the Pipeline Open Data Standard (PODS) | 03/07/2024 11:09 AM |
| 6734 | WG16 Issues | CIM Issues | | | New | Normal | | Review use/inheritance of Document by UCA TF 16 classes, profile, standards | 03/11/2024 09:58 AM |
| 6744 | WG14 Part 3 Issues | CIM Issues | | | New | Normal | 61968-3 | CrewStatusKind enumeration is missing values for deassignment | 03/26/2024 11:59 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6768 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Control of substituted or blocked objects | 04/19/2024 05:08 AM |
| 6788 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Integration of the "Regensburg" decisions on local/remote into the relevant parts of IEC 61850 | 05/16/2024 11:17 AM |
| 6789 | CIM Joint Issues | CIM Issues | | | New | Normal | | Need new cdPerm2 enumerated value for Unit Symbol | 05/16/2024 03:29 PM |
| 6801 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Modelling of 3 position switches | 06/05/2024 08:49 AM |
| 6819 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | discussion | New | Normal | | Reworking IEC/TR 61860-7-500 clause 10.1.1.2 about pole discrepancy | 07/26/2024 04:43 AM |
| 6820 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | Revising IEC/TR 61860-7-500 clause 11.1.3 about the use of GGIO and GAPC, Figures 12 and 23 | 07/26/2024 03:02 AM |
| 6832 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | New | Normal | | CPOW interface with CSWI and XCBR needs to be revise. | 07/25/2024 10:10 AM |
| 6835 | Test Procedure Issues | Issues | | | New | Normal | | Impact of publication of IEC 61850-6 Edition 2.2 on Edition 2.1 certification of Server/Client and Tools | 08/07/2024 01:58 AM |
| 6870 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Cable Info classes | 09/06/2024 01:27 PM |
| 6881 | SCL Tooling | Issues | | | New | Normal | | tDfe6b the SCT is not allowed to create new bindings | 10/01/2024 08:12 AM |
| 6890 | Market Management | CIM Issues | | | New | Normal | | Addition of Permission class to MarketManagement | 10/01/2024 01:50 AM |
| 6897 | Server | Issues | | | New | Normal | | sCnf7, sCnf66 services can be defined on IED and AccessPoint when identical | 09/05/2024 07:27 AM |
| 6902 | Client | Issues | | | New | Normal | | cLogN5 has no Ed1 specific error code | 09/11/2024 02:27 AM |
| 6903 | Server | Issues | | | New | Normal | | sGos20 requires the ICT to accept invalid SCD files due to FC out of tFCEnum | 09/11/2024 04:13 AM |
| 6905 | Server | Issues | | | New | Normal | | sSBOes8  why is time validated for Cancel but not for the Operate | 09/11/2024 10:19 AM |
| 6924 | WG13 Issues | CIM Issues | | | New | Normal | | Add subclasses of SubSchedulingArea | 09/16/2024 04:17 PM |
| 6926 | WG13 Issues | CIM Issues | | | New | Normal | | Domain RotationSpeed | 09/17/2024 09:07 AM |
| 6983 | WG13 Issues | CIM Issues | | | New | Normal | | Diagram HyperLink | 10/02/2024 10:09 AM |
| 6988 | Server | Issues | | | New | Normal | | sCtl16 in TP1.3 is in conflict with 7-4 Table B.1 | 09/20/2024 06:10 AM |
| 6989 | Server | Issues | | | New | Normal | | sSvp14 for Backwards the max MSVID is 34 char not 32 | 09/20/2024 06:29 AM |
| 6990 | Server | Issues | | | New | Normal | | sSvp9 step 4 PTP class not 6/7 with/without holdover time? | 10/01/2024 08:46 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6991 | Server | Issues | | | New | Normal | | sCnf75 not all devices have control objects | 10/01/2024 08:30 AM |
| 6993 | WG13 Issues | CIM Issues | | | New | Normal | | Modeling of multiple inverters mapping to PCC | 09/20/2024 10:24 AM |
| 6995 | WG13 Issues | CIM Issues | | | New | Normal | | Add transmission composite load model | 09/20/2024 11:26 AM |
| 7002 | WG13 Issues | CIM Issues | | | New | Normal | IEC 61970-600-2, IEC 61970-456 | BusbarSection SvStatus must be updated in publications | 09/24/2024 11:22 AM |
| 7007 | WG13 Issues | CIM Issues | | | New | Normal | IEC 61970-600-1 | IEC 61970-600-1 General Requirements clause updates. | 09/25/2024 05:48 PM |
| 7009 | Market Management | CIM Issues | | | New | Normal | | Addition of EnergyCharacteristics to MarketManagement | 10/10/2024 11:17 AM |
| 7025 | CIM Joint Issues | CIM Issues | | | New | Normal | | Standardized the use of flow/direction across working groups and CIM packages (Grid, Enterprise, Market) | 10/10/2024 11:19 AM |
| 6413 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | IEC 61850-80-7 | Asset Management of Setting & Configuration Data | 02/08/2024 05:32 AM |
| 6430 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | IEC 61850-6 | Management of SCL File Sizes (Compression Techniques, Handling of Privates) | 02/08/2024 03:17 AM |
| 6433 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | | SCL Extensions (partial configuration updates in a top-down approach, mixed editions with private CDCs, etc.) | 02/08/2024 03:03 AM |
| 6435 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | IEC 61850-9-2 | Compression of Sample Value Messages | 02/08/2024 05:36 AM |
| 6436 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | TR IEC 61850-10-3 | SCL Modelling of the Test Equipment | 02/08/2024 02:36 AM |
| 6446 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | TR IEC 61850-7-500 | SCL Modelling of Fault Measurements (RFMX) | 02/08/2024 02:12 AM |
| 6447 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | New | Low | | Enhanced Quality Information for Measurements (accuracy classes, update periods, filter applied, algorithm applied, etc.) | 02/08/2024 03:16 AM |
| 7010 | Client | Issues | | | New | Low | | UCA logo is missing on the certificate template of the goose performance | 10/01/2024 08:16 AM |
| 5375 | WG13 Issues | CIM Issues | | | In Progress | Urgent | | Clean up transformer documentation - Margaret removed paragraphs from Part-11 and see where they fit [GMDM #5] (align xf descriptions in 61870-301, -457 and 61968-11, -13) | 09/18/2024 10:23 AM |
| 6414 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | In Progress | Urgent | | Golden Single Line Diagram For All SCL/GCL/HCL Examples | 10/26/2023 02:58 AM |
| 6420 | IEC TC57 WG10 Future Work | WG10 Future Work | | WG10 Fall workshop | In Progress | Urgent | IEC 61850-6, IEC 61850-7-x, IEC 61850-8-1, IEC 61850-9-2 | Validation of SCL Files Using Object Constraint Language (OCL) | 10/26/2023 02:57 AM |
| 5076 | WG13 Issues | CIM Issues | | | In Progress | High | 61970-301, 61970-452, 61970-456 | Convention and usage of operational limits of GeneratingUnit and injections | 09/18/2024 11:47 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5248 | WG14 Part 6 Issues | CIM Issues | | | In Progress | High | 61968-6 | Contract work | 11/09/2023 11:44 AM |
| 5250 | WG14 Part 11 Issues | CIM Issues | | | In Progress | High | | Document identification | 10/17/2023 03:04 AM |
| 5309 | WG13 Issues | CIM Issues | | | In Progress | High | | Support on FACTS device modeling | 09/19/2024 02:29 PM |
| 6663 | WG13 Issues | CIM Issues | | | In Progress | High | IEC 61970-456 | The SSH profile needs to be revisited and updated for consistency. | 09/19/2024 09:54 AM |
| 6680 | WG13 Issues | CIM Issues | | | In Progress | High | 61970-456 | Support time series/schedule for SSH | 09/19/2024 02:13 PM |
| 556 | IEC 61850 User Feedback Task Force | Support | 3 | H30 | In Progress | Normal | IEC 61850-90-20 | Rendundant CT/TT measurements | 06/21/2022 02:09 AM |
| 605 | IEC 61850 User Feedback Task Force | Improvement | 4 | H30 | In Progress | Normal | IEC 61850-10-3 | Test and Simulation mode questions | 06/21/2022 02:09 AM |
| 607 | IEC 61850 User Feedback Task Force | Support | 6 | H30 | In Progress | Normal | IEC 61850-80-6 (90-2) | LPHD.Sim management | 06/21/2022 02:09 AM |
| 608 | IEC 61850 User Feedback Task Force | Feature | 7 | H30 | In Progress | Normal | IEC 61850-90-xx | Comprehensive set of requirements covering validation and supervision of all IEC 61850 communications | 06/21/2022 02:09 AM |
| 611 | IEC 61850 User Feedback Task Force | Bug | 5 | RTE | In Progress | Normal | IEC 61850-7-4 / IEC 61850-80-6 | Need a new DO (ENUM) to identify the protocol used for the SCADA exchange, in LN ITCI | 11/07/2023 08:29 AM |
| 621 | IEC 61850 User Feedback Task Force | Feature | 17 | RTE | In Progress | Normal | IEC 61850-7-4/7-500 | New controllable DO in RREC to define the mode of the recloser of the circuit breaker | 05/11/2021 10:08 AM |
| 623 | IEC 61850 User Feedback Task Force | Feature | 19 | RTE | In Progress | Normal | | New LN of group L (as "LPLE") representing a group of LED | 03/02/2021 09:42 AM |
| 677 | IEC 61850 User Feedback Task Force | Feature | 50 | RTE | In Progress | Normal | IEC 61850-7-4 | Impact of IEC 61869-13 (SAMU) | 02/28/2023 09:42 AM |
| 3098 | IEC 61850 User Feedback Task Force | Improvement | 1 | WG17 | In Progress | Normal | | Need to Change 8-1 to allow multiple DOs to be written | 03/29/2022 09:36 AM |
| 5015 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61970-501 | Create validation constaints for the UML model and profile | 09/22/2022 03:11 PM |
| 5016 | WG13 Issues | CIM Issues | | | In Progress | Normal | | OperationalLimit for BranchGroupNeed a means to apply the | 09/19/2024 01:42 PM |
| 5097 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61970-301, 61970-452 | Allow OperationalLimitSet to be described by a Season by adding a new association between OperationalLimitSet and Season | 09/18/2024 12:00 PM |
| 5124 | IEC 61850 User Feedback Task Force | Feature | 3 | TF 61850-80-6 | In Progress | Normal | IEC 61850-80-6 | Telemonitoring blocking | 12/21/2021 09:26 AM |
| 5336 | IEC 61850 User Feedback Task Force | Feature | 4 | TF 61850-80-6 | In Progress | Normal | IEC 61850-7-2; IEC 61850-8-1, 80-6 | Extension of the AddCause required to reflect communication issues in multi level control | 11/07/2023 08:28 AM |
| 5374 | IEC 61850 User Feedback Task Force | Feature | | RTE | In Progress | Normal | IEC 61850-7-4 | Creation of a new LN for protection function | 02/28/2023 09:42 AM |
| 5803 | WG16 Issues | CIM Issues | | | In Progress | Normal | | Add meterReadingPeriodicity attribute (String) in the MarketEvaluationPoint class | 09/15/2022 04:01 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5868 | WG13 Issues | CIM Issues | | | In Progress | Normal | | New BusSegment for busbar modeling | 09/19/2024 03:01 PM |
| 5886 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61968-13 | CDPSM missing TransformerTank and TransformerTankEnd | 09/18/2024 08:26 AM |
| 5894 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61968-13 | CDPSM conflicting roles OperationalLimitType.OperationalLimit and OperationalLimit.OperationalLimitType | 09/18/2024 11:05 AM |
| 5947 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61970-456 | Description classes inheriting from IdentifiedObject | 09/19/2024 11:04 AM |
| 5970 | IEC 61850 User Feedback Task Force | Improvement | | 2022 f2F IOP | In Progress | Normal | IEC 61850-6 | SCT behavior needs to be specified regarding mismatch between substation section and IED section | 11/08/2022 08:24 AM |
| 6147 | WG13 Issues | CIM Issues | | | In Progress | Normal | | [GMDM #1] Streamlining of tank-based transformer modelling | 09/18/2024 09:26 AM |
| 6175 | IEC 61850 User Feedback Task Force | Bug | | 2022 IOP | In Progress | Normal | IEC 61850-6 | SCL SICS requires SNTP even with 2.1 where PTP is the preferred method. | 11/07/2023 08:21 AM |
| 6216 | IEC 61850 User Feedback Task Force | Feature | 51 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized LN - SetPhNum | 02/28/2023 09:42 AM |
| 6217 | IEC 61850 User Feedback Task Force | Feature | 52 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized LN - NamAccRtg | 02/28/2023 09:42 AM |
| 6218 | IEC 61850 User Feedback Task Force | Feature | 53 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized LN - PhyConnITF | 02/28/2023 09:42 AM |
| 6219 | IEC 61850 User Feedback Task Force | Feature | 54 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized LN - VRtg, ARtg and HzRtg | 02/28/2023 09:42 AM |
| 6221 | IEC 61850 User Feedback Task Force | Feature | 56 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized GAPC LN - OnOff | 02/28/2023 09:42 AM |
| 6222 | IEC 61850 User Feedback Task Force | Feature | 57 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized GAPC LN - SetNb | 02/28/2023 09:42 AM |
| 6223 | IEC 61850 User Feedback Task Force | Feature | 58 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized GAPC LN - StrVal | 02/28/2023 09:42 AM |
| 6224 | IEC 61850 User Feedback Task Force | Feature | 59 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized GAPC LN - SetRef | 02/28/2023 09:42 AM |
| 6225 | IEC 61850 User Feedback Task Force | Feature | 60 | RTE | In Progress | Normal | IEC 61850-7-4 | Parameters not available in standardized LN - SetPhsOrig | 02/28/2023 09:42 AM |
| 6299 | WG13 Issues | CIM Issues | | | In Progress | Normal | | OperationalLimitType; add an attribute to hold the "type" of limit, such as Emergency, Normal, ... | 09/18/2024 12:05 PM |
| 6341 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61970-301, 61970-452 | [GMDM #4] Support for transformer type designation / determination | 09/18/2024 08:56 AM |
| 6343 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61970-301, 61970-452, 61968-13 | [GMDM #7] Convention for use of xxxPhase classes | 09/18/2024 04:38 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6346 | WG13 Issues | CIM Issues | | | In Progress | Normal | 61970-301,, 61968-13 | [GMDM #14] Indicating starting point for feeder tracing | 09/18/2024 04:33 PM |
| 6347 | WG13 Issues | CIM Issues | | | In Progress | Normal | | [GMDM #15] Add a limited amount of ‘structure’ modeling to distribution grid models | 09/19/2024 10:15 AM |
| 6375 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | XCBR LN new DO to describe withdrawable circuit breaker | 08/24/2023 07:57 AM |
| 6378 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 1/8 | 10/05/2023 08:56 AM |
| 6388 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 2/8 | 10/05/2023 08:55 AM |
| 6389 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 3/8 | 10/05/2023 08:55 AM |
| 6390 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 4/8 | 10/05/2023 08:55 AM |
| 6391 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 5/8 | 10/05/2023 08:55 AM |
| 6392 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 6/8 | 10/05/2023 08:55 AM |
| 6393 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 7/8 | 10/05/2023 08:55 AM |
| 6394 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Clarifications on the local/remote concept 8/8 | 09/14/2023 08:04 AM |
| 6482 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Figures 36, 37, 38 | 09/14/2023 07:56 AM |
| 6499 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Explanation text on the application of check conditions | 10/05/2023 08:57 AM |
| 6500 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Parameters to enforce the checking of interlocking and synchronism | 10/05/2023 08:57 AM |
| 6617 | SCL Tooling | Issues | | | In Progress | Normal | | tlieN1 - can a popup warning be considered as 'not allowed' | 10/01/2024 08:15 AM |
| 6725 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | RTE | In Progress | Normal | | Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation | 02/29/2024 09:07 AM |
| 6726 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | RTE | In Progress | Normal | | New LN of group L (as "LTED") to represent the dynamic topology of the substation. | 02/29/2024 09:07 AM |
| 6739 | IEC 61850 User Feedback Task Force | Feature | | | In Progress | Normal | | How to deal with 'Beh' and 'Health' of isolated functions | 04/09/2024 08:43 AM |
| 6773 | WG13 Issues | CIM Issues | | | In Progress | Normal | IEC61970-301, IEC61970-452 | DC device containment rules need to be updated | 09/19/2024 04:24 PM |
| 6787 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | | In Progress | Normal | | Harmonization of Table 4 with Figure 22 | 06/13/2024 08:44 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6809 | WG13 Issues | CIM Issues | | | In Progress | Normal | IEC 61970-301 | Migrate approved Ext* Protection Equipment and Network Code extensions into normative CIM | 09/19/2024 01:57 PM |
| 6871 | WG13 Issues | CIM Issues | | | In Progress | Normal | IEC 61970-456, IEC 61970-450 | Review the existing TP and SV profiles to determine a more logical split | 09/18/2024 05:10 PM |
| 6875 | Client | Issues | | | In Progress | Normal | | Update Client certificate template following the server certificate template | 10/01/2024 08:12 AM |
| 6886 | Server | Issues | | | In Progress | Normal | | Tissue 1897Data-change and data-update inclusion bitstring bits set in a report | 10/01/2024 08:04 AM |
| 6896 | Server | Issues | | | In Progress | Normal | | sSrv17 | 10/01/2024 08:03 AM |
| 6904 | Server | Issues | | | In Progress | Normal | | sCtl14 in TP1.3 does not reflect the Issue #6214 resolution | 09/27/2024 03:40 AM |
| 7001 | IEC 61850 User Feedback Task Force | Bug | | | In Progress | Normal | | Presence condition of DO in statistic Logical Nodes | 09/24/2024 09:05 AM |
| 6711 | 61850-7-5 and 61850-7-500 | IEC61850-7-5 | | WG10 Fall workshop | In Progress | Low | | SCL Modelling of Fault Measurements (RFMX) | 02/29/2024 08:33 AM |
| 439 | IEC 61850 User Feedback Task Force | Bug | 2 | Vattenfall | Resolved | High | IEC 61850-6 | How to add utility process name to DOs | 11/07/2023 09:04 AM |
| 632 | IEC 61850 User Feedback Task Force | Support | 8 | H30 | Resolved | High | IEC 61850-9-2, IEC 61869-9 | APPID 0x4000 - Sampled Values | 12/05/2023 09:16 AM |
| 636 | Client | Issues | | | Resolved | High | | Mandate RCB reservation for Ed2.0 client and Amd1 server | 04/20/2021 02:23 PM |
| 6792 | Client | Issues | | | Resolved | High | | Discrepancies between certificate tables and testprocedures - client testprocedure | 06/11/2024 08:06 AM |
| 438 | IEC 61850 User Feedback Task Force | Feature | 1 | Vattenfall | Resolved | Normal | IEC 61850-4 | The engineering-process is well defined for a green field / new IEC 61850 substation but needs clarification for refurbishment | 12/05/2023 08:26 AM |
| 519 | IEC 61850 User Feedback Task Force | Support | 1 | UFTF | Resolved | Normal | 80-7 | Optionality in DOI NamPlt, PhyNam resp. in ICD/IID file: IED.manufacturer, .IED.type, makes a device recognition in a machine to | 06/05/2023 01:58 AM |
| 525 | IEC 61850 User Feedback Task Force | Support | 6 | IOP_2017/8 | Resolved | Normal | IEC 61850-6 | IEC 61850-6 does not allow the authentication configuration (none, password, weak, strong or certificate) to be used for Client | 05/09/2023 09:32 AM |
| 547 | IEC 61850 User Feedback Task Force | Support | 28 | IOP_2017/49 | Resolved | Normal | IEC 61850-9-3 | Requirement for Boundary Clocks to adjust the clock accuracy to reflect their actual accuracy, not that of their grandmaster | 05/09/2023 09:32 AM |
| 548 | IEC 61850 User Feedback Task Force | Support | 29 | IOP_2017/50 | Resolved | Normal | IEC 61850-9-3 | The start-up behaviour of Boundary Clocks | 05/09/2023 09:32 AM |
| 549 | IEC 61850 User Feedback Task Force | Support | 30 | IOP_2017/51 | Resolved | Normal | IEC 61850-9-3 | Standard should clarify the relation between the PTP clock clockQuality signals and the timeQuality in TimeStamp | 05/09/2023 09:32 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 550 | IEC 61850 User Feedback Task Force | Support | 31 | IOP_2017/52 | Resolved | Normal | IEC 61850-9-3 | Incorrect variance adjustment for Time Masters with degradation (loss of GPS) | 05/09/2023 09:32 AM |
| 551 | IEC 61850 User Feedback Task Force | Support | 32 | IOP_2017/53 | Resolved | Normal | IEC 61850-9-3 | IEC/IEEE 61850-9-3 - Sync messages have to be padded to the same length as the Pdelay_Req/Pdelay_Resp messages | 05/09/2023 09:32 AM |
| 552 | IEC 61850 User Feedback Task Force | Support | 33 | IOP_2017/54 | Resolved | Normal | IEC 61850-9-3 | Disruption of network when TC are not set to the correct domain | 05/09/2023 09:32 AM |
| 553 | IEC 61850 User Feedback Task Force | Support | 34 | IOP_2017/55 | Resolved | Normal | IEC 61850-9-3 | IEC/IEEE 61850-9-3 should clarify the meaning and use of TimeTraceable and FrequencyTraceable | 05/09/2023 09:32 AM |
| 554 | IEC 61850 User Feedback Task Force | Support | 1 | H30 | Resolved | Normal | | Performance requirement for SV and implications to Protection applications | 05/09/2023 09:32 AM |
| 572 | IEC 61850 User Feedback Task Force | Support | 44 | ENTSO-E | Resolved | Normal | IEC 61850-7-500 | S/S related applications: Auxiliary circuit supervision | 05/09/2023 09:32 AM |
| 579 | IEC 61850 User Feedback Task Force | Support | 51 | ENTSO-E | Resolved | Normal | IEC 61850-7-500 | Voltage protection: Overvoltage protection - 3ph operate | 05/09/2023 09:32 AM |
| 580 | IEC 61850 User Feedback Task Force | Support | 52 | ENTSO-E | Resolved | Normal | IEC 61850-7-500 | Voltage protection: Undervoltage protection - 3ph operate | 05/09/2023 09:32 AM |
| 590 | IEC 61850 User Feedback Task Force | Feature | 1800 | IOP_2019 | Resolved | Normal | IEC 61850-6 | ICT fails to check validity of the SCD file regarding the IED constraints | 11/07/2023 08:22 AM |
| 597 | IEC 61850 User Feedback Task Force | Feature | 1120 | IOP_2019 | Resolved | Normal | 61850-90-28 | SCTs updating the confRev of 9-2 LE Sampled Value streams - problem with subscription to test tool SV injection | 05/09/2023 09:32 AM |
| 599 | IEC 61850 User Feedback Task Force | Feature | 12 | IOP_2019 | Resolved | Normal | | ICD files do not match requirements (several issues) - increase in engineering efforts | 06/05/2023 01:58 AM |
| 602 | IEC 61850 User Feedback Task Force | Feature | 1742 | IOP_2019 | Resolved | Normal | IEC 61850-9-3 | Merging Unit standard requires MU clock to jump on PTP time jumps, which is not true for Boundary Clocks. | 05/09/2023 09:32 AM |
| 610 | IEC 61850 User Feedback Task Force | Improvement | 2 | RTE | Resolved | Normal | IEC 61850-6 | Mapping of another phases system description to the generic phases phsA, phsB, phsC | 05/09/2023 09:32 AM |
| 612 | IEC 61850 User Feedback Task Force | Feature | 11 | RTE | Resolved | Normal | IEC 61850-7-4 | Need to create a new LN of group P (Protection), as "PCDP" to represent the Pole Discrepancy Protection. | 05/09/2023 09:32 AM |
| 618 | IEC 61850 User Feedback Task Force | Improvement | 14 | RTE | Resolved | Normal | IEC 61850-90-3 | Evolution of DO SumSqA of LN SPTRExt | 05/09/2023 09:32 AM |
| 619 | IEC 61850 User Feedback Task Force | Feature | 15 | RTE | Resolved | Normal | | New LN of group L (as "LTED") to represent the dynamic topology of the substation. | 05/09/2023 09:32 AM |
| 624 | IEC 61850 User Feedback Task Force | Support | 21 | RTE | Resolved | Normal | IEC 61850-6 | Clarification of using of ValKind, ValImport. | 05/09/2023 09:32 AM |
| 625 | IEC 61850 User Feedback Task Force | Improvement | 22 | RTE | Resolved | Normal | IEC 61850-7-4 | LN RADR evolution | 12/05/2023 08:31 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 626 | IEC 61850 User Feedback Task Force | Improvement | 23 | RTE | Resolved | Normal | TR IEC 61850-90-4, IEC 61850-6 | Extension of P-type to describe connexion type (PhysCon) | 12/05/2023 08:52 AM |
| 627 | IEC 61850 User Feedback Task Force | Feature | 29 | RTE | Resolved | Normal | IEC 61850-7-4 | Activation and deactivation of a function by configuration. | 05/09/2023 09:32 AM |
| 629 | IEC 61850 User Feedback Task Force | Improvement | 35 | RTE | Resolved | Normal | IEC TR 61850-90-29 | TCTR and TVTR new DO to identify physical terminal allocation in the IED | 01/16/2024 08:11 AM |
| 630 | IEC 61850 User Feedback Task Force | Improvement | 43 | RTE | Resolved | Normal | IEC 61850-7-500 | XCBR LN new DO to describe withdrawable circuit breaker | 05/09/2023 09:32 AM |
| 633 | IEC 61850 User Feedback Task Force | Improvement | 1 | ZIV | Resolved | Normal | IEC 61850-4 | Initial values of paramRev and valRev | 11/21/2023 09:09 AM |
| 647 | IEC 61850 User Feedback Task Force | Support | 57 | ENTSO-E | Resolved | Normal | IEC 61850-7-500 | Single phase and multi phase trip indication for the autorecloser | 05/09/2023 09:32 AM |
| 658 | Client | Issues | | | Resolved | Normal | | Verify Client does process a report before RptEna write respond+ | 06/01/2021 08:23 AM |
| 667 | IEC 61850 User Feedback Task Force | Improvement | 4 | WG10 | Resolved | Normal | IEC 61850-7-4 | Report of current active setting group | 06/05/2023 01:58 AM |
| 672 | IEC 61850 User Feedback Task Force | Improvement | 46 | RTE | Resolved | Normal | TR IEC 61850-7-500 | Create DO indicating the source of synchronisation | 11/21/2023 08:49 AM |
| 673 | IEC 61850 User Feedback Task Force | Improvement | 47 | RTE | Resolved | Normal | TR IEC 61850-7-500 | CPU monitoring | 11/21/2023 08:40 AM |
| 675 | IEC 61850 User Feedback Task Force | Support | 48 | RTE | Resolved | Normal | IEC 61850-7-4 Ed2.1 | Clarification of blocked mode | 11/21/2023 08:38 AM |
| 676 | IEC 61850 User Feedback Task Force | Support | 49 | RTE | Resolved | Normal | IEC 61850-7-5 | Clarification of addCause | 06/05/2023 01:58 AM |
| 3099 | IEC 61850 User Feedback Task Force | Improvement | 1 | TissueDB | Resolved | Normal | IEC 61850-7-4 | IEC61850.Tissue #1756 Event driven schedules – Extend description | 06/05/2023 01:58 AM |
| 3100 | IEC 61850 User Feedback Task Force | Improvement | 2 | TissueDB | Resolved | Normal | IEC 61850-7-4 | IEC61850.Tissue #1754 Event driven schedules - Type of InSyn missing | 06/05/2023 01:58 AM |
| 3101 | IEC 61850 User Feedback Task Force | Bug | 3 | TissueDB | Resolved | Normal | IEC 61850-7-4 | IEC61850.Tissue #1755 Event driven schedules – Add DO to stop schedule by event | 06/05/2023 01:58 AM |
| 3115 | Client | Issues | | | Resolved | Normal | | Forward compatibility to Amd1 server with pre-assigned URCB/BRCB | 06/14/2022 08:35 AM |
| 5078 | IEC 61850 User Feedback Task Force | Feature | 2 | MH | Resolved | Normal | IEC 61850-7-1 / 7-2 Ed2.1 / 7-5/7-500 | Clarification on the ctlModel 1/3 | 06/05/2023 01:58 AM |
| 5079 | IEC 61850 User Feedback Task Force | Feature | 3 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1, 7-500 | Clarification on the ctlModel 2/3 | 06/05/2023 01:58 AM |
| 5080 | IEC 61850 User Feedback Task Force | Feature | 4 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1 ,7-500 | Clarification on the ctlModel 3/3 | 06/05/2023 01:58 AM |
| 5081 | IEC 61850 User Feedback Task Force | Feature | 5 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1/7-4 Ed2.1 Annex B/7-500 | Clarifications on the local/remote concept 1/8 | 06/05/2023 01:58 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5082 | IEC 61850 User Feedback Task Force | Feature | 6 | MH | Resolved | Normal | IEC 61850-7-4,7-5 | Clarifications on the local/remote concept 2/8 | 06/05/2023 01:58 AM |
| 5083 | IEC 61850 User Feedback Task Force | Feature | 7 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1,7-5 | Clarifications on the local/remote concept 3/8 | 06/05/2023 01:58 AM |
| 5084 | IEC 61850 User Feedback Task Force | Feature | 8 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1,7-5 | Clarifications on the local/remote concept 4/8 | 06/05/2023 01:58 AM |
| 5085 | IEC 61850 User Feedback Task Force | Feature | 9 | MH | Resolved | Normal | IEC 61850 7-1 / 7-4 Ed2.1,7-5 | Clarifications on the local/remote concept 5/8 | 06/05/2023 01:58 AM |
| 5086 | IEC 61850 User Feedback Task Force | Feature | 10 | MH | Resolved | Normal | IEC 61850-7-4 Ed2.1 ,7-5 | Clarifications on the local/remote concept 6/8 | 06/05/2023 01:58 AM |
| 5087 | IEC 61850 User Feedback Task Force | Feature | 11 | MH | Resolved | Normal | IEC 61850-7-4 Ed2.1 ,7-5 | Clarifications on the local/remote concept 7/8 | 06/05/2023 01:58 AM |
| 5088 | IEC 61850 User Feedback Task Force | Feature | 12 | MH | Resolved | Normal | IEC 61850-7-4 Ed2.1 ,7-5 | Clarifications on the local/remote concept 8/8 | 06/05/2023 01:58 AM |
| 5089 | IEC 61850 User Feedback Task Force | Improvement | 13 | MH | Resolved | Normal | IEC 61850 7-3 Ed2.1 | Extension of CDC ASG | 06/05/2023 01:58 AM |
| 5091 | IEC 61850 User Feedback Task Force | Feature | 10 | H30 | Resolved | Normal | IEC 61850-2 | Devices types/acronyms | 06/05/2023 01:58 AM |
| 5120 | SCL Tooling | Issues | | | Resolved | Normal | | LGOS/LSVS reference with functional naming (SCL) | 08/09/2022 08:40 AM |
| 5122 | IEC 61850 User Feedback Task Force | Feature | 1 | TF 61850-80-6 | Resolved | Normal | IEC 61850-90-28 | New LN in LN group L to reflect the status of TPAA between Proxy/Gateway and IED | 06/05/2023 01:58 AM |
| 5123 | IEC 61850 User Feedback Task Force | Feature | 2 | TF 61850-80-6 | Resolved | Normal | IEC 61850-90-28 | ACSI service for link supervision on application level | 06/05/2023 01:58 AM |
| 5321 | IEC 61850 User Feedback Task Force | Improvement | 1 | WG17 | Resolved | Normal | IEC 61850-7-4,7-5 | Schedules - allow 3 values per time point | 06/05/2023 01:58 AM |
| 5322 | IEC 61850 User Feedback Task Force | Improvement | 2 | WG17 | Resolved | Normal | IEC 61850-7-4,7-5 | Schedules - add optional data objects to support irregular interval schedules | 06/05/2023 01:58 AM |
| 5323 | IEC 61850 User Feedback Task Force | Improvement | 3 | WG17 | Resolved | Normal | IEC 61850-7-4,7-5 | Schedules - allow updates to single values while schedules are running | 06/05/2023 01:58 AM |
| 5327 | Client | Issues | | | Resolved | Normal | | PIXIT - add processing/mapping of quality bits | 06/28/2022 09:44 AM |
| 5329 | IEC 61850 User Feedback Task Force | Improvement | | SCL IOP 2021 | Resolved | Normal | IEC 61850-6 | Clarify iedType attribute usage in DataTypeTemplates | 06/05/2023 01:58 AM |
| 5330 | IEC 61850 User Feedback Task Force | Improvement | | SCL IOP 2021 | Resolved | Normal | IEC 61850-90-30 | LNode iedName attribute usage needs to be clarified | 06/05/2023 01:58 AM |
| 5331 | IEC 61850 User Feedback Task Force | Feature | | SCL IOP 2021 | Resolved | Normal | IEC 61850-6 | Multiple LNodes implemented by same LN | 06/05/2023 01:58 AM |
| 5335 | IEC 61850 User Feedback Task Force | Improvement | | Dustin Tessier | Resolved | Normal | IEC 61850-90-4 | Adding Normative Requirements & Conformance Testing Pertaining to Broadcast Storms | 06/05/2023 01:58 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 5347 | Server | Issues | | | Resolved | Normal | | How should time correlated GOOSE change status in GOOSE Performance test | 10/04/2022 09:11 AM |
| 5372 | IEC 61850 User Feedback Task Force | Improvement | | RTE | Resolved | Normal | IEC 61850-7-1 | Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation | 06/05/2023 01:58 AM |
| 5876 | IEC 61850 User Feedback Task Force | Improvement | | FNN Germany | Resolved | Normal | IEC 61850-7-4 Ed.3 | Proposal of a new LN class ASWI | 06/05/2023 01:58 AM |
| 5921 | General Testing Issues | Improvement | | | Resolved | Normal | | Start using Vendor and Lab Submission Information | 09/06/2022 09:33 AM |
| 5926 | SCL Tooling | Issues | | | Resolved | Normal | | Review ICT TP | 11/29/2022 07:23 AM |
| 5955 | IEC 61850 User Feedback Task Force | Improvement | | EDF | Resolved | Normal | | Indicate typical SIUnit for every DO with CDC MV would help users + Add a dedicated attribute in NSD files instead of having it in the description ? | 06/05/2023 01:58 AM |
| 5968 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | | Change the diagrams in 7-500 to not use yellow lines | 06/05/2023 01:58 AM |
| 6167 | IEC 61850 User Feedback Task Force | Support | | email | Resolved | Normal | IEC 61850-90-6 | IEC 61850-90-6 Voltage presence CDC for SVPI.Prs | 06/05/2023 01:58 AM |
| 6172 | Client | Issues | | | Resolved | Normal | | client check bits must be tested | 12/13/2022 08:34 AM |
| 6200 | SCL Tooling | Issues | | | Resolved | Normal | | tTf1 change Ed2/2007B to Ed2.1/2007B4 | 01/24/2023 08:33 AM |
| 6207 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | IEC 61850-6 | How to manage update of an IEDName or LDName for object references when valImport is false | 06/05/2023 01:58 AM |
| 6226 | IEC 61850 User Feedback Task Force | Bug | | | Resolved | Normal | | In the downgrading rules from ed 2.1 to ed 2.0 in part 6, it is mentionned to exclude ORS CDC (I.4.2.4). Why CDCs: CST, VSD and TCS that were also added in ed2.1 are not mentionned to be excluded also ? | 06/05/2023 01:58 AM |
| 6246 | IEC 61850 User Feedback Task Force | Feature | | | Resolved | Normal | IEC 61850-6 | ExtRef cannot specify a Poll intended to be implemented as a GetDataSetValues request | 06/05/2023 01:58 AM |
| 6248 | IEC 61850 User Feedback Task Force | Improvement | | EDF | Resolved | Normal | IEC 61850-6 | There are controls between IEDs for automatic control functions, we need to be able to represent those controls in SCL (for configuration in SCT, data flow documentation...) | 06/14/2023 08:33 AM |
| 6256 | IEC 61850 User Feedback Task Force | Bug | | | Resolved | Normal | IEC 61850-7-4 | IEC 61850-7-4 list of abbreviations | 06/06/2023 08:32 AM |
| 6263 | IEC 61850 User Feedback Task Force | Bug | | | Resolved | Normal | IEC 61850-6 | GOOSE MinTime / Max Time - Probable discrepancy between Part-6 and Part-8 | 06/20/2023 08:44 AM |
| 6303 | IEC 61850 User Feedback Task Force | Support | | RTE | Resolved | Normal | IEC 61850-7-500 | LN PDIF – setting for nominal current | 06/05/2023 01:58 AM |
| 6323 | SCL Tooling | Issues | | | Resolved | Normal | | tTtf5 IED name=None is not allowed tissue #1365 | 05/02/2023 08:20 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6325 | SCL Tooling | Issues | | | Resolved | Normal | | PIXIT missing entries on tlie1 "when supported" | 05/16/2023 08:04 AM |
| 6326 | SCL Tooling | Issues | | | Resolved | Normal | | tlie1 - remove step 10-14 to undo previous changes | 05/16/2023 08:09 AM |
| 6327 | SCL Tooling | Issues | | | Resolved | Normal | | tTf2 - export CID file only for Ed2.1? | 05/16/2023 08:20 AM |
| 6370 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | | SBOns to be deprecated in future. | 06/20/2023 09:39 AM |
| 6463 | Client | Issues | | | Resolved | Normal | | cSrv7, cSvrN3 some clients only read DA (not DO) | 07/25/2023 08:07 AM |
| 6464 | Client | Issues | | | Resolved | Normal | | cSrv5 change the condition to GetDataValues or Reporting | 07/11/2023 08:38 AM |
| 6465 | GOOSE Performance | Issues | | | Resolved | Normal | | The Ed2 GOOSE performance also apply for Ed2Amd1 | 08/08/2023 08:42 AM |
| 6471 | Client | Issues | | | Resolved | Normal | | Select.response+ (Tissue 1753) | 08/22/2023 08:10 AM |
| 6483 | Server | Issues | | | Resolved | Normal | | Need to be able to test 61850-7-420 (Ed2) | 06/10/2024 09:25 AM |
| 6489 | GOOSE Performance | Issues | | | Resolved | Normal | | Reducing the needed resources for time correlated subscribed GOOSE not used for ping-pong | 01/23/2024 08:05 AM |
| 6490 | Client | Issues | | | Resolved | Normal | | UCAiug requires Ed2Amd1 Jan 2024 - expect testlabs/toolvendors need more time | 08/22/2023 08:16 AM |
| 6596 | IEC 61850 User Feedback Task Force | Bug | | | Resolved | Normal | | Simulation Mode with Centralized Protection | 11/21/2023 08:32 AM |
| 6605 | IEC 61850 User Feedback Task Force | Support | | RTE | Resolved | Normal | TR IEC 61850-7-500 | Identification of three phase trip with ACT DO | 11/21/2023 08:13 AM |
| 6631 | SCL Tooling | Issues | | | Resolved | Normal | | tTf1 (mustUnderstand) for the ICT test needs clarification | 01/09/2024 08:59 AM |
| 6654 | Client | Issues | | | Resolved | Normal | | Tracking numbering mismatch Ed2 <> Ed2.1 | 01/09/2024 08:27 AM |
| 6655 | Client | Issues | | | Resolved | Normal | | cLogN5 is missing in table A4.2 and certificate template | 01/09/2024 08:28 AM |
| 6685 | GOOSE Performance | Issues | | | Resolved | Normal | | Device need to be certified for Ed2.1 server first | 06/11/2024 08:28 AM |
| 6688 | Client | Issues | | | Resolved | Normal | | cSrvN10 - Ed1 specific error codes do not exist for MMS GetNameList | 04/02/2024 08:42 AM |
| 6724 | Client | Issues | | | Resolved | Normal | | GOOSE Subscriber sGos12 test expects DUT to _send_ a GOOSE message | 08/06/2024 08:49 AM |
| 6727 | Client | Issues | | | Resolved | Normal | | cDsN1bc, cFtN2 have no non-Ed2 specific error code | 04/02/2024 08:42 AM |
| 6728 | Client | Issues | | | Resolved | Normal | | cSg13 refers to PIXIT entry Sg5/Sg6 but not clarified in the expected result | 05/28/2024 08:17 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6737 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | IEC 61850-90-29 | Amending TGSN LN class with signal characteristics | 04/09/2024 08:10 AM |
| 6738 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | | Amending TGSN LN class with settings for adapting the signal | 04/09/2024 08:19 AM |
| 6751 | IEC 61850 TPWG | Issues | | | Resolved | Normal | | Update IEC 61850 QAP Addendum for adding requirement quickly | 04/16/2024 08:16 AM |
| 6767 | IEC 61850 User Feedback Task Force | Feature | | | Resolved | Normal | | Specifying virtualized physical devices and LN's | 06/03/2024 03:10 AM |
| 6776 | Client | Issues | | | Resolved | Normal | | cSBOns4 requires different control value | 05/28/2024 08:07 AM |
| 6777 | Client | Issues | | | Resolved | Normal | | SCD import and Tool Functionality test procedures | 05/28/2024 08:05 AM |
| 6793 | Client | Issues | | | Resolved | Normal | | cCnf13  the ICT tool shall refuse the configuration | 05/28/2024 09:04 AM |
| 6803 | IEC 61850 User Feedback Task Force | Improvement | | | Resolved | Normal | IEC 61850-6 | In part 6, the reference of "pure client" LN by LNodes is not clear. | 09/24/2024 08:14 AM |
| 6810 | IEC 61850 User Feedback Task Force | Improvement | | TC57 WG18 | Resolved | Normal | IEC 61850-90-3 | Amending Txxx LN classes with settings for adapting the signal | 09/24/2024 08:09 AM |
| 6817 | Server | Issues | | | Resolved | Normal | | sBr25 purge only when attribute value change | 08/06/2024 08:20 AM |
| 6821 | Server | Issues | | | Resolved | Normal | | Missing SMVsc check - sCnf130 | 07/23/2024 08:37 AM |
| 6823 | Server | Issues | | | Resolved | Normal | | sAss4 - Step 2 indicates two different situations with localDetailCalling | 08/06/2024 08:15 AM |
| 6830 | Server | Issues | | | Resolved | Normal | | Testing max number of persistent and non-persistent datasets | 08/06/2024 08:11 AM |
| 6488 | GOOSE Performance | Issues | | | Resolved | Low | | Incorrect reference | 09/05/2023 08:08 AM |
| 5246 | WG14 Issues | CIM Issues | | | Rejected | High | | Object status | 10/17/2023 02:45 AM |
| 555 | IEC 61850 User Feedback Task Force | Support | 2 | H30 | Rejected | Normal | | Link Failover reliability problem - implication to protection application | 10/25/2022 09:01 AM |
| 3027 | IEC 61850 Certificate | IEC 61850 Certificate | | | Rejected | Normal | | F650 Digital Bay Controller [GE Power Management, S.L.] | 08/04/2021 09:37 AM |
| 5138 | Server | Issues | | | Rejected | Normal | | sBr13 without pre-assignment | 12/13/2021 04:43 AM |
| 5265 | WG14 Part 6 Issues | CIM Issues | | | Rejected | Normal | 61968-7, 61968-6 | DesignLocation association to WorkTask | 11/16/2023 11:51 AM |
| 5269 | WG14 Part 6 Issues | CIM Issues | | | Rejected | Normal | 61968-6 | Status attributes in WorkOrder | 10/16/2023 03:17 PM |
| 5344 | Server | Issues | | | Rejected | Normal | | sBr29 power-up the IED is missing | 06/02/2022 04:12 PM |
| 5906 | Server | Issues | | | Rejected | Normal | | sCnf51 at least one LPHD | 09/06/2022 08:20 AM |
| 6174 | Server | Issues | | | Rejected | Normal | | Amend sCtl7 to test both interlocking check and check synchronizing ? | 02/07/2023 08:24 AM |
| 6206 | Server | Issues | | | Rejected | Normal | | Type and size of Length field value (TLV) encoding in SV | 01/11/2023 06:19 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 6208 | Server | Issues | | | Rejected | Normal | | sSvsN2 in TP1.2 does not check the situation where the DUT checks ConfRev | 03/21/2023 08:20 AM |
| 6324 | SCL Tooling | Issues | | | Rejected | Normal | | sCnf6 - not all extRef require intAddr not referring to external device | 05/16/2023 08:44 AM |
| 6365 | Server | Issues | | | Rejected | Normal | | Considering PTP version 2.1 | 07/11/2023 08:12 AM |
| 6466 | Server | Issues | | | Rejected | Normal | | TP1.2 sSvs1 step 6 shall be removed | 07/11/2023 08:33 AM |
| 6472 | Server | Issues | | | Rejected | Normal | | Concept of smpRate for input analogue signal acquisition is misleading (Tissue 1857) | 08/22/2023 08:22 AM |
| 6520 | SCL Tooling | Issues | | | Rejected | Normal | | ICT Ed2.1 refers to TICS but there no part 6 tissues | 10/31/2023 08:35 AM |
| 6565 | Server | Issues | | | Rejected | Normal | | Added more precise qualifications to TmSrcTyp - 1883 | 11/14/2023 09:03 AM |
| 6568 | Server | Issues | | | Rejected | Normal | | The definition of LTMS.TmSrc is different in the actual AMD1 and Consolidated Version - 1846 | 11/14/2023 08:37 AM |
| 6589 | Server | Issues | | | Rejected | Normal | | Create DataSets with Multiple Clients (for example, sDsN4) | 11/14/2023 08:48 AM |
| 6590 | Server | Issues | | | Rejected | Normal | | sGopN2 - The clear meaning of too large a dataset | 11/14/2023 08:58 AM |
| 6591 | Server | Issues | | | Rejected | Normal | | sSg11 - Non-volatile property test (for various FCs) | 11/14/2023 08:38 AM |
| 6622 | IEC 61850 TPWG | Bug | | | Rejected | Normal | | Test case Ttf1 (mustUnderstand) for the ICT conformance test needs clarification | 12/12/2023 08:19 AM |
| 6653 | Server | Issues | | | Rejected | Normal | | sFt2c does deletable means everything else is not deletable | 01/09/2024 08:19 AM |
| 6766 | WG16 Issues | CIM Issues | | | Rejected | Normal | | ResourceCertification attribute type is generic and could be renamed to a more describe attribute name | 06/10/2024 10:31 AM |
| 6778 | Market Operations | CIM Issues | | | Rejected | Normal | | RegisteredDistributedResource vs RegisteredResource attributes | 06/10/2024 09:42 AM |
| 6816 | Client | Issues | | | Rejected | Normal | | cBr31 is mandatory but for not applicable "small" client controllers | 07/23/2024 08:51 AM |
| 7008 | Server | Issues | | | Rejected | Normal | | Proposal to change Mandatory test items related to compatibility to Conditional | 10/01/2024 08:19 AM |
| 651 | Server | Issues | | | Rejected | Low | | Verify subscriber can accept maximum size GOOSE | 01/24/2023 08:40 AM |
| 653 | Server | Issues | | | Rejected | Low | | Subscriber can use maximum number of dataset elements | 01/24/2023 09:03 AM |
| 654 | Server | Issues | | | Rejected | Low | | Publish/subscribe minimum length data GOOSE | 01/24/2023 09:02 AM |
| 5268 | WG14 Part 6 Issues | CIM Issues | | | Rejected | Low | 61968-6 | Add rank as attribute to WorkOrder | 10/17/2023 03:21 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|---|---|---|---|---|---|---|---|---|---|
| 631 | IEC 61850 User Feedback Task Force | Feature | 44 | RTE | Triage | Normal | | Evolution of LN PSCH to build switching on information | 08/17/2021 08:03 AM |
| 6992 | IEC 61850 User Feedback Task Force | Improvement | | | Triage | Normal | IEC 61850-6 | Add identifier to KDC | 09/24/2024 08:33 AM |
| 724 | Gateway Certificates | OpenFMB Gateway | | | Approved | Normal | | OES Gateway | 08/20/2021 01:13 PM |
| 1866 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CP-MUP [ABB Switzerland Ltd.] | 06/13/2022 03:24 PM |
| 1867 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Siemens SICAM PAS  [Siemens AG ] | 07/08/2021 04:13 PM |
| 1868 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Telvent subCAT [Telvent Energia, S.A.] | 07/09/2021 09:16 AM |

**...**