WG13 Issues - CIM Issues #4929

ENTSO-E 12 - SynchronousMachine PU Some attributes need to

09/14/2021 03:47 PM - Herbert Falk

Status:	Closed		
Priority:	Low		
Target version:			
Author/Contact Info:	ENTSO-E	**Standard(s):**	
Base Release:	61970cim15v28	**Version:**	
Solution to be Applied To:	61970cim16	**Clause:**	
Solution Version:	CIM17	**Sub-Clause:**	
Solution Applied By:		**Paragraph:**	
Completion Date:		**Table:**	
CIM Keywords:		**Originally Closed in Version:**	
Breaking Change:	No	**Origination Date:**	08/17/2011
Breaking Change Description:		**Origination ID:**	13_90
CIM Impacted Groups:	WG13	**Originally Assigned To:**	
Requestor:			

Description

ENTSO-E 12 - SynchronousMachine PU
Some attributes need to be PU.i

History

#1 - 02/07/2023 01:19 PM - Chavdar Ivanov

- Subject changed from ENTSO-E 12 - SynchronousMachine PU Some attributes need to to ENTSO-E 12 - SynchronousMachine PU Some attributes need to

- Status changed from Open to In Progress

- Base Release changed from 61970cim15v28 to 61970cim15v28

- Solution Version set to CIM17

Attributes were changed either in CIM16 or CIM17. Therefore the issue is closed.

#2 - 02/07/2023 01:19 PM - Chavdar Ivanov

- Status changed from In Progress to Closed