WG16 Issues - CIM Issues #5778

All end role association names for EnvironmentalLocationType are incorrectly named EnvironmentalLocationKind.

06/23/2022 10:33 AM - Herbert Falk

Status:	Closed		
Priority:	Normal		
Target version:			
Author/Contact Info:	Becky	**Standard(s):**	
Base Release:	iec61970cim17v34ec61968cim13v12iec62325cim04v04	**Version:**	
Solution to be Applied To:		**Clause:**	Environmental
Solution Version:	iec61970cim17v34ec61968cim13v12iec62325cim04v05	**Sub-Clause:**	
Solution Applied By:	BLI	**Paragraph:**	
Completion Date:	07/18/2019	**Table:**	
CIM Keywords:		**Originally Closed in Version:**	
Breaking Change:		**Origination Date:**	05/28/2019
Breaking Change Description:		**Origination ID:**	16_0062
CIM Impacted Groups:	None	**Originally Assigned To:**	
Requestor:			

Description

All end role association names for EnvironmentalLocationType are incorrectly named EnvironmentalLocationKind.

Add new association to EnvironmentalEvent

Proposed Solution

Update end role names to match the name of the class

Add new association to EnvironmentalEvent

Decision

Updated end role names and added association

History

#1 - 08/08/2022 05:27 PM - Becky Iverson

- Status changed from New to Closed

- Base Release changed from iec61970cim17v34ec61968cim13v12iec62325cim04v04 to iec61970cim17v34ec61968cim13v12iec62325cim04v04

- Solution Version changed from iec61970cim17v34ec61968cim13v12iec62325cim04v05 to iec61970cim17v34ec61968cim13v12iec62325cim04v05

- Proposed Solution updated