Server - Issues #6213

sSvsN1 - confRev-1 not possible for backwards config

01/12/2023 09:31 AM - Richard Schimmel

Status:	Closed	**Due date:**	02/07/2023
Priority:	Normal		
Assignee:	Richard Schimmel		
Category:			
Target version:			
Discuss in Upcoming Meeting:	No	**Updated Test Document:**	TP1.3
Clause Reference:		**Test Case ID:**	
61850 Standard:	9-2	**Closed Reason:**	--Not Set---
Triggering Tissue:		**Triggering Tissue 2:**	
Final Decision:		**Triggering Tissue 3:**	
Initial Test Document:	Server Ed2.1 TP1.2		

Description

backwards MSVCB's shall have confRev=1 so reducing confRev results in a zero value which is not allowed. Propose to move step 6 to the preferred configuration.

History

#1 - 01/24/2023 06:40 AM - Richard Schimmel

- File Solution to redmine 6213.docx added

- Status changed from New to In Progress

Added solution

#2 - 01/24/2023 08:59 AM - IEC 61850 TPWG

- Due date set to 02/07/2023

- Status changed from In Progress to Resolved

#3 - 03/01/2024 10:00 AM - Richard Schimmel

- Status changed from Resolved to Closed

- Updated Test Document set to TP1.3

Files

Solution to redmine 6213.docx	21.2 KB	01/24/2023	Richard Schimmel