Server - Issues #6466

TP1.2 sSvs1 step 6 shall be removed

07/06/2023 06:07 AM - Hua Qin

Status:	Rejected	**Due date:**	
Priority:	Normal		
Assignee:			
Category:			
Target version:			
Discuss in Upcoming Meeting:	No	**Updated Test Document:**	
Clause Reference:		**Test Case ID:**	sSvs1
61850 Standard:		**Closed Reason:**	--Not Set---
Triggering Tissue:		**Triggering Tissue 2:**	
Final Decision:		**Triggering Tissue 3:**	
Initial Test Document:	TP1.2		

Description

TP1.2 sSvs1 step 6 requires the DUT to subscribe to the MAC address which is out of recommended range.

According to 61869-9 TABLE 908, it says that "the address shall be 01-0C-CD-04-xx-xx".
In 9-2LE table 9 says "Needs to be configured; the recommendation of 9-2 Annex C shall be followed".
So it seems that SV publisher shall publish the recommend MAC range.

Suggest to remove all the words after step 5.

History

#1 - 07/11/2023 06:34 AM - Thierry Dufaure

I tend to disagree; the recommended range from 9-2 is still a recommended range from 9-2 Ed2.1 perspective, and we should test addresses outside the recommended range in order to make subscriber compatible with any multicast address

#2 - 07/11/2023 08:33 AM - IEC 61850 TPWG

- Status changed from New to Rejected

Subscribers should be flexible to align with -9-2