## Issues

| #    | Project | Tracker | ID | Source | Status   | Priority | Standard(s) | Subject  | Updated             |
|------|---------|---------|----|--------|----------|----------|-------------|--|---------------------|
| 7091 | Server  | Issues  |    |        | Rejected | Normal   |             | sSrv17 - New value should be different from the previous one and not from the SCL value. Test case will not work twice with SPG setpoints. | 01/21/2025 08:06 AM |
| 6904 | Server  | Issues  |    |        | Resolved | Normal   |             | sCtl14 in TP1.3 does not reflect the Issue #6214 resolution  | 10/29/2024 08:53 AM |
| 6903 | Server  | Issues  |    |        | Resolved | Normal   |             | sGos20 requires the ICT to accept invalid SCD files due to FC out of tFCEnum   | 10/29/2024 08:52 AM |
| 6823 | Server  | Issues  |    |        | Resolved | Normal   |             | sAss4 - Step 2 indicates two different situations with localDetailCalling  | 08/06/2024 08:15 AM |

04/19/2025