

Issues

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|----------------|----|--------|--------|----------|--------------------------|---|---------------------|
| 6491 | Server | Issues | | | Closed | Low | | Incorrect reference | 03/01/2024 10:06 AM |
| 6281 | Server | Issues | | | Closed | Normal | | Templates for Ed. 2.1 conformance statements | 03/01/2024 10:04 AM |
| 6269 | Server | Issues | | | Closed | Normal | | sSrv9, sSrv10: change Table 3 to Table D.1 reference | 03/01/2024 10:01 AM |
| 6546 | IEC 61850 User Feedback Task Force | Improvement | | | Closed | Normal | | Prevent the modification of setting parameters | 11/07/2023 08:14 AM |
| 6184 | IEC 61850 User Feedback Task Force | Bug | | | Closed | Normal | IEC 61850-7-3 Ed.2 Amd.1 | Trigger option 'dchg' for settings of FC=SG | 06/05/2023 01:59 AM |
| 6186 | IEC 61850 User Feedback Task Force | Feature | | | Closed | Normal | IEC 61850-7-2 Clause 16 | Changing the ActSG while reservation by another client is ongoing | 12/06/2022 09:39 AM |
| 5102 | IEC TC57 WG10 Future Work | WG10FutureWork | | WG 10 | Closed | Normal | IEC 61850-7-2 | Control of LN.Mod without using MMS | 03/01/2022 08:28 AM |
| 674 | Server | Issues | | | Closed | Normal | | sCtl5 to be more precise related to "blocked" and "test/blocked" | 09/14/2021 06:45 AM |