

Issues

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
606	IEC 61850 User Feedback Task Force	Bug	5	H30	Closed	Normal		LGOS/LSVS mandatory	02/09/2022 07:48 AM
628	IEC 61850 User Feedback Task Force	Bug	30	RTE	Closed	Normal		Enum type reduction in ICD/SSD file	03/02/2021 09:54 AM
609	IEC 61850 User Feedback Task Force	Bug	1	RTE	Closed	Normal		The value of the DO LLN0.Health of a LD should inherit from the alarm status of LPHD0.PhyHealth of the IED nesting the LD	03/02/2021 08:37 AM
5077	IEC 61850 User Feedback Task Force	Feature	1	MH	Closed	Normal	IEC61850 7-1	Location of SGCB in LD structures	03/14/2023 09:10 AM
622	IEC 61850 User Feedback Task Force	Feature	18	RTE	Closed	Normal	IEC 61850-7-4	Parameters not available in standardized LN	01/17/2023 09:04 AM
620	IEC 61850 User Feedback Task Force	Feature	16	RTE	Closed	Normal	TR 61850-90-29	New LN LPDO / LPDI in IEC 61850-7-5	10/25/2022 08:45 AM
5090	IEC 61850 User Feedback Task Force	Feature	9	H30	Closed	Normal	IEC 61850-7-1 Ed2.1	Mod inheritance when multiple root LD's (GrRef's) exist	12/07/2021 08:19 AM
660	IEC 61850 User Feedback Task Force	Support	1	WG10	Closed	Normal	IEC 61850-6, TR IEC 61850-90-30	IED model documentation	11/21/2023 09:00 AM
613	IEC 61850 User Feedback Task Force	Support	13	RTE	Closed	Normal	IEC 61850-7-4	Clarification of representation of tap changer (LN ATTC, YLTC).	11/09/2021 02:13 PM
664	IEC 61850 User Feedback Task Force	Improvement	9	H30	Closed	Normal		Recommended improvements to TISSUE Process	07/13/2021 04:05 PM