

Issues

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------|-------------|----|--------|-------------|----------|-------------|--|---------------------|
| 5852 | WG16 Issues | CIM Issues | | | Open | Normal | | Request for an association between AccountingPoint and DateAndOrTime | 08/12/2022 03:34 AM |
| 5853 | WG16 Issues | CIM Issues | | | Open | Normal | | Request for an association between MarketEvaluationPoint and Domain | 08/12/2022 03:32 AM |
| 5854 | WG16 Issues | CIM Issues | | | Open | Normal | | Request for an association between MarketEvaluationPoint and MarketParticipant | 08/12/2022 03:31 AM |
| 5855 | WG16 Issues | CIM Issues | | | Open | Normal | | Request for an association between MarketEvaluationPoint and MarketAgreement | 08/12/2022 03:31 AM |
| 5856 | WG16 Issues | CIM Issues | | | Open | Normal | | Request for a self-association on AccountingPoint | 08/12/2022 03:26 AM |
| 5922 | WG16 Issues | CIM Issues | | | Open | Normal | | New association between energyMarket & Process and Timeseries | 08/12/2022 03:23 AM |
| 5906 | Server | Issues | | | Rejected | Normal | | sCnf51 at least one LPHD | 08/11/2022 01:55 AM |
| 656 | Server | Issues | | | In Progress | Low | | Publish/subscribe enum with value > 127 | 08/10/2022 11:16 AM |
| 5917 | Server | Issues | | | In Progress | Urgent | | 'Expected result' for some test cases of CB9b: GOOSE subscribe | 08/09/2022 10:21 AM |
| 5921 | General Testing Issues | Improvement | | | New | Normal | | Start using Vendor and Lab Submission Information | 08/09/2022 10:20 AM |
| 5926 | General Testing Issues | Improvement | | | New | Normal | | Review ICT TP | 08/09/2022 10:12 AM |
| 5914 | Server | Issues | | | In Progress | Normal | | Verify that LPHD.Sim is not affected by LLN0.Beh | 08/09/2022 08:59 AM |
| 5913 | Server | Issues | | | Resolved | Normal | | sSrvN1e and sSrvN3 change condition SCL FC=CF/DC/SP with valKind=Set | 08/09/2022 08:48 AM |
| 5912 | Server | Issues | | | In Progress | Normal | | sSrv6 checking the read-only part is always applicable | 08/09/2022 08:47 AM |
| 5362 | Server | Issues | | | Resolved | Normal | | sGop2 and sGop4 check minimum MinTime and minimum MaxTime | 08/09/2022 08:45 AM |
| 5319 | Server | Issues | | | In Progress | Normal | | T1782 sCtl7 addcause "inconsistent-parameters" when check=00 not-supported | 08/09/2022 08:43 AM |
| 5347 | Server | Issues | | | In Progress | Normal | | How should time correlated GOOSE change status in GOOSE Performance test | 08/09/2022 08:41 AM |
| 5120 | SCL Tooling | Issues | | | Resolved | Normal | | LGOS/LSVS reference with functional naming (SCL) | 08/09/2022 08:40 AM |
| 5947 | WG13 Issues | CIM Issues | | | New | Normal | 61970-456 | Description classes inheriting from IdentifiedObject | 08/09/2022 08:40 AM |
| 657 | Server | Issues | | | In Progress | Low | | Publish/subscribe enum with negative value | 08/09/2022 08:38 AM |
| 654 | Server | Issues | | | In Progress | Low | | Publish/subscribe minimum length data GOOSE | 08/09/2022 08:35 AM |
| 653 | Server | Issues | | | In Progress | Low | | Subscriber can use maximum number of dataset elements | 08/09/2022 08:34 AM |
| 652 | Server | Issues | | | In Progress | Normal | | Publisher can use maximum number of dataset elements | 08/09/2022 08:34 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|---------------------------|----------------|----|------------------|-------------|----------|---------------------|--|---------------------|
| 651 | Server | Issues | | | In Progress | Low | | Verify subscriber can accept maximum size GOOSE | 08/09/2022 08:32 AM |
| 5910 | Server | Issues | | | In Progress | Normal | | Need to test that IEDs support 1 Step and 2 Step clocks: IOP 2022 | 08/09/2022 08:30 AM |
| 5946 | WG13 Issues | CIM Issues | | | New | High | 61970-456 | Association Terminal.TopologicalNode | 08/09/2022 08:29 AM |
| 5907 | Server | Issues | | | Resolved | Normal | | sCtl26 - Cancel a direct control object | 08/09/2022 08:24 AM |
| 5905 | Server | Issues | | | In Progress | Normal | | sSrvN4 is mandatory, used SetDataValues service is optional in PICS and may not be not supported | 08/09/2022 08:20 AM |
| 5945 | WG13 Issues | CIM Issues | | | New | High | | DCSwitch does not have open flag | 08/09/2022 08:20 AM |
| 5944 | IEC TC57 WG10 Future Work | WG10FutureWork | | RTE | New | Normal | IEC 61850-7-4 | Need to create a new LN of group P (Protection), as "PCDP" to represent the Pole Discrepancy Protection. | 08/09/2022 08:17 AM |
| 5943 | IEC TC57 WG10 Future Work | WG10FutureWork | | RTE | New | Normal | | New LN of group L (as "LTED") to represent the dynamic topology of the substation. | 08/09/2022 08:17 AM |
| 5942 | IEC TC57 WG10 Future Work | WG10FutureWork | | RTE | New | Normal | IEC 61850-7-4 | Activation and deactivation of a function by configuration. | 08/09/2022 08:16 AM |
| 5941 | IEC TC57 WG10 Future Work | WG10FutureWork | | TissueDB | New | Normal | IEC 61850-7-4 | IEC61850.Tissue #1755 Event driven schedules – Add DO to stop schedule by event | 08/09/2022 08:16 AM |
| 5940 | IEC TC57 WG10 Future Work | WG10FutureWork | | SCL IOP 2021 | New | Normal | IEC 61850-6 | Multiple LN nodes implemented by same LN | 08/09/2022 08:15 AM |
| 5939 | IEC TC57 WG10 Future Work | WG10FutureWork | | RTE | New | Normal | IEC 61850-6 | Mapping of another phases system description to the generic phases phsA, phsB, phsC | 08/09/2022 08:14 AM |
| 5938 | IEC TC57 WG10 Future Work | WG10FutureWork | | RTE | New | Normal | IEC 61850-7-4 | LN RADR evolution | 08/09/2022 08:14 AM |
| 5937 | IEC TC57 WG10 Future Work | WG10FutureWork | | WG10 | New | Normal | IEC 61850-7-4 | Report of current active setting group | 08/09/2022 08:13 AM |
| 5936 | IEC TC57 WG10 Future Work | WG10FutureWork | | TissueDB | New | Normal | IEC 61850-7-4 | IEC61850.Tissue #1756 Event driven schedules – Extend description | 08/09/2022 08:13 AM |
| 5935 | IEC TC57 WG10 Future Work | WG10FutureWork | | MH | New | Normal | IEC 61850 7-3 Ed2.1 | Extension of CDC ASG | 08/09/2022 08:12 AM |
| 5934 | IEC TC57 WG10 Future Work | WG10FutureWork | | RTE | New | Normal | IEC 61850-7-1 | Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation | 08/09/2022 08:11 AM |
| 5933 | IEC TC57 WG10 Future Work | WG10FutureWork | | FNN Germany | New | Normal | IEC 61850-7-4 Ed.3 | Proposal of a new LN class ASWI | 08/09/2022 08:11 AM |
| 5932 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEC 62361-102 R2 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - Extend list of equipment type codes | 08/09/2022 08:08 AM |
| 5931 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEC 62361-102 R3 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - Add string attribute psrType to tPowerSystemResource. | 08/09/2022 08:07 AM |
| 5930 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEC 62361-102 R6 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - mRID attribute in SCL for Equipment, Terminals, ConnectivitNodes | 08/09/2022 08:06 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|---------------------------|----------------|----|-------------------|--------|----------|---------------|---|---------------------|
| 5929 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEC 62361-102 R8 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - allow Terminals with no connections - use explicit ConnectivityNode.name = None | 08/09/2022 08:06 AM |
| 5928 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEC 62361-102 R9 | New | Normal | IEC 61850-6 | CIM-61850 Harmonization - extend tPhaseEnum to match CIM PhaseCode | 08/09/2022 08:05 AM |
| 5927 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEC 62361-102 R15 | New | Normal | IEC 61850-7-4 | CIM-61850 Harmonization - Add PosFlwIn data object to measurement classes | 08/09/2022 08:02 AM |
| 5865 | WG16 Issues | CIM Issues | | | Open | Normal | | MarketProductType; update description to correct typo | 08/08/2022 06:05 PM |
| 5864 | WG16 Issues | CIM Issues | | | Open | Normal | | Enumeration missing descriptions; PriorityKind, ResourceCertificationKind | 08/08/2022 06:05 PM |
| 5863 | WG16 Issues | CIM Issues | | | Open | Normal | | Update the set of DemandSideResourceInterfaceProfiles from WG21 | 08/08/2022 06:05 PM |
| 5857 | WG16 Issues | CIM Issues | | | Open | Normal | | MarketProductType enum values update | 08/08/2022 06:03 PM |
| 5847 | WG16 Issues | CIM Issues | | | Open | Normal | | IEC62325 Dependency Diagram Update | 08/08/2022 05:59 PM |
| 5839 | WG16 Issues | CIM Issues | | | Open | Normal | | ResourceCapacity; Propose to use DecimalQuantity for the attributes defaultCapacity, maximumCapacity, minimumCapacity | 08/08/2022 05:56 PM |
| 5830 | WG16 Issues | CIM Issues | | | Open | Normal | | MarketProductType new enum values | 08/08/2022 05:53 PM |
| 5829 | WG16 Issues | CIM Issues | | | Open | Normal | | Environmental Profile diagrams moved to Environmental package | 08/08/2022 05:52 PM |
| 5818 | WG16 Issues | CIM Issues | | | Open | Normal | | Consider enhancing the FuelSource enumeration to include more fuel types | 08/08/2022 05:49 PM |
| 5816 | WG16 Issues | CIM Issues | | | Open | Normal | | Associate the class BusinessSector with the MktActivityRecord class (many-many-association). | 08/08/2022 05:48 PM |
| 5815 | WG16 Issues | CIM Issues | | | Open | Normal | | Associate the class BusinessSector with the TimeSeries class (many-many-association). | 08/08/2022 05:48 PM |
| 5814 | WG16 Issues | CIM Issues | | | Open | Normal | | Associate the class BusinessSector with the MarketDocument class (many-many-association). | 08/08/2022 05:47 PM |
| 5813 | WG16 Issues | CIM Issues | | | Open | Normal | | Add attribute type (string) in the BusinessSector class to tell the specific Businss sector [required]. | 08/08/2022 05:47 PM |
| 5812 | WG16 Issues | CIM Issues | | | Open | Normal | | Add a new BusinessSector class in the MarketManagement package. | 08/08/2022 05:47 PM |
| 5809 | WG16 Issues | CIM Issues | | | Open | Normal | | Add a new EnergyTechnologyAndFuel class in the MarketManagement package | 08/08/2022 05:46 PM |
| 5808 | WG16 Issues | CIM Issues | | | Open | Normal | | Add disconnectionContract attribute (Boolean) in the MarketEvaluationPoint class | 08/08/2022 05:45 PM |
| 5807 | WG16 Issues | CIM Issues | | | Open | Normal | | Add contractedConnectionCapacity attribute (DecimalQuantity) in the MarketEvaluationPoint class | 08/08/2022 05:45 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|-------------|----------|----------|--------------------|---|---------------------|
| 5806 | WG16 Issues | CIM Issues | | | Open | Normal | | Add administrativeStatus attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:45 PM |
| 5805 | WG16 Issues | CIM Issues | | | Open | Normal | | Add gridAgreementType attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:45 PM |
| 5804 | WG16 Issues | CIM Issues | | | Open | Normal | | Add meteredDataCollectionMethod attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:44 PM |
| 5803 | WG16 Issues | CIM Issues | | | Open | Normal | | Add meterReadingPeriodicity attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:44 PM |
| 5802 | WG16 Issues | CIM Issues | | | Open | Normal | | Add scheduledMeterReadingDate attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:44 PM |
| 5801 | WG16 Issues | CIM Issues | | | Open | Normal | | Add settlementMethod attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:43 PM |
| 5800 | WG16 Issues | CIM Issues | | | Open | Normal | | Add meteringMethod attribute (String) in the MarketEvaluationPoint class | 08/08/2022 05:43 PM |
| 5799 | WG16 Issues | CIM Issues | | | Open | Normal | | Add marketEvaluationPointType attribute (String) to the MarketEvaluationPoint class | 08/08/2022 05:43 PM |
| 5795 | WG16 Issues | CIM Issues | | | Open | Normal | | ResourceTimeSeriesFactor add attributes value1Description and value2Description | 08/08/2022 05:41 PM |
| 5794 | WG16 Issues | CIM Issues | | | Open | Normal | | MarketParticipant association to MarketRole | 08/08/2022 05:40 PM |
| 5764 | WG16 Issues | CIM Issues | | | Open | Normal | | Clean up of RegisteredInterTie attributes | 08/08/2022 05:21 PM |
| 5762 | WG16 Issues | CIM Issues | | | Open | Normal | | RegisteredLoad clean-up of attributes | 08/08/2022 05:20 PM |
| 5760 | WG16 Issues | CIM Issues | | | Open | Normal | | Addition of new Anode types | 08/08/2022 05:20 PM |
| 5751 | WG16 Issues | CIM Issues | | | Open | Normal | | Mkt classes review | 08/08/2022 05:14 PM |
| 5920 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Kalki SYNC 3000 Edition 2 Client | 08/05/2022 10:52 AM |
| 5919 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | DS Agile aView Edition 2 Client | 08/05/2022 10:39 AM |
| 5918 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MiCOMP40AgileP44T Edition 2 Server | 08/04/2022 06:56 AM |
| 5876 | IEC 61850 User Feedback Task Force | Improvement | | FNN Germany | Resolved | Normal | IEC 61850-7-4 Ed.3 | Proposal of a new LN class ASWI | 08/02/2022 08:56 AM |
| 5916 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | XJ Electric Co., Ltd. WYD-811 Microcomputer Tele-control Unit - Edition 2 Client | 07/31/2022 12:59 PM |
| 5909 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | VITZRO EM CO., LTD. VIPAM-PB | 07/24/2022 03:11 PM |
| 5908 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | AEGIS SERIES Numerical Protection Relay Protection Relay | 07/24/2022 03:11 PM |
| 5750 | WG16 Issues | CIM Issues | | | Open | Normal | | The characteristics of a MSG Generating Plant uses similar definition as a RegisteredGenerator. | 07/19/2022 05:59 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|--------|----------|----------|---------------|--|---------------------|
| 5374 | IEC 61850 User Feedback Task Force | Feature | | RTE | Triage | Normal | IEC 61850-7-4 | Creation of a new LN for protection function | 07/19/2022 02:46 AM |
| 5904 | IEC TC57 WG10 Future Work | WG10FutureWork | | WG10 | New | Normal | 7-4 | Introduce alarm and counter DOs in 7-4 | 07/14/2022 10:27 AM |
| 5897 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM Substation.Station and Substation.SupplyingStation | 07/13/2022 02:22 PM |
| 5896 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM conflicting roles RotatingMachine.HydroPump and HydroPump.RotatingMachine | 07/13/2022 02:20 PM |
| 5895 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM OperationalLimitSet.RateTemperature | 07/13/2022 02:17 PM |
| 5894 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM conflicting roles OperationalLimitType.OperationalLimit and OperationalLimit.OperationalLimitType | 07/13/2022 02:15 PM |
| 5893 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM conflicting roles HydroPowerPlant.HydroPumps and HydroPump.HydroPowerPlant | 07/13/2022 02:13 PM |
| 5892 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM EquipmentContainer.WeatherStation | 07/13/2022 02:10 PM |
| 5891 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM CurrentTransformer.CurrentTransformerPhase | 07/13/2022 02:08 PM |
| 5890 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM WirePhaseInfo.WireEarthInfo | 07/13/2022 02:05 PM |
| 5889 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM WireInfo.WireInfoType | 07/13/2022 02:03 PM |
| 5888 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM OperatingParticipant.Organization | 07/13/2022 02:01 PM |
| 5887 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM CatalogAssetType.TypeAssetCatalogue | 07/13/2022 01:59 PM |
| 5886 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM missing TransformerTank and TransformerTankEnd | 07/13/2022 01:54 PM |
| 5885 | CIM Issues | CIM Issues | | | New | Normal | IEC 61970-301 | Consider CIM measurement classes that can hold multiple measured values with the same timestamp and quality. | 07/13/2022 10:50 AM |
| 5884 | CIM Issues | CIM Issues | | | New | Normal | | Modify control model - create DiscreteCommand for enumerations such as raise/lower | 07/13/2022 10:45 AM |
| 5883 | CIM Issues | CIM Issues | | | New | Normal | IEC 61970-301 | Define a standard way to define IEC 61850 data object names for MeasurementTypes and ControlTypes | 07/13/2022 10:31 AM |
| 5882 | CIM Issues | CIM Issues | | | New | Normal | IEC 61970-301 | Model fans, motors, battery systems and similar auxiliary equipment with terminals | 07/13/2022 10:24 AM |
| 5881 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | DS Agile aView System HMI [GE Renewable Energy] | 07/12/2022 03:27 PM |
| 5878 | IEC TC57 WG10 Future Work | WG10FutureWork | | | New | Normal | | Technical reports to be considered in edition 3 of IEC 61850-7-4 | 07/12/2022 08:58 AM |
| 5880 | WG14 Part 11 Issues | CIM Issues | | | New | Normal | 61968-11 | Location should follow Spatial Data best practice | 07/06/2022 11:51 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|------|-------------|-------------|----------|------------------------------|---|---------------------|
| 5879 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ZLFC [ZIV Aplicaciones y Tecnología SL] | 07/05/2022 07:37 PM |
| 602 | IEC 61850 User Feedback Task Force | Feature | 1742 | IOP_2019 | Resolved | Normal | IEC 61850-9-3 | Merging Unit standard requires MU clock to jump on PTP time jumps, which is not true for Boundary Clocks. | 07/05/2022 08:52 AM |
| 599 | IEC 61850 User Feedback Task Force | Feature | 12 | IOP_2019 | Resolved | Normal | | ICD files do not match requirements (several issues) - increase in engineering efforts | 07/05/2022 08:48 AM |
| 597 | IEC 61850 User Feedback Task Force | Feature | 1120 | IOP_2019 | Resolved | Normal | TF Communication supervision | SCTs updating the confRev of 9-2 LE Sampled Value streams - problem with subscription to test tool SV injection | 07/05/2022 08:46 AM |
| 590 | IEC 61850 User Feedback Task Force | Feature | 1800 | IOP_2019 | In Progress | Normal | IEC 61850-6 | ICT fails to check validity of the SCD file regarding the IED constraints | 07/05/2022 08:30 AM |
| 584 | IEC 61850 User Feedback Task Force | Feature | 1122 | IOP_2019 | Resolved | Normal | IEC 61850-6 | SCL validation - Should all name parts of PhV be contained in the doName? | 07/05/2022 08:20 AM |
| 612 | IEC 61850 User Feedback Task Force | Feature | 11 | RTE | Resolved | Normal | IEC 61850-7-4 | Need to create a new LN of group P (Protection), as "PCDP" to represent the Pole Discrepancy Protection. | 07/05/2022 08:17 AM |
| 629 | IEC 61850 User Feedback Task Force | Improvement | 35 | RTE | Resolved | Normal | IEC TR 61850-90-29 | TCTR and TVTR new DO to identify physical terminal allocation in the IED | 07/05/2022 08:15 AM |
| 5371 | Server | Issues | | | Resolved | Normal | | Scope of the test is limited to a given NSD release. | 06/29/2022 02:11 AM |
| 5871 | WG14 Part 11 Issues | CIM Issues | | | In Progress | Low | 61968-11 | Association end role name is spelled incorrectly | 06/28/2022 12:26 PM |
| 5873 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | xGrids Transfer KPG-v1 [KEPCO Knowledge Data & Network Co., Ltd.] | 06/28/2022 12:23 PM |
| 5874 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | xGrids Transfer KPG-v1 [KEPCO Knowledge Data & Network Co., Ltd.] | 06/28/2022 12:22 PM |
| 5365 | WG14 Part 9 Issues | CIM Issues | | | New | Low | All WG13 and WG14 stds | Version control in XSDs | 06/28/2022 10:59 AM |
| 5872 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | UR N60 [GE Renewable Energy] | 06/28/2022 10:41 AM |
| 5327 | Client | Issues | | | Resolved | Normal | | PIXIT - add processing/mapping of quality bits | 06/28/2022 09:44 AM |
| 5868 | WG13 Issues | CIM Issues | | | New | Normal | | New BusSegment for busbar modeling | 06/26/2022 10:02 PM |
| 5870 | WG13 Issues | CIM Issues | | | New | Normal | | BusSegment - Profiles | 06/26/2022 10:00 PM |
| 5869 | WG13 Issues | CIM Issues | | | New | Normal | | BusSegment - UML updates | 06/26/2022 09:59 PM |
| 5318 | WG14 Issues | CIM Issues | | | New | High | | Address modeling is too complex | 06/21/2022 09:32 AM |
| 553 | IEC 61850 User Feedback Task Force | Support | 34 | IOP_2017/55 | Resolved | Normal | IEC 61850-9-3 | IEC/IEEE 61850-9-3 should clarify the meaning and use of TimeTraceable and FrequencyTraceable | 06/21/2022 09:26 AM |
| 552 | IEC 61850 User Feedback Task Force | Support | 33 | IOP_2017/54 | Resolved | Normal | IEC 61850-9-3 | Disruption of network when TC are not set to the correct domain | 06/21/2022 09:26 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-------------|----|---------------|-------------|----------|-----------------------|--|---------------------|
| 551 | IEC 61850 User Feedback Task Force | Support | 32 | IOP_2017/53 | Resolved | Normal | IEC 61850-9-3 | IEC/IEEE 61850-9-3 - Sync messages have to be padded to the same length as the Pdelay_Req/Pdelay_Resp messages | 06/21/2022 09:26 AM |
| 550 | IEC 61850 User Feedback Task Force | Support | 31 | IOP_2017/52 | Resolved | Normal | IEC 61850-9-3 | Incorrect variance adjustment for Time Masters with degradation (loss of GPS) | 06/21/2022 09:26 AM |
| 549 | IEC 61850 User Feedback Task Force | Support | 30 | IOP_2017/51 | Resolved | Normal | IEC 61850-9-3 | Standard should clarify the relation between the PTP clock clockQuality signals and the timeQuality in TimeStamp | 06/21/2022 09:26 AM |
| 548 | IEC 61850 User Feedback Task Force | Support | 29 | IOP_2017/50 | Resolved | Normal | IEC 61850-9-3 | The start-up behaviour of Boundary Clocks | 06/21/2022 09:26 AM |
| 547 | IEC 61850 User Feedback Task Force | Support | 28 | IOP_2017/49 | Resolved | Normal | IEC 61850-9-3 | Requirement for Boundary Clocks to adjust the clock accuracy to reflect their actual accuracy, not that of their grandmaster | 06/21/2022 09:26 AM |
| 519 | IEC 61850 User Feedback Task Force | Support | 1 | UFTF | Resolved | Normal | 90-16 | Optionality in DOI NamPlt, PhyNam resp. in ICD/IID file: IED.manufacturer, .IED.type, makes a device recognition in a machine to | 06/21/2022 09:20 AM |
| 525 | IEC 61850 User Feedback Task Force | Support | 6 | IOP_2017/8 | Resolved | Normal | IEC 61850-6 | IEC 61850-6 does not allow the authentication configuration (none, password, weak, strong or certificate) to be used for Client | 06/21/2022 09:17 AM |
| 5123 | IEC 61850 User Feedback Task Force | Feature | 2 | TF 61850-80-6 | Resolved | Normal | IEC 61850-90-28 | ACSI service for link supervision on application level | 06/21/2022 08:35 AM |
| 556 | IEC 61850 User Feedback Task Force | Support | 3 | H30 | In Progress | Normal | IEC 61850-90-20 | Rendundant CT/TT measurements | 06/21/2022 02:09 AM |
| 605 | IEC 61850 User Feedback Task Force | Improvement | 4 | H30 | In Progress | Normal | IEC 61850-10-3 | Test and Simulation mode questions | 06/21/2022 02:09 AM |
| 607 | IEC 61850 User Feedback Task Force | Support | 6 | H30 | In Progress | Normal | IEC 61850-80-6 (90-2) | LPHD.Sim management | 06/21/2022 02:09 AM |
| 608 | IEC 61850 User Feedback Task Force | Feature | 7 | H30 | In Progress | Normal | IEC 61850-90-xx | Comprehensive set of requirements covering validation and supervision of all IEC 61850 communications | 06/21/2022 02:09 AM |
| 677 | IEC 61850 User Feedback Task Force | Feature | 50 | RTE | In Progress | Normal | IEC 61850-7-4 | Impact of IEC 61869-13 (SAMU) | 06/21/2022 02:04 AM |
| 622 | IEC 61850 User Feedback Task Force | Feature | 18 | RTE | Triage | Normal | IEC 61850-7-4 | Parameters not available in standardized LN | 06/20/2022 03:56 AM |
| 620 | IEC 61850 User Feedback Task Force | Feature | 16 | RTE | Triage | Normal | | New LN LPDO / LPDI in IEC 61850-7-5 | 06/20/2022 03:55 AM |
| 618 | IEC 61850 User Feedback Task Force | Improvement | 14 | RTE | Triage | Normal | IEC 61850-90-3 | Evolution of DO SumSqA of LN SPTRExt | 06/20/2022 03:54 AM |
| 5321 | IEC 61850 User Feedback Task Force | Improvement | 1 | WG17 | Resolved | Normal | IEC 61850-7-4,7-5 | Schedules - allow 3 values per time point | 06/20/2022 03:49 AM |
| 672 | IEC 61850 User Feedback Task Force | Improvement | 46 | RTE | Resolved | Normal | IEC 61850-90-4 | Create DO indicating the source of synchronisation | 06/16/2022 03:51 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|------|----------------|-------------|----------|----------------|---|---------------------|
| 676 | IEC 61850 User Feedback Task Force | Support | 49 | RTE | Resolved | Normal | IEC 61850-7-5 | Clarification of addCause | 06/14/2022 10:44 AM |
| 419 | IEC 61850 User Feedback Task Force | Support | 10.2 | ENTSO-E | In Progress | Normal | IEC 61850-7-2 | Also many other features of GOOSE messaging are left to the manufacturer to choose. | 06/14/2022 09:33 AM |
| 5335 | IEC 61850 User Feedback Task Force | Improvement | | Dustin Tessier | Resolved | Normal | IEC 61850-90-4 | Adding Normative Requirements & Conformance Testing Pertaining to Broadcast Storms | 06/14/2022 09:22 AM |
| 3115 | Client | Issues | | | Resolved | Normal | | Forward compatibility to Amd1 server with pre-assigned URCB/BRCB | 06/14/2022 08:35 AM |
| 5326 | Server | Issues | | | Resolved | Normal | | sSBOes8 incorrectly requires addCause=blocked-by-mode | 06/14/2022 08:34 AM |
| 5382 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Work Dispatch | 06/13/2022 07:50 PM |
| 5381 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Interfaces External to CIM | 06/13/2022 07:44 PM |
| 5380 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer Installation Management | 06/13/2022 07:43 PM |
| 5379 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Construction Planning revision | 06/13/2022 07:40 PM |
| 5136 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SAMU-1000 [KEPCO KDN] | 06/13/2022 05:09 PM |
| 1866 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CP-MUP [ABB Switzerland Ltd.] | 06/13/2022 03:24 PM |
| 2091 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | BHEL-MU Merging Unit [Bharat Heavy Electricals Ltd.] | 06/13/2022 03:23 PM |
| 2092 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SAMU-IX [Interoptix Inc.] | 06/13/2022 03:23 PM |
| 2093 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CMC850 Test Set [OMICRON Electronics GmbH] | 06/13/2022 03:22 PM |
| 2094 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | PCS-221 Merging Unit [NR Electric Co., Ltd.] | 06/13/2022 03:22 PM |
| 2095 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CMC256plus Test Set [OMICRON Electronics GmbH] | 06/13/2022 03:21 PM |
| 2096 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CMC353 Test Set [OMICRON Electronics GmbH] | 06/13/2022 03:21 PM |
| 2097 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CMC356 Test Set [OMICRON Electronics GmbH] | 06/13/2022 03:20 PM |
| 2098 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | YSMU-121540 [YOUSUNG Instrument & Electric Co., Ltd.] | 06/13/2022 03:20 PM |
| 2099 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MU Agile AMU [ALSTOM Grid UK LTD] | 06/13/2022 03:18 PM |
| 2100 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SO-52v11-MUA [Mikronika] | 06/13/2022 03:16 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|-----------------------|-----------------------|----|--------|----------|----------|---------------------------|---|---------------------|
| 2101 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | PRS-7395 Smart Terminal & MU [CYG SUNRI Co., Ltd.] | 06/13/2022 03:15 PM |
| 2102 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SIPROTEC 7SC805 Merging Unit [Siemens A.G., IC SG EA] | 06/13/2022 03:14 PM |
| 2103 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | DRTS 64 Relay Test Set [I.S.A. Istrumentazioni Sistemi Automatici S.r.l.] | 06/13/2022 03:14 PM |
| 2436 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Siprotec 7SC805 Merging Unit [Siemens Power Automation Ltd.] | 06/13/2022 03:13 PM |
| 2511 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | F6150sv [Doble Engineering Company] | 06/13/2022 03:12 PM |
| 2535 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | CSD-603 [Beijing Sifang Automation Co., Ltd.] | 06/13/2022 03:12 PM |
| 2601 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | FOCS-LTB420 Fiber optic current sensor [ABB Schweiz AG] | 06/13/2022 03:10 PM |
| 2633 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SAM600 Merging Unit [ABB Switzerland Ltd.] | 06/13/2022 03:10 PM |
| 2684 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | INGEPAC EF PB Merging Unit [Ingeteam Power Technology, S.A.] | 06/13/2022 03:09 PM |
| 2747 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | FOCS-FST kit (Fiber Optic Current Sensor [ABB Schweiz AG] | 06/13/2022 03:08 PM |
| 2793 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | XMU800 Merging Unit [GE Grid Solutions] | 06/13/2022 03:07 PM |
| 2861 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | G5 Digital Fault Recorder [Elspec Engineering Ltd.] | 06/13/2022 03:07 PM |
| 2949 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SMRT410 Relay Test System (4U41) [Megger] | 06/13/2022 03:06 PM |
| 2952 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SIPROTEC 5 6MU85 Merging Unit / Bay Unit [Siemens AG] | 06/13/2022 03:05 PM |
| 5137 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | IM1 [HYOSUNG CORPORATION] | 06/13/2022 03:02 PM |
| 5145 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SIPROTEC 5 7SL87 with variants [Siemens AG] | 06/13/2022 03:00 PM |
| 5147 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SIPROTEC 5 6MU85 [Siemens AG] | 06/13/2022 02:59 PM |
| 5287 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | PCS-221S [NR Electric Co., Ltd.] | 06/13/2022 02:34 PM |
| 5378 | WG14 Issues | CIM Issues | | | New | Normal | IEC61968-11, IEC61968-100 | Add Part100 Specific Metadata classes to the UML | 06/13/2022 12:01 PM |
| 5377 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MM300 [GE Renewable Energy] | 06/10/2022 08:32 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|--------|----------|----------|---------------|---|---------------------|
| 5376 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | EVRC2A-NT-610 [ENTEC Electric & Electronic Co., Ltd.] | 06/08/2022 10:50 AM |
| 5372 | IEC 61850 User Feedback Task Force | Improvement | | RTE | Resolved | Normal | IEC 61850-7-1 | Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation | 06/07/2022 09:23 AM |
| 5344 | Server | Issues | | | Rejected | Normal | | sBr29 power-up the IED is missing | 06/02/2022 04:12 PM |
| 5375 | WG13 Issues | CIM Issues | | | New | Normal | | Review removed paragraphs from Part-11 and see where they fit | 06/02/2022 03:54 PM |
| 5328 | Server | Issues | | | Resolved | Normal | | sFt2ab issues with "directory" files | 06/02/2022 03:07 PM |
| 5337 | Server | Issues | | | Resolved | Normal | | Independence of GOOSE subscriber timeouts is not tested | 06/02/2022 03:06 PM |
| 5343 | Server | Issues | | | Resolved | Normal | | sGosN2 remove PIXIT Gs5 | 06/02/2022 03:05 PM |
| 5356 | Server | Issues | | | Resolved | Normal | | PIXIT entries mandated by 61850-8-1 but missing in PIXIT | 06/02/2022 03:02 PM |
| 5373 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MULTILIN B90 [M/s. GE T&D INDIA LIMITED] | 06/01/2022 01:44 PM |
| 3013 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | PCM600 [ABB Oy] | 06/01/2022 11:07 AM |
| 5370 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Multilin D60 [GE T&D India Limited] | 05/29/2022 08:44 PM |
| 5369 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Multilin L90 [GE T&D India Limited] | 05/27/2022 12:37 PM |
| 5368 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | VIPAM-ARC [VITZRO EM CO., LTD.] | 05/27/2022 09:40 AM |
| 5277 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Subclasses of WorkRequest/WorkOrder | 05/26/2022 01:34 PM |
| 5283 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Identifying non-utility crew | 05/26/2022 01:28 PM |
| 5367 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | GRW200 [TOSHIBA Energy Systems & Solutions Corporation] | 05/25/2022 09:28 AM |
| 5366 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MUST DM624 [WOODAM TECH CO., LTD.] | 05/18/2022 09:33 AM |
| 5359 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | YH-ISD xGrids Transfer [YOUHO Electric Ind CO., Ltd.] | 05/18/2022 08:51 AM |
| 5364 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | AQ-250: AQ-F255 [Arcteq Relays Ltd.] | 05/17/2022 04:45 PM |
| 5363 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | NP950: NPF955 [ICE SAS] | 05/17/2022 04:40 PM |
| 5312 | CIM Joint Issues | CIM Issues | | | Open | Normal | IEC 61968 | Change associations for meter UsagePoint to make it more like Measurements | 05/16/2022 06:56 AM |
| 5361 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Mirage Servidor IEC 61850 [Controles S.A.] | 05/12/2022 10:10 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|---------------|-------------|----------|------------------------------------|---|---------------------|
| 5360 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | NC61850FEP [NexChal Co., Ltd.] | 05/12/2022 09:52 AM |
| 5358 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | YH-ISD xGrids Transfer [YOUHO Electric Ind CO., Ltd.] | 05/11/2022 08:57 AM |
| 5089 | IEC 61850 User Feedback Task Force | Improvement | 13 | MH | Resolved | Normal | IEC 61850 7-3 Ed2.1 | Extension of CDC ASG | 05/10/2022 09:26 AM |
| 5323 | IEC 61850 User Feedback Task Force | Improvement | 3 | WG17 | Resolved | Normal | IEC 61850-7-4,7-5 | Schedules - allow updates to single values while schedules are running | 05/10/2022 09:18 AM |
| 5357 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301, 61970-452 | Documentation on ShuntCompensator.grounded and EnergyConsumer.grounded attributes | 05/09/2022 11:06 AM |
| 5044 | WG13 Issues | CIM Issues | | | Open | Normal | | Review circuit class in CIM18 | 05/09/2022 10:58 AM |
| 5045 | WG13 Issues | CIM Issues | | | Open | Normal | | Voltage-dependent reactive capability curve support | 05/09/2022 10:51 AM |
| 5047 | WG13 Issues | CIM Issues | | | Open | Normal | 61970-301 | Clarifications on equivalents, e.g., EquivalentInjection, ExternalNetworkInjections and the aggregate attribute | 05/09/2022 10:49 AM |
| 5049 | WG13 Issues | CIM Issues | | | New | Normal | | Inconsistent naming for p,q,r,x and others | 05/09/2022 10:39 AM |
| 5062 | WG13 Issues | CIM Issues | | | Open | Low | | DC auxiliary equipment support | 05/09/2022 10:37 AM |
| 5355 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Ingepac Efx BD [Ingeteam Power Technology, S.A.] | 05/05/2022 01:33 PM |
| 5354 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | XMR-P [Thytronic S.p.A.] | 05/05/2022 12:55 PM |
| 5353 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | XMR-P [Thytronic S.p.A.] | 05/05/2022 12:49 PM |
| 5352 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | TCTCORE 61850 [The Core Tech Inc.] | 05/05/2022 11:31 AM |
| 5351 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | BCU-50-M [SAE IT-systems GmbH & Co. KG] | 05/02/2022 10:29 AM |
| 5349 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MULTILIN T60 [M/s. GE T&D INDIA LIMITED] | 05/02/2022 10:07 AM |
| 5350 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | G60 [M/s. GE T&D INDIA LIMITED] | 05/02/2022 10:05 AM |
| 5348 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SAMU-1000 [KEPCO KDN] | 04/29/2022 02:30 PM |
| 5279 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Primary crew for WorkTask | 04/28/2022 03:35 PM |
| 5273 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Use Names.name for workOrderNumber | 04/28/2022 03:31 PM |
| 5336 | IEC 61850 User Feedback Task Force | Feature | 4 | TF 61850-80-6 | In Progress | Normal | IEC 61850-7-2; IEC 61850-8-1, 80-6 | Extension of the AddCause required to reflect communication issues in multi level control | 04/26/2022 09:20 AM |
| 5275 | WG14 Part 6 Issues | CIM Issues | | | Review | High | | WorkRequest class | 04/22/2022 01:27 PM |
| 5271 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Use of Location generalizations | 04/22/2022 01:24 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|--------------|-------------|----------|--------------------|---|---------------------|
| 5270 | WG14 Part 6 Issues | CIM Issues | | | Review | High | | Location association to WorkOrder | 04/22/2022 01:23 PM |
| 5269 | WG14 Part 6 Issues | CIM Issues | | | Open | Normal | | Status attributes in WorkOrder | 04/22/2022 01:21 PM |
| 5268 | WG14 Part 6 Issues | CIM Issues | | | Review | Low | | Add rank as attribute to WorkOrder | 04/22/2022 01:19 PM |
| 5346 | WG14 Part 11 Issues | CIM Issues | | | New | Normal | 61968-11 | OrganisationRoles should be able to associate to more than one Organisation | 04/21/2022 11:49 AM |
| 5345 | WG14 Part 11 Issues | CIM Issues | | | New | Normal | 61968-11 | Add attribute nextReadingSchedule to UsagePoint | 04/21/2022 11:14 AM |
| 5329 | IEC 61850 User Feedback Task Force | Improvement | | SCL IOP 2021 | Resolved | Normal | IEC 61850-6 | Clarify iedType attribute usage in DataTypeTemplates | 04/12/2022 09:20 AM |
| 5322 | IEC 61850 User Feedback Task Force | Improvement | 2 | WG17 | Resolved | Normal | IEC 61850-7-4,7-5 | Schedules - add optional data objects to support irregular interval schedules | 04/12/2022 09:12 AM |
| 5266 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Outage association to WorkOrder | 04/08/2022 07:53 PM |
| 5267 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Deprecate/replace OutageOrder | 04/08/2022 07:52 PM |
| 5263 | WG14 Part 6 Issues | CIM Issues | | | On Hold | High | | ProcedureStep and revision of Procedure | 04/08/2022 07:49 PM |
| 5260 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Customer association to WorkOrder | 04/08/2022 07:48 PM |
| 5262 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | TimeSchedule association to WorkOrder and WorkTask | 04/08/2022 07:48 PM |
| 5261 | WG14 Part 6 Issues | CIM Issues | | | Review | Normal | | Appointment association to WorkTask | 04/08/2022 07:46 PM |
| 5342 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ZSC-100A [ZenithTek Co., Ltd.] | 04/08/2022 03:23 PM |
| 5341 | WG13 Issues | CIM Issues | | | New | Normal | 61970-452 | CPSM (61970-452) artifacts not published | 04/07/2022 09:52 AM |
| 5340 | WG13 Issues | CIM Issues | | | New | Normal | 61968-13 | CDPSM (61968-13) artifacts not published | 04/07/2022 09:50 AM |
| 5339 | WG13 Issues | CIM Issues | | | New | High | | Copyright statement to be included in the 301 template | 04/06/2022 10:42 AM |
| 5338 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MiCOM P4 Agile P746 [UK Grid Solutions Limited] | 04/04/2022 01:58 PM |
| 5334 | WG13 Issues | CIM Issues | | | New | Normal | 301 Ed8 | TapChanger model update - 301 | 03/30/2022 10:56 AM |
| 3098 | IEC 61850 User Feedback Task Force | Improvement | 1 | WG17 | In Progress | Normal | | Need to Change 8-1 to allow multiple DOs to be written | 03/29/2022 09:36 AM |
| 5331 | IEC 61850 User Feedback Task Force | Feature | | SCL IOP 2021 | Resolved | Normal | IEC 61850-6 | Multiple LNodes implemented by same LN | 03/29/2022 09:14 AM |
| 5330 | IEC 61850 User Feedback Task Force | Improvement | | SCL IOP 2021 | Resolved | Normal | IEC 61850-6, 6-100 | LNode iedName attribute usage needs to be clarified | 03/29/2022 09:00 AM |
| 5332 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Easergy MiCOM P643 [Schneider Electric Industries SAS] | 03/28/2022 04:47 PM |
| 5325 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | AVEVA Telemetry Server [AVEVA Solutions Ltd.] | 03/21/2022 12:42 PM |
| 441 | IEC 61850 User Feedback Task Force | Improvement | 4 | Vattenfall | Resolved | High | IEC 61850-6-100 | Limitations of one to one mapping between LNode and LN | 03/15/2022 11:08 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|------------|----------|----------|-------------------------------|--|---------------------|
| 442 | IEC 61850 User Feedback Task Force | Bug | 5 | Vattenfall | Resolved | High | IEC 61850-6-100 | Mapping LNode (substation section) to LN (IED section) | 03/15/2022 09:10 AM |
| 5324 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SuperTAPP SG [Fundamentals Ltd] | 03/15/2022 08:24 AM |
| 580 | IEC 61850 User Feedback Task Force | Support | 52 | ENTSO-E | Resolved | Normal | IEC 61850-7-4, 7-5 | Voltage protection: Undervoltage protection - 3ph operate | 03/01/2022 09:09 AM |
| 579 | IEC 61850 User Feedback Task Force | Support | 51 | ENTSO-E | Resolved | Normal | IEC 61850-7-4, 7-500 | Voltage protection: Overvoltage protection - 3ph operate | 03/01/2022 09:09 AM |
| 572 | IEC 61850 User Feedback Task Force | Support | 44 | ENTSO-E | Resolved | Normal | IEC 61850-7-4, 7-500 | S/S related applications: Auxiliary circuit supervision | 03/01/2022 08:37 AM |
| 5133 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | AVANT K400 [Prosoft-Systems Ltd.] | 02/16/2022 12:34 PM |
| 4989 | WG13 Issues | CIM Issues | | | Open | Normal | | Feeder:How to modelize a feeder as a collection of equipme | 02/16/2022 10:51 AM |
| 5317 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | StreamBridge [Elvexys SA] | 02/16/2022 10:32 AM |
| 3068 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | TOR 300 KC3 510 155 (TOP 300) [Relematika, LLC] | 02/15/2022 04:38 PM |
| 5316 | CIM Joint Issues | CIM Issues | | | New | Normal | IEC 61968 series | How to best associate the CIM with other related information standards such as ERP, GML, and BIM | 02/15/2022 07:24 AM |
| 5080 | IEC 61850 User Feedback Task Force | Feature | 4 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1 ,7-500 | Clarification on the ctiModel 3/3 | 02/14/2022 04:00 AM |
| 5079 | IEC 61850 User Feedback Task Force | Feature | 3 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1 , 7-500 | Clarification on the ctiModel 2/3 | 02/14/2022 03:59 AM |
| 5082 | IEC 61850 User Feedback Task Force | Feature | 6 | MH | Resolved | Normal | IEC 61850-7-4,7-5 | Clarifications on the local/remote concept 2/8 | 02/14/2022 03:57 AM |
| 5083 | IEC 61850 User Feedback Task Force | Feature | 7 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1,7-5 | Clarifications on the local/remote concept 3/8 | 02/14/2022 03:57 AM |
| 5084 | IEC 61850 User Feedback Task Force | Feature | 8 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1,7-5 | Clarifications on the local/remote concept 4/8 | 02/14/2022 03:57 AM |
| 5085 | IEC 61850 User Feedback Task Force | Feature | 9 | MH | Resolved | Normal | IEC 61850 7-1 / 7-4 Ed2.1,7-5 | Clarifications on the local/remote concept 5/8 | 02/14/2022 03:57 AM |
| 5086 | IEC 61850 User Feedback Task Force | Feature | 10 | MH | Resolved | Normal | IEC 61850-7-4 Ed2.1 ,7-5 | Clarifications on the local/remote concept 6/8 | 02/14/2022 03:56 AM |
| 5088 | IEC 61850 User Feedback Task Force | Feature | 12 | MH | Resolved | Normal | IEC 61850-7-4 Ed2.1 ,7-5 | Clarifications on the local/remote concept 8/8 | 02/14/2022 03:56 AM |
| 5087 | IEC 61850 User Feedback Task Force | Feature | 11 | MH | Resolved | Normal | IEC 61850-7-4 Ed2.1 ,7-5 | Clarifications on the local/remote concept 7/8 | 02/14/2022 03:55 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|---------------|-------------|----------|---|--|---------------------|
| 5081 | IEC 61850 User Feedback Task Force | Feature | 5 | MH | Resolved | Normal | IEC 61850-7-1 Ed2.1/7-4 Ed2.1 Annex B/7-500 | Clarifications on the local/remote concept 1/8 | 02/14/2022 02:50 AM |
| 5315 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Rename Customer Site Installation Management to CSIM | 02/12/2022 01:08 PM |
| 5314 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Asset Warranty | 02/10/2022 10:47 AM |
| 5304 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301, 61970-452, 61968-13 | Clarify description on TransformerEnd attributes | 02/10/2022 09:17 AM |
| 5313 | WG13 Issues | CIM Issues | | | New | Low | | Better description for governorSCD | 02/10/2022 01:02 AM |
| 5091 | IEC 61850 User Feedback Task Force | Feature | 10 | H30 | In Progress | Normal | IEC 61850-2 | Devices types/acronyms | 02/09/2022 10:30 AM |
| 5077 | IEC 61850 User Feedback Task Force | Feature | 1 | MH | Resolved | Normal | IEC61850 7-1 | Location of SGCB in LD structures | 02/09/2022 10:06 AM |
| 555 | IEC 61850 User Feedback Task Force | Support | 2 | H30 | Triage | Normal | | Link Failover reliability problem - implication to protection application | 02/09/2022 09:13 AM |
| 630 | IEC 61850 User Feedback Task Force | Improvement | 43 | RTE | Resolved | Normal | IEC 61850-7-5/7-500 | XCBR LN new DO to describe withdrawable circuit breaker | 02/09/2022 08:05 AM |
| 5078 | IEC 61850 User Feedback Task Force | Feature | 2 | MH | Resolved | Normal | IEC 61850-7-1 / 7-2 Ed2.1 / 7-5/7-500 | Clarification on the ctlModel 1/3 | 02/09/2022 07:11 AM |
| 5122 | IEC 61850 User Feedback Task Force | Feature | 1 | TF 61850-80-6 | Resolved | Normal | IEC 61850-90-28 | New LN in LN group L to reflect the status of TPAA between Proxy/Gateway and IED | 02/09/2022 07:06 AM |
| 5311 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MiCOM Agile P345 [GE T&D INDIA LIMITED] | 02/07/2022 12:11 PM |
| 5048 | WG13 Issues | CIM Issues | | | Open | Normal | | Per CDV country comments CH_71, NO64 & SE68 for 301 Ed7:H | 02/07/2022 11:06 AM |
| 5310 | IEC TC57 WG10 Future Work | WG10FutureWork | | WG 18 | Accepted | Normal | IEC 61850-7-3 | New CDC for IEC/TC 57/WG 18 | 02/07/2022 03:54 AM |
| 5309 | WG13 Issues | CIM Issues | | | New | High | | Support on FACTS device modeling | 02/06/2022 09:03 PM |
| 5111 | WG13 Issues | CIM Issues | | | Review | Normal | 61970-301 | Versioning of CIM packages | 02/04/2022 03:00 PM |
| 5305 | CIM Joint Issues | CIM Issues | | | New | Normal | | test issue | 01/30/2022 08:30 AM |
| 5307 | WG13 Issues | CIM Issues | | | New | Normal | | test | 01/30/2022 08:11 AM |
| 5306 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | test issue | 01/30/2022 08:06 AM |
| 5302 | CIM Joint Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4, 61970-301, 61968-13 | Explicit association between TransformerTank and TransformerTankInfo | 01/30/2022 05:34 AM |
| 5303 | WG13 Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4, 61970-301, 61968-13 | 5302:5303 61970 portion of TransformerTank to TransformerTankInfo association | 01/30/2022 05:32 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|-----------------------|-----------------------|----|--------|----------|----------|--|--|---------------------|
| 5300 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4 | 5302:5301:5300 Part 4 TransformerTankInfo | 01/30/2022 05:27 AM |
| 5301 | WG14 Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4 | 5302:5301 61968 portion of TransformerTankInfo to TransformerTank association | 01/30/2022 05:09 AM |
| 5299 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301, 61968-13 | ACLLineSegment updates for mutual coupling | 01/30/2022 04:15 AM |
| 5295 | CIM Joint Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4, 61970-301, 61968-13 | Joint issue on ACLLineSegment physical modeling clarification | 01/30/2022 04:14 AM |
| 5296 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4 | 5295:5297:5296 - WG14 Part 4 WireAssemblyInfo and related cleanup for ACLLineSegment physical modeling | 01/30/2022 04:12 AM |
| 5297 | WG14 Issues | CIM Issues | | | New | Normal | 61968-11, 61968-4 | 5295:5297 61968 AssetInfo cleanup for ACLLineSegment physical modeling | 01/30/2022 04:12 AM |
| 5298 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301, 61968-13 | 5295:5298 61970 PhaseImpedanceData cleanup for ACLLineSegment physical modeling | 01/30/2022 04:11 AM |
| 5294 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MPU55/MPU56 [Nexus Controls LLC] | 01/27/2022 03:23 PM |
| 5099 | WG13 Issues | CIM Issues | | | Open | High | 61970-301 | Not possible to properly model variable shunt reactor | 01/27/2022 01:22 PM |
| 5113 | WG13 Issues | CIM Issues | | | New | Normal | | NonlinearShuntCompensator has ambiguity in definition of per section or total | 01/27/2022 01:01 PM |
| 5068 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301 | Energy allocation to devices | 01/26/2022 11:05 AM |
| 5000 | WG13 Issues | CIM Issues | | | Open | Normal | | Use of GeneatingUnit.normalPF The attribute is used by ENT | 01/26/2022 10:43 AM |
| 5012 | WG13 Issues | CIM Issues | | | Open | Normal | | Exchange of seasonal limit sets.Functionally this is excha | 01/26/2022 10:38 AM |
| 5016 | WG13 Issues | CIM Issues | | | Open | Normal | | OperationalLimit for BranchGroupNeed a means to apply the | 01/26/2022 10:32 AM |
| 5290 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | saTECH SCU-HMI 122 [Arteche/SAC] | 01/24/2022 01:14 PM |
| 5291 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | RTU194 [Controles S.A.] | 01/24/2022 01:11 PM |
| 5152 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MCS-8500 [XJ Electric Co., Ltd.] | 01/16/2022 09:55 AM |
| 5280 | WG14 Part 6 Issues | CIM Issues | | | On Hold | Normal | | Asset association to MaterialItem | 01/13/2022 08:47 AM |
| 5264 | WG14 Part 4 Issues | CIM Issues | | | New | High | | ProcedureStep and revision of Procedure | 01/13/2022 08:46 AM |
| 5282 | WG14 Part 6 Issues | CIM Issues | | | New | Normal | | WorkTask association to MaterialItem | 01/13/2022 08:40 AM |
| 5281 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Asset association to MaterialItem | 01/13/2022 08:40 AM |
| 5274 | WG14 Part 6 Issues | CIM Issues | | | New | Low | | Review/update enumerations | 01/13/2022 08:40 AM |
| 5272 | WG14 Part 6 Issues | CIM Issues | | | New | High | | Class for WorkTask cost/related attributes | 01/13/2022 08:40 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|--------------------|------------|----|--------|---------|----------|-------------|--|---------------------|
| 5265 | WG14 Part 6 Issues | CIM Issues | | | On Hold | Normal | | DesignLocation association to WorkTask | 01/13/2022 08:40 AM |
| 5255 | WG14 Part 4 Issues | CIM Issues | | | New | High | | ProcedureStep and revision of Procedure | 01/13/2022 08:38 AM |
| 5250 | WG14 Issues | CIM Issues | | | New | High | | Document identification | 01/13/2022 06:39 AM |
| 5249 | WG14 Issues | CIM Issues | | | New | High | | Document activity | 01/13/2022 06:39 AM |
| 5248 | WG14 Issues | CIM Issues | | | New | High | | Contract work | 01/13/2022 06:39 AM |
| 5247 | WG14 Issues | CIM Issues | | | New | High | | Refactor Location | 01/13/2022 06:39 AM |
| 5246 | WG14 Issues | CIM Issues | | | New | High | | Object status | 01/13/2022 06:39 AM |
| 5245 | WG14 Issues | CIM Issues | | | New | High | | Non standard addresses | 01/13/2022 06:39 AM |
| 5244 | WG14 Issues | CIM Issues | | | New | High | | Location legal descriptions | 01/13/2022 06:39 AM |
| 5243 | CIM Joint Issues | CIM Issues | | | New | High | | Measurement activity | 01/13/2022 06:39 AM |
| 5242 | WG14 Issues | CIM Issues | | | New | High | | Crew membership tracking | 01/13/2022 06:39 AM |
| 5241 | WG14 Issues | CIM Issues | | | New | High | | Document type | 01/13/2022 06:39 AM |
| 5240 | WG14 Issues | CIM Issues | | | New | High | | Multiple TelephoneNumber associations | 01/13/2022 06:39 AM |
| 5239 | WG14 Issues | CIM Issues | | | New | High | | Multiple ElectronicAddress associations | 01/13/2022 06:39 AM |
| 5238 | WG14 Issues | CIM Issues | | | New | High | | Multiple Address associations | 01/13/2022 06:39 AM |
| 5237 | WG14 Issues | CIM Issues | | | New | High | | Eliminate compounds | 01/13/2022 06:39 AM |
| 5236 | WG14 Issues | CIM Issues | | | New | High | | Refactor TimeSchedule | 01/13/2022 06:39 AM |
| 5235 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetKind enumeration list | 01/12/2022 02:44 PM |
| 5234 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Structure can contain multiple Poles | 01/12/2022 02:44 PM |
| 5233 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Move UndergroundStructure classes (e.g. Pole & Tower) to Normative package | 01/12/2022 02:44 PM |
| 5232 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | PeriodicStatisticalCalculation Class Description | 01/12/2022 02:44 PM |
| 5231 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Asset Structure Associations | 01/12/2022 02:44 PM |
| 5230 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Maintenance Requirement | 01/12/2022 02:44 PM |
| 5229 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Part-3 AssetConfig profile should be moved to Part-4 | 01/12/2022 02:44 PM |
| 5228 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - EndDevice | 01/12/2022 02:44 PM |
| 5227 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - DER | 01/12/2022 02:44 PM |
| 5226 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Test Model | 01/12/2022 02:44 PM |
| 5225 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetDeployment | 01/12/2022 02:44 PM |
| 5224 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - Structure | 01/12/2022 02:44 PM |
| 5223 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - AuxiliaryEquipment | 01/12/2022 02:44 PM |
| 5222 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - Controller | 01/12/2022 02:44 PM |
| 5221 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - FACTS Device | 01/12/2022 02:44 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|--------------------|------------|----|--------|--------|----------|-------------|--|---------------------|
| 5220 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - Compensator | 01/12/2022 02:44 PM |
| 5219 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | AssetInfo - Rigid Busbar Section | 01/12/2022 02:44 PM |
| 5218 | WG14 Part 4 Issues | CIM Issues | | | New | Low | | Deprecate AssetOrganisationRole | 01/12/2022 02:44 PM |
| 5217 | WG14 Part 4 Issues | CIM Issues | | | New | Normal | | Deprecate electronicAddress | 01/12/2022 02:44 PM |
| 5216 | WG14 Part 4 Issues | CIM Issues | | | New | Low | | Add kindOther to Asset | 01/12/2022 02:44 PM |
| 5215 | WG14 Part 4 Issues | CIM Issues | | | New | High | | Add ProcedureStep | 01/12/2022 02:44 PM |
| 5214 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer Installation Management (CIM) rename | 01/12/2022 02:44 PM |
| 5213 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer Account Management (ACT) not following naming convention | 01/12/2022 02:44 PM |
| 5212 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | CompatibleUnit association to Conceptual Design Development | 01/12/2022 02:44 PM |
| 5211 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Missing structural analysis function | 01/12/2022 02:44 PM |
| 5210 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Consider to add Business Actor & Role into the IRM for Ed.4 | 01/12/2022 02:44 PM |
| 5209 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Outage Management Business Function | 01/12/2022 02:44 PM |
| 5208 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | To link ArchiMate to UML on how to use IRM for Part teams | 01/12/2022 02:44 PM |
| 5207 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Add Business Roles into IRM Model (for Ed.4) | 01/12/2022 02:44 PM |
| 5206 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | TC57 WG13 / 14 scope | 01/12/2022 02:44 PM |
| 5205 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Asset Decision Support (ADS) | 01/12/2022 02:44 PM |
| 5204 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Use of IEC Cloud server for IRM model | 01/12/2022 02:44 PM |
| 5203 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | IRM team to review SyC work for 61850 actors | 01/12/2022 02:44 PM |
| 5202 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Function decomposition | 01/12/2022 02:44 PM |
| 5201 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Document the process on using IEC 62913 series business / system use cases | 01/12/2022 02:44 PM |
| 5200 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Add an activity diagram example in Appendix A.5 | 01/12/2022 02:44 PM |
| 5199 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Need to include functions relevant to Transactive Energy | 01/12/2022 02:44 PM |
| 5198 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Merge EXT business functions to individual Parts | 01/12/2022 02:44 PM |
| 5197 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | To align IRM with Archimate 2.x | 01/12/2022 02:44 PM |
| 5196 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | A consolidated IRM for WG13, WG14 and WG16 | 01/12/2022 02:44 PM |
| 5195 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Typos in Annex A | 01/12/2022 02:44 PM |
| 5194 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Public Outage Data Distribution | 01/12/2022 02:44 PM |
| 5193 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | First Responder Outage Data Distribution | 01/12/2022 02:44 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|--------------------|------------|----|--------|--------|----------|-------------|---|---------------------|
| 5192 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Move message header (including verbs) and other structures into Part-100 | 01/12/2022 02:44 PM |
| 5191 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Discussion on the IEC 62913 Ed 1 SGAM to identify any gaps for Part-1 IRM | 01/12/2022 02:44 PM |
| 5190 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | IoT functions to be accommodated | 01/12/2022 02:44 PM |
| 5189 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Merge EPRI / SGIP Use Case Actors list into Part-1 IRM | 01/12/2022 02:44 PM |
| 5188 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Key ADMS functionalities: | 01/12/2022 02:44 PM |
| 5187 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | IRM sub-function issues from the Part 4 work | 01/12/2022 02:44 PM |
| 5186 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Incomplete IEC 61968 Data Model, Profiles and Messages | 01/12/2022 02:44 PM |
| 5185 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Use case harmonisation between SGIP and EPRI | 01/12/2022 02:44 PM |
| 5184 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | SGIP Function/Services missing in the Part-1 IRM | 01/12/2022 02:44 PM |
| 5183 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Use SGIP actor list and TC8 actor list by reference | 01/12/2022 02:43 PM |
| 5182 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Needs a centralized repository for common profiles of entire WG14 | 01/12/2022 02:43 PM |
| 5181 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Customer support (Part-8) on Demand Response | 01/12/2022 02:43 PM |
| 5180 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Business functions on HAN / DER / EV | 01/12/2022 02:43 PM |
| 5179 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | To clarify interoperability | 01/12/2022 02:43 PM |
| 5178 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Update Section 3.3 / Table 2 | 01/12/2022 02:43 PM |
| 5177 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Update Section 5.6 / Last paragraph | 01/12/2022 02:43 PM |
| 5176 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Update Section A.6 / Table A.2 | 01/12/2022 02:43 PM |
| 5175 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Re-organize Figure 1 | 01/12/2022 02:43 PM |
| 5174 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Change "61968-1" to "61968" so "...Figure 1 clarifies the scope of IEC 61968 graphically in terms of" | 01/12/2022 02:43 PM |
| 5173 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Consider to specify "automated geographical mapping" | 01/12/2022 02:43 PM |
| 5172 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Are profiles related to grammar/syntax or only to an abstract definition of CIM subset ? | 01/12/2022 02:43 PM |
| 5171 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | 61968 RDF statement | 01/12/2022 02:43 PM |
| 5170 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Comments on Web Services (WS) | 01/12/2022 02:43 PM |
| 5169 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Describe the meaning of "DAC" "VRU" | 01/12/2022 02:43 PM |
| 5168 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Modify "enables a non-compliant software application to use the services." | 01/12/2022 02:43 PM |
| 5167 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Typo | 01/12/2022 02:43 PM |
| 5166 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Should the section refer to IEC/PAS 62559 ? | 01/12/2022 02:43 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|---------------|-------------|----------|----------------|--|---------------------|
| 5165 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Message type comment | 01/12/2022 02:43 PM |
| 5164 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Recommendation / direction on foreign language support | 01/12/2022 02:43 PM |
| 5163 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Mobile Workforce Management | 01/12/2022 02:43 PM |
| 5162 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Missing actor AM-MAM in Part-1 | 01/12/2022 02:43 PM |
| 5161 | WG14 Part 1 Issues | CIM Issues | | | New | Normal | | Refer to methodology document | 01/12/2022 02:43 PM |
| 5160 | WG14 Issues | CIM Issues | | | New | Normal | | Location Model Update | 01/12/2022 02:18 PM |
| 5159 | WG14 Issues | CIM Issues | | | New | Normal | | Address Model Update | 01/12/2022 02:18 PM |
| 5158 | WG14 Issues | CIM Issues | | | New | Normal | | Person Model Update | 01/12/2022 02:18 PM |
| 5157 | WG14 Issues | CIM Issues | | | New | Normal | | Organisation Model Update | 01/12/2022 02:18 PM |
| 5108 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301 | PowerTransformerEnd | 01/09/2022 09:02 PM |
| 5124 | IEC 61850 User Feedback Task Force | Feature | 3 | TF 61850-80-6 | In Progress | Normal | IEC 61850-80-6 | Telemonitoring blocking | 12/21/2021 09:26 AM |
| 554 | IEC 61850 User Feedback Task Force | Support | 1 | H30 | Resolved | Normal | | Performance requirement for SV and implications to Protection applications | 12/21/2021 08:56 AM |
| 5146 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SIPROTEC 5 Compact 7SX800 [Siemens AG] | 12/17/2021 02:16 PM |
| 5148 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SIPROTEC 5 7SJ82 with variants [Siemens AG] | 12/17/2021 02:12 PM |
| 5150 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ENTEK E2R2(G)-1 [ENTELES LLC] | 12/15/2021 02:23 PM |
| 5149 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ARIS-2305 [Prosoft-Systems Ltd.] | 12/15/2021 02:11 PM |
| 5144 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SM160-02M/D [Prompibor Plant Limited] | 12/15/2021 10:59 AM |
| 5141 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | USPD 248.M2 [SYSTEL LLC] | 12/13/2021 10:00 AM |
| 5140 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ARIS-C303 Bay controller [Prosoft-Systems Ltd.] | 12/13/2021 09:51 AM |
| 5139 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | saTECH SCU-HMI 122 [Arteche/SAC] | 12/13/2021 09:41 AM |
| 5138 | Server | Issues | | | Rejected | Normal | | sBr13 without pre-assignment | 12/13/2021 04:43 AM |
| 5135 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | TOPAZ DRP-35 [PLC Technology] | 12/06/2021 03:22 PM |
| 5134 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | P0101 [NIPOM] | 12/06/2021 03:16 PM |
| 5132 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | BIM 2235.89.16/16 ADP01 [STC GOSAN Ltd.] | 12/06/2021 03:02 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|-----------------------|-----------------------|----|--------|----------|----------|---------------------------------|---|---------------------|
| 4987 | WG13 Issues | CIM Issues | | | Open | Normal | | ExternalNetworkInjection.maxQ .minQ descriptionNote talks | 12/01/2021 11:59 AM |
| 4994 | WG13 Issues | CIM Issues | | | Open | Normal | | Documentation missingat several classes and associations. | 12/01/2021 11:56 AM |
| 4995 | WG13 Issues | CIM Issues | | | Open | Normal | | Time intervalsFor time intervals to be used in series the | 12/01/2021 11:56 AM |
| 4999 | WG13 Issues | CIM Issues | | | Open | Normal | | Use of RequaltingControl/TapChangerControlThe use cases fo | 12/01/2021 11:56 AM |
| 5001 | WG13 Issues | CIM Issues | | | Open | Normal | | Modelling line segmentsThere is a need to model line segme | 12/01/2021 11:53 AM |
| 5002 | WG13 Issues | CIM Issues | | | Open | Normal | | Line zag temperatureThe line zag is dependent on temperatu | 12/01/2021 11:53 AM |
| 5003 | WG13 Issues | CIM Issues | | | Open | Normal | | Profile dependenciesHow the differnet profiles depend on e | 12/01/2021 11:52 AM |
| 5004 | WG13 Issues | CIM Issues | | | Open | Normal | | Short circuit data for power electronicsCurrently PowerEle | 12/01/2021 11:51 AM |
| 5005 | WG13 Issues | CIM Issues | | | Open | Normal | | GroundDisconnector examplesThe intended use of GroundDisco | 12/01/2021 11:51 AM |
| 5006 | WG13 Issues | CIM Issues | | | Open | Normal | | Overlap between transformer xMin and xThe TransformerEnd.x | 12/01/2021 11:50 AM |
| 5011 | WG13 Issues | CIM Issues | | | Open | Normal | | The 61970 452 profile and 456 profile both contain the same | 12/01/2021 11:49 AM |
| 5014 | WG13 Issues | CIM Issues | | | Open | Normal | | Handling unit multiplierNeed a policy for WG13 with respec | 12/01/2021 11:47 AM |
| 5063 | WG13 Issues | CIM Issues | | | Open | Normal | 61970-301, 61970-452, 61970-456 | There are a variety of issues with RegulatingControl. Thes | 12/01/2021 11:41 AM |
| 5076 | WG13 Issues | CIM Issues | | | New | High | 61970-301, 61970-452, 61970-456 | Convention and usage of operational limits of GeneratingUnit and injections | 12/01/2021 11:39 AM |
| 5129 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | WXH-803 [XJ Electric Co., Ltd.] | 11/30/2021 04:37 PM |
| 5128 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | WCB-822C [XJ Electric Co., Ltd.] | 11/30/2021 04:31 PM |
| 5038 | WG13 Issues | CIM Issues | | | Open | Low | | 18 CIM attributes whose name starts with the name of contai | 11/23/2021 05:48 PM |
| 5035 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 1 attributes (whose type is enumerated type | 11/23/2021 05:39 PM |
| 5036 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 18 CIM attributes whose name starts with an | 11/23/2021 05:39 PM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|----------|----------|----------|---------------|---|---------------------|
| 5037 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 71 CIM attributes that should be singular - | 11/23/2021 05:38 PM |
| 5039 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 46 associations that have same documentatio | 11/23/2021 05:37 PM |
| 5042 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 215 CIM association ends that should be plu | 11/23/2021 05:36 PM |
| 5040 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 6 informative associations missing informat | 11/23/2021 05:35 PM |
| 5041 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 2 association ends whose name contains ille | 11/23/2021 05:35 PM |
| 5043 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 3 CIM association ends that should be singu | 11/23/2021 05:34 PM |
| 5025 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean Found 10 packages with unexpected embedded elemen | 11/23/2021 05:25 PM |
| 5026 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean Found 23 enumeration classes with bad name: name | 11/23/2021 05:25 PM |
| 5027 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean Found 4 CIM classes never used in any association | 11/23/2021 05:24 PM |
| 5028 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean Found 1 CIM datatype classes that should have at | 11/23/2021 05:24 PM |
| 5029 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 7 classes whose documentation does not end | 11/23/2021 05:23 PM |
| 5030 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 11 CIM classes that should be singular - re | 11/23/2021 05:22 PM |
| 5031 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 1 enum classes that have some codes, but no | 11/23/2021 05:22 PM |
| 5032 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 18 CIM classes never used as type for attri | 11/23/2021 05:21 PM |
| 5033 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 2 CIM attributes that are not 'static const | 11/23/2021 05:21 PM |
| 5034 | WG13 Issues | CIM Issues | | | Open | Low | | JCIMClean found 7 attributes that have word 'flag'. - renam | 11/23/2021 05:20 PM |
| 5126 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MVI56E-61850C [ProSoft Technology, Inc] | 11/23/2021 09:33 AM |
| 5125 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | MVI56E-61850C [ProSoft Technology, Inc] | 11/23/2021 09:28 AM |
| 3102 | IEC TC57 WG10 Future Work | WG10FutureWork | | TissueDB | Resolved | Normal | IEC 61850-7-4 | https://iec61850.tissue-db.com/tissue/1744 Clarification of Start Times in StrTm.setCal | 11/23/2021 08:46 AM |
| 3101 | IEC 61850 User Feedback Task Force | Bug | 3 | TissueDB | Resolved | Normal | IEC 61850-7-4 | IEC61850.Tissue #1755 Event driven schedules – Add DO to stop schedule by event | 11/23/2021 08:34 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|------------------------------------|-----------------------|----|----------|----------|----------|---------------------------------|--|---------------------|
| 3100 | IEC 61850 User Feedback Task Force | Improvement | 2 | TissueDB | Resolved | Normal | IEC 61850-7-4 | IEC61850.Tissue #1754 Event driven schedules - Type of InSyn missing | 11/23/2021 08:33 AM |
| 3099 | IEC 61850 User Feedback Task Force | Improvement | 1 | TissueDB | Resolved | Normal | IEC 61850-7-4 | IEC61850.Tissue #1756 Event driven schedules – Extend description | 11/23/2021 08:32 AM |
| 5121 | IEC TC57 WG10 Future Work | WG10FutureWork | | | New | Normal | 61850-7-2 | sFt2ab does not verify that the LastModified value is consistent or changes when file is modified | 11/16/2021 09:03 AM |
| 5118 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | TwinCarp [Hsiang Cheng Electric Corp] | 11/10/2021 10:34 AM |
| 5117 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ProField-HE Substation Automation Gateway [Prolan Power Zrt] | 11/08/2021 12:45 PM |
| 5116 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ENIP-2-45/100-220-A2E4x2-21 [Engineering Center Energoservice] | 11/05/2021 12:02 PM |
| 5115 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | TESLA 4000 [M/s. Phase Power Protection Private Limited] | 11/03/2021 04:15 PM |
| 5114 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | APCG-42 Data Concentrator/RTU [Ashida Electronics Pvt. Ltd.] | 10/29/2021 09:34 AM |
| 5106 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | SA-ICD [Hyosung Heavy Industries Co., Ltd.] | 10/18/2021 08:16 AM |
| 5104 | IEC TC57 WG10 Future Work | WG10FutureWork | | WG 17 | Accepted | Normal | IEC 61850-6 | Add a type code 'INV' | 10/12/2021 08:59 AM |
| 5105 | IEC TC57 WG10 Future Work | WG10FutureWork | | WG 10 | Accepted | Normal | | Outcome of WG 10 Workshop "Future of IEC 61850" | 10/08/2021 12:41 PM |
| 5103 | IEC TC57 WG10 Future Work | WG10FutureWork | | IEEE H27 | Accepted | Normal | IEC 61850-7-2 | Modified/new CDC for IEEE H27 | 10/08/2021 02:27 AM |
| 5101 | IEC TC57 WG10 Future Work | WG10FutureWork | | | New | Normal | | test | 10/07/2021 11:40 AM |
| 5098 | WG13 Issues | CIM Issues | | | New | High | 71970-301, 61970-452, 61970-600 | CsConverter targtAlpha and targetGamma | 10/03/2021 03:33 PM |
| 5097 | WG13 Issues | CIM Issues | | | New | Normal | 61970-301, 61970-452 | Allow OperationalLimitSet to be described by a Season by adding a new association between OperationalLimitSet and Season | 10/01/2021 11:24 AM |
| 5096 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | TwinCarp [Hsiang Cheng Electric Corp] | 09/30/2021 11:26 AM |
| 675 | IEC 61850 User Feedback Task Force | Support | 48 | RTE | Resolved | Normal | IEC 61850-7-4 Ed2.1 | Clarification of blocked mode | 09/29/2021 03:50 AM |
| 673 | IEC 61850 User Feedback Task Force | Improvement | 47 | RTE | Resolved | Normal | | CPU monitoring | 09/29/2021 03:50 AM |
| 5093 | WG13 Issues | CIM Issues | | | New | Normal | | Clarify ambiguity on using Terminal phases for unbalanced loads. | 09/22/2021 09:08 AM |

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|-----------------------|-----------------------|----|--------|----------|----------|-------------|--|---------------------|
| 5075 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | LK_SAICD [LK Eleven Co., Ltd] | 09/16/2021 12:52 PM |
| 5074 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | LK_SAOPD [LK Eleven Co., Ltd] | 09/16/2021 12:46 PM |
| 5073 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | LK_SALID [LK Eleven Co., Ltd] | 09/16/2021 10:07 AM |
| 5072 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | LK_SAIMD [LK Eleven Co., Ltd] | 09/15/2021 07:00 PM |
| 5071 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | ENCS-3m.648-1-3 [Engineering Center Energoservice] | 09/15/2021 01:06 PM |
| 5070 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Easergy MiCOM P546 [Schneider Electric Industries SAS] | 09/15/2021 12:35 PM |
| 5069 | IEC 61850 Certificate | IEC 61850 Certificate | | | Approved | Normal | | Easergy MiCOM P139 [Schneider Electric Industries SAS] | 09/15/2021 12:13 PM |
| 5015 | WG13 Issues | CIM Issues | | | Open | Normal | | Specify validation constraints like via OCLAdd constraints | 09/14/2021 06:27 PM |
| 5013 | WG13 Issues | CIM Issues | | | Open | Normal | | Unused abstract classes in profilesSometimes inheritance i | 09/14/2021 06:25 PM |
| 5010 | WG13 Issues | CIM Issues | | | New | Normal | | Support exchange of limit values in SSH profile - Need to e | 09/14/2021 03:47 PM |
| 4996 | WG13 Issues | CIM Issues | | | Open | Normal | | IdentifiedObject.name to be optional There are many classes | 09/14/2021 03:47 PM |

...