

## IEC 61850 User Feedback Task Force - Bug #403

### Problem exchanging SCL file between tools

02/03/2021 02:07 PM - Herbert Falk

<b>Status:</b> Closed	<b>Start date:</b>
<b>Priority:</b> High	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b>	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	<b>To discuss in WG10:</b>
<b>ID:</b> 1	<b>Short Proposal:</b> We will get the files and analyse the issues; will be handled between Diederik Moers and Thierry Dufaure
<b>Source:</b> ENTSO-E	<b>Standard(s):</b>
<b>TF Unique ID:</b> 1 # ENTSO-E	<b>Needs More Information:</b>
<b>WG10 Proposal:</b> The issue came from ENTSO-E and in particular from ELIA. Because there is no action. It is decided to close the issue.	<b>Assigned TF:</b>
<b>Estimated Completion:</b> June 2014 WG 10 Meeting	
<b>Discuss in Upcoming Meeting:</b>	

**Description**

There may be problems by exchanging SCL files between tools. In this particular case, this may be associated with TISSUE 425.

As an example, we've experienced problems with importing SCL files (CID file for exemple with SBO function) from one vendor to another. We had to make small adaptations in the SCD file (add manually SBO, although SBO was mentioned in the CID) in order to make it work. When bringing this to the attention of the concerned manufacturers, they replied that their IED (and therefore the SCL file) is certified and therefore not the source of the problem.

#### History

##### #1 - 02/03/2021 02:19 PM - Herbert Falk

- Subject changed from *There may be problems by exchanging SCL files between tools.*  
In this particular case, this may be associated with TISSUE 425.

A to *There may be problems by exchanging SCL files between tools.*In this particular case, this may be associated with TISSUE 425.A

- Status changed from *New* to *Closed*

- WG10 Proposal changed from *The issue came from ENTSO-E and in particular from ELIA.*

*Because there is no action. It is decided to close the issue.* to *The issue came from ENTSO-E and in particular from ELIA. Because there is no action. It is decided to close the issue.*

##### #2 - 02/03/2021 03:54 PM - Herbert Falk

- Priority changed from *Normal* to *High*

##### #3 - 02/09/2021 06:22 AM - Carlos Rodriguez del Castillo

- Subject changed from *There may be problems by exchanging SCL files between tools.*In this particular case, this may be associated with TISSUE 425.A to *Problem exchanging SCL file between tools*