

WG13 Issues - CIM Issues #4038

Add potential transformer attribute for inductive Need to a

09/14/2021 03:43 PM - Herbert Falk

| | |
|--|--|
| Status: Closed | |
| Priority: Normal | |
| Target version: | |
| Author/Contact Info: Kendall Demaree | Standard(s): |
| Base Release: 61970cim15v33 | Version: |
| Solution to be Applied To: | Clause: |
| Solution Version: CIM16 | Sub-Clause: |
| Solution Applied By: KDD | Paragraph: |
| Completion Date: 12/16/2011 | Table: |
| CIM Keywords: | Originally Closed in Version: CIM16 |
| Breaking Change: No | Origination Date: 10/27/2011 |
| Breaking Change Description: | Origination ID: 13_102 |
| CIM Impacted Groups: WG13 | Originally Assigned To: |
| Requestor: | |
| Description Add potential transformer attribute for inductive Need to add an indication of the potential transformer being inductive.. | |
| Proposed Solution Add a new attribute to the potential transformer listing the types. Suggest this be an enumeration on the Potential. Phasing information may be needed as well. Phasing information could go on AuxilliaryEquipment. | |
| Decision Add. | |