WG13 Issues - CIM Issues #4103

Description ControlArea

1: IOP suggest to change the descri

09/14/2021 03:44 PM - Herbert Falk

Status: Closed

Priority: Normal

Target version:

Author/Contact Info: **ENTSO-E N9** Base Release: 61970cim16v21 61970cim16v22

Solution to be Applied To:

Sub-Clause: Solution Version: CIM₁₆ Solution Applied By: LOO Paragraph:

Completion Date: 06/01/2013 Table:

CIM Keywords: **Originally Closed in** CIM₁₆

Version:

Origination ID:

13_164

Standard(s):

Version:

Clause:

Breaking Change: Origination Date: 05/29/2013 No

Breaking Change Description:

CIM Impacted

Groups:

WG13

Originally Assigned

To:

Requestor:

Description

Description ControlArea

1: IOP suggest to change the description of ControlArea.netInterchange to clarify the sign (is the value positive if the area imports?, etc.). Consistency with svPowerFlow should be applied.

Proposed Solution

Proposed text netInterchange:

i.e. positive sign means flow in to the area.

Decision

Updated 2013-06-01/LOO

05/21/2024 1/1