

WG13 Issues - CIM Issues #4105

DCPoleOperatingModeKind

The class should be renamed as we d

09/14/2021 03:44 PM - Herbert Falk

Status: Closed	
Priority: Normal	
Target version:	
Author/Contact Info: ENTSO-E N11	Standard(s):
Base Release: 61970cim16v21	Version:
Solution to be Applied To: 61970cim16v22	Clause:
Solution Version: CIM16	Sub-Clause:
Solution Applied By: LOO	Paragraph:
Completion Date: 06/01/2013	Table:
CIM Keywords:	Originally Closed in Version: CIM16
Breaking Change: No	Origination Date: 05/29/2013
Breaking Change Description:	Origination ID: 13_167
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor:	
Description DCPoleOperatingModeKind The class should be renamed as we do not have DCPole anymore	
Proposed Solution Rename to DCConverterOperatingModeKind.	
Decision Updated 2013-06-01/LOO	