

WG13 Issues - CIM Issues #4674

Adjust doc.

09/14/2021 03:46 PM - Herbert Falk

Status: Closed	
Priority: Normal	
Target version:	
Author/Contact Info: Tatjana Kostic	Standard(s):
Base Release:	Version:
Solution to be Applied To:	Clause:
Solution Version: CIM11	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords:	Originally Closed in Version: CIM11
Breaking Change: No	Origination Date: 11/12/2007
Breaking Change Description:	Origination ID: 608
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor:	
Description Adjust doc.	
Proposed Solution Provide correct documentation for InductionMotorLoad. Remove sentence: " The typeName attribute indicates the type of induction * motor (1 = wound rotor) (2 = squirrel cage)." Note: If you need info on type: 1) create a new enum in this package, and, 2) add a 'type' attribute to InductionMotorLoad, and its doc "Type of induction motor load".	
Decision 20071130/LOO Same problem as with CustomerLoad. Is there a good usecase motivating to keep it? Is the load parameters in EquivalentLoad sufficient and InductionMotor can be removed? 2009-03-11: KLH - CustomerLoad and InductionMotorLoad have both been removed from the model with issue 607. Close.	