

WG13 Issues - CIM Issues #4899

WindingTest Issue Related - The following attributes need t

09/14/2021 03:47 PM - Herbert Falk

Status: Closed	
Priority: Normal	
Target version:	
Author/Contact Info: UCTE IOP (Issue 15)	Standard(s):
Base Release:	Version:
Solution to be Applied To:	Clause:
Solution Version: CIM15	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords:	Originally Closed in Version: CIM15
Breaking Change: No	Origination Date: 04/01/2009
Breaking Change Description:	Origination ID: 1223
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor:	
Description WindingTest Issue Related - The following attributes need to be added to the Transformer model in the CIM: No load losses (Pn), no load current (I0) and short circuit voltage for windings 1 & 2 (uk12/Pk12), windings 1 & 3 (uk13/Pk13), and windings 2 & 3 (uk23/Pk23).	
Decision 2009-06-04: KLH - All of these values either exist in the model or can be derived from values that exist in the model. Closed.	