

WG13 Issues - CIM Issues #4925

SynchronousMachine.type should use full type nameThe attri

09/14/2021 03:47 PM - Herbert Falk

Status: Closed	
Priority: Low	
Target version:	
Author/Contact Info: Kendall Demaree for Chuck Dubose	Standard(s):
Base Release: 61970cim15v31	Version:
Solution to be Applied To: 61970cim16	Clause:
Solution Version: CIM17	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords:	Originally Closed in Version:
Breaking Change: No	Origination Date: 08/09/2011
Breaking Change Description:	Origination ID: 13_81
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor:	
Description	
SynchronousMachine.type should use full type name The attribute name should be more explicit and more like the enumeation type.	
Proposed Solution	
Suggest a new attribute name.	

History

#1 - 02/07/2023 12:05 PM - Chavdar Ivanov

- Subject changed from SynchronousMachine.type should use full type name
The attri to SynchronousMachine.type should use full type nameThe attri
- Status changed from Open to In Progress
- Base Release changed from 61970cim15v31
to 61970cim15v31
- Solution Version set to CIM17

There is an enumeration SynchronousMachineKind and the enumeration contains the full names of the types. Therefore the issue is considered fixed in CIM17.

#2 - 02/07/2023 12:05 PM - Chavdar Ivanov

- Status changed from In Progress to Closed