

WG13 Issues - CIM Issues #4927

ENTSO-E 4 - MAS in SV headerThe MAS indicated in the SV pr

09/14/2021 03:47 PM - Herbert Falk

Status: Closed	
Priority: Low	
Target version:	
Author/Contact Info: ENTSO-E	Standard(s):
Base Release: 61970cim15v28	Version:
Solution to be Applied To: 61970cim16	Clause:
Solution Version: CIM17	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords:	Originally Closed in Version:
Breaking Change: No	Origination Date: 08/17/2011
Breaking Change Description:	Origination ID: 13_85
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor:	
Description ENTSO-E 4 - MAS in SV header The MAS indicated in the SV profile header needs to be clarified when SV file contains merged model. For ENTSO-E IOP the following was agreed - Required if the SV covers only one MAS and empty if SV covers more than one MAS.	
Proposed Solution Discuss further to clarify if we re using merged model and MAS correctly.	
Decision This was clarified in a different direction. All changes are included in 456 and 600. The MAS for SV of a merged model is the MAS of the one that produces the solution.	

History

#1 - 02/07/2023 12:11 PM - Chavdar Ivanov

- Subject changed from ENTSO-E 4 - MAS in SV header
The MAS indicated in the SV pr to ENTSO-E 4 - MAS in SV headerThe MAS indicated in the SV pr
- Status changed from Open to In Progress
- Base Release changed from 61970cim15v28
to 61970cim15v28

#2 - 02/07/2023 12:12 PM - Chavdar Ivanov

- Status changed from In Progress to Closed
- Solution Version set to CIM17
- Decision updated

Taking into account that the issue was resolved in CIM17 I am closing the issue.