

IEC 61850 User Feedback Task Force - Support #500

2.2. BufMod is optional for ReportControl. No default value provided by the schema. SCT is interpreting as unbuffered only.

Com

02/03/2021 02:07 PM - Herbert Falk

Status: Closed	Start date:
Priority: Normal	Due date:
Assignee:	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version:	
ID: 15	To discuss in WG10:
Source: IOP_2015	Short Proposal: Make BufMod mandatory and add upgrading rules coming from Thierry document (Annexe I part 6). The aim is to provide the appropriate value based on the device documentation.
TF Unique ID: 15 # IOP_2015	Standard(s): 6
WG10 Proposal: Need comment on the CDV (57/1697/CDV amendment 1 of edition 2 of part 6). Done	Needs More Information:
Estimated Completion:	Assigned TF:
Discuss in Upcoming Meeting:	

Description 2.2. BufMod is optional for ReportControl. No default value provided by the schema. SCT is interpreting as unbuffered only. Comment (Rome 060616) Changed after reading the original test report. The description regards BufMod, not BufConf.
--

History

#1 - 06/21/2022 09:12 AM - Carlos Rodriguez del Castillo

- Status changed from New to Closed

Confirm to IEC 61850-6 editor that this issue has been accounted for.