

## WG16 Issues - CIM Issues #5778

All end role association names for EnvironmentalLocationType are incorrectly named EnvironmentalLocationKind.

06/23/2022 10:33 AM - Herbert Falk

<b>Status:</b> Closed	
<b>Priority:</b> Normal	
<b>Target version:</b>	
<b>Author/Contact Info:</b> Becky	<b>Standard(s):</b>
<b>Base Release:</b> iec61970cim17v34ec61968cim13v12iec62325cim04v04	<b>Version:</b>
<b>Solution to be Applied To:</b>	<b>Clause:</b> Environmental
<b>Solution Version:</b> iec61970cim17v34ec61968cim13v12iec62325cim04v05	<b>Sub-Clause:</b>
<b>Solution Applied By:</b> BLI	<b>Paragraph:</b>
<b>Completion Date:</b> 07/18/2019	<b>Table:</b>
<b>CIM Keywords:</b>	<b>Originally Closed in Version:</b>
<b>Breaking Change:</b>	<b>Origination Date:</b> 05/28/2019
<b>Breaking Change Description:</b>	<b>Origination ID:</b> 16_0062
<b>CIM Impacted Groups:</b> None	<b>Originally Assigned To:</b>
<b>Requestor:</b>	
<b>Description</b>	
All end role association names for EnvironmentalLocationType are incorrectly named EnvironmentalLocationKind.	
Add new association to EnvironmentalEvent	
<b>Proposed Solution</b>	
Update end role names to match the name of the class	
Add new association to EnvironmentalEvent	
<b>Decision</b>	
Updated end role names and added association	

### History

#### #1 - 08/08/2022 05:27 PM - Becky Iverson

- Status changed from New to Closed
- Base Release changed from iec61970cim17v34ec61968cim13v12iec62325cim04v04 to iec61970cim17v34ec61968cim13v12iec62325cim04v04
- Solution Version changed from iec61970cim17v34ec61968cim13v12iec62325cim04v05 to iec61970cim17v34ec61968cim13v12iec62325cim04v05
- Proposed Solution updated