WG16 Issues - CIM Issues #5822

ConstraintRampType; fix enum FAST

06/23/2022 10:34 AM - Herbert Falk

Status: Closed

Priority: Normal

Target version:

Author/Contact Info: Becky

Base Release: iec61970cim17v34 iec61968cim13v12 i

ec62325cim04v08

Solution to be

Applied To:

Solution Version:

iec61970cim17v34 iec61968cim13v12 i

ec62325cim04v09

Solution Applied By: Becky Iverson

Completion Date:

CIM Keywords:

01/20/2022

Breaking Change:

Breaking Change

Description:

CIM Impacted

Groups:

Requestor:

Standard(s):

Version:

Clause: ConstraintRampType

Sub-Clause:

Paragraph:

Table:

Originally Closed in

Version:

Origination Date: 01/04/2022

Origination ID: 16_0106

Originally Assigned

To:

Description

The attribute "FAST" is not an enumeration literal but instead is defined as an attribute.

Proposed Solution

Correct the type of the attribute to be an enumeration literal

None

Decision

Agree to clean up enumeration

History

#1 - 08/08/2022 05:50 PM - Becky Iverson

- Status changed from New to Closed

04/20/2024 1/1