

IEC 61850 User Feedback Task Force - Support #583

Autoreclosure: Autoreclosure - 3ph closing command missing

02/03/2021 02:07 PM - Herbert Falk

Status:	Closed	Start date:	02/16/2021
Priority:	Normal	Due date:	08/16/2021
Assignee:		% Done:	0%
Category:	Standard extension required	Estimated time:	0.00 hour
Target version:		To discuss in WG10:	No
ID:	55	Short Proposal:	ENTSO-E to submit additional information.
Source:	ENTSO-E	Standard(s):	IEC 61850-7-4
TF Unique ID:	55 # ENTSO-E	Needs More Information:	Yes
WG10 Proposal:		Assigned TF:	
Estimated Completion:			
Discuss in Upcoming Meeting:	No		
Description			
Autoreclosure: Autoreclosure - 3ph closing command missing			

History

#1 - 02/15/2021 11:59 AM - Vladan Cvejic

- Category set to Standard extension required
- Standard(s) set to IEC 61850-7-4
- Discuss in Upcoming Meeting set to No

Checking done.

#2 - 02/16/2021 04:00 AM - Vladan Cvejic

- Due date set to 08/16/2021
- Status changed from New to Triage
- Start date set to 02/16/2021
- Short Proposal set to ENTSO-E to submit additional information.
- To discuss in WG10 set to No

ENTSO-E to submit additional information.

#3 - 12/06/2022 09:38 AM - Vladan Cvejic

- Status changed from Triage to Closed
- Needs More Information set to Yes

Since there is no representation from ENTSO-E anymore we can close these tickets for now. Additionally, we can eventually re-open if in the future similar needs are identified by other users.