

Client - Issues #6172

client check bits must be tested

11/01/2022 08:36 AM - IEC 61850 TPWG

Status:	Resolved	Due date:	12/13/2022
Priority:	Normal		
Assignee:	Thierry Dufaure		
Category:			
Target version:			
Discuss in Upcoming Meeting:	No	Updated Test Document:	
Clause Reference:		Test Case ID:	
61850 Standard:		Closed Reason:	--Not Set--
Triggering Tissue:	1782	Triggering Tissue 2:	
Final Decision:		Triggering Tissue 3:	
Initial Test Document:			
Description			
per resolution of https://redmine.ucaiug.org/issues/5319 client check bits must meet the operational condition of the IED.			
PIXIT ctl5 to be updated			

History

#1 - 11/29/2022 08:23 AM - IEC 61850 TPWG

- Due date changed from 11/15/2022 to 12/13/2022

#2 - 12/01/2022 04:46 AM - Thierry Dufaure

- File Solution to redmine 6172 client check bits must be tested (1dec).docx added

- Triggering Tissue set to 1782

See proposal that verifies that according to tissue resolution "the Clients shall provide a means so that the check conditions are appropriately set."

#3 - 12/13/2022 08:34 AM - Herbert Falk

- Status changed from In Progress to Resolved

Agreed with the proposed test procedure revision.

Files

Solution to redmine 6172 client check bits must be tested (1dec).docx 21.6 KB	12/01/2022	Thierry Dufaure
---	------------	-----------------