

Server - Issues #6213

sSvsN1 - confRev-1 not possible for backwards config

01/12/2023 09:31 AM - Richard Schimmel

Status: Closed	Due date: 02/07/2023
Priority: Normal	
Assignee: Richard Schimmel	
Category:	
Target version:	
Discuss in Upcoming Meeting: No	Updated Test Document: TP1.3
Clause Reference:	Test Case ID:
61850 Standard: 9-2	Closed Reason: --Not Set--
Triggering Tissue:	Triggering Tissue 2:
Final Decision:	Triggering Tissue 3:
Initial Test Document: Server Ed2.1 TP1.2	
Description	
backwards MSVCB's shall have confRev=1 so reducing confRev results in a zero value which is not allowed. Propose to move step 6 to the preferred configuration.	

History

#1 - 01/24/2023 06:40 AM - Richard Schimmel

- File Solution to redmine 6213.docx added
- Status changed from New to In Progress

Added solution

#2 - 01/24/2023 08:59 AM - IEC 61850 TPWG

- Due date set to 02/07/2023
- Status changed from In Progress to Resolved

#3 - 03/01/2024 10:00 AM - Richard Schimmel

- Status changed from Resolved to Closed
- Updated Test Document set to TP1.3

Files

Solution to redmine 6213.docx	21.2 KB	01/24/2023	Richard Schimmel
-------------------------------	---------	------------	------------------