

## WG14 Part 4 Issues - CIM Issues #6582

### May need to add "kind" attribute to OverheadStructure to be consistent with UndergroundStructure.kind

11/07/2023 02:04 PM - Shawn Hu

<b>Status:</b> New	
<b>Priority:</b> Normal	
<b>Target version:</b>	
<b>Author/Contact Info:</b>	<b>Standard(s):</b>
<b>Base Release:</b>	<b>Version:</b>
<b>Solution to be Applied To:</b>	<b>Clause:</b>
<b>Solution Version:</b>	<b>Sub-Clause:</b>
<b>Solution Applied By:</b>	<b>Paragraph:</b>
<b>Completion Date:</b>	<b>Table:</b>
<b>CIM Keywords:</b>	<b>Originally Closed in Version:</b>
<b>Breaking Change:</b>	<b>Origination Date:</b>
<b>Breaking Change Description:</b>	<b>Origination ID:</b>
<b>CIM Impacted Groups:</b> None	<b>Originally Assigned To:</b>
<b>Requestor:</b>	
<b>Description</b>	
[2023-11-06 Jim H.] The "kind" attribute is missing in OverheadStructure class. It is not consistent with UndergroundStructure.kind.	
[2023-11-07 Shawn & Jim]: Reviewed the case. If a "kind" attribute were added, the specialized "Tower" and "Pole" would become inconsistent.	