

CPOW interface with CSWI and XCBR needs to be revise.

07/25/2024 10:10 AM - Thierry Dufaure

Status:	New	Start date:	07/25/2024
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:			
Target version:			
Source:		TF 7-5 Project document:	IEC 61850-7-500
Category:	Not yet categorized	Related TISSUE:	
Description			
During the discussion related to phase discrepancy, we have identified that 7-500 clause 15.2 needs to be revise to explain how the exchanges are. CSWI.Pos vs CPOW.Pos - both controllable. Is it a configuration issue, that CSWI never commands XCBR directly? The Operate(CSWI.Pos) does not indicate with POW, so does the client control CPOW - or never.			