### WG16 Issues - CIM Issues #7075

# InterTieBid attribute minHourlyBlock has a trailing whitespace in the attribute name that should be removed

12/11/2024 03:59 PM - Becky Iverson

Status: Review

Target version:

**Priority:** 

Author/Contact Info:

Normal

Base Release: CIM Grid18v14 Enterprise14v04 Marke

t04v17

Solution to be CIM Grid18v14 Enterprise14v04 Marke

Applied To: t04v18

Solution Version: CIM Grid18v14 Enterprise14v04 Marke

t04v18

Solution Applied By: Becky Iverson

**Completion Date:** 

**Originally Closed in** CIM Keywords:

Version:

Table:

Standard(s):

Sub-Clause:

Paragraph:

Version:

Clause:

**Origination Date: Breaking Change:** 

**Breaking Change Description:** 

**CIM Impacted** 

None

**Groups:** 

Requestor:

**Originally Assigned** 

**Origination ID:** 

To:

Description

Remove the trailing whitespace on the attribute minHourlyBlock in the InterTieBid class.

**Proposed Solution** 

Remove trailing whitespace

**Decision** 

Remove trailing whitespace

**Release Notes** 

Removed trailing whitespace from minHourlyBlock attribute.

#### History

## #1 - 03/06/2025 10:34 AM - Becky Iverson

- Status changed from New to Open
- Proposed Solution updated
- Decision updated

#### #2 - 03/06/2025 10:34 AM - Becky Iverson

- Status changed from Open to In Progress

#### #3 - 03/27/2025 08:57 AM - Becky Iverson

- Status changed from In Progress to Review
- Solution to be Applied To set to CIM\_Grid18v14\_Enterprise14v04\_Market04v18
- Solution Version set to CIM\_Grid18v14\_Enterprise14v04\_Market04v18
- Solution Applied By set to Becky Iverson
- Release Notes updated

04/04/2025 1/1