

# IEC 61850 User Feedback Task Force - Improvement #7092

## Missing DO in LN PSCH

01/08/2025 03:36 AM - Christophe Ghafari

<b>Status:</b> Resolved	<b>Start date:</b> 01/08/2025
<b>Priority:</b> Normal	<b>Due date:</b>
<b>Assignee:</b>	<b>% Done:</b> 0%
<b>Category:</b> Already captured with TISSUE	<b>Estimated time:</b> 0.00 hour
<b>Target version:</b>	
<b>ID:</b>	<b>To discuss in WG10:</b> No
<b>Source:</b>	<b>Short Proposal:</b>
<b>TF Unique ID:</b>	<b>Standard(s):</b> 61850-7-4
<b>WG10 Proposal:</b>	<b>Needs More Information:</b> No
<b>Estimated Completion:</b>	<b>Assigned TF:</b> 61850-7-4
<b>Discuss in Upcoming Meeting:</b> No	
<b>Description</b> Please refer to the TISSUE following: <a href="https://iec61850.tissue-db.com/tissues/1943">https://iec61850.tissue-db.com/tissues/1943</a>	

### History

#### #1 - 01/08/2025 03:41 AM - Christophe Ghafari

- Standard(s) set to 61850-7-4
- Assigned TF None added
- Assigned TF deleted (61850-7-4)

#### #2 - 01/14/2025 08:32 AM - Carlos Rodriguez del Castillo

- Category set to Already captured with TISSUE
- Status changed from New to Resolved
- Discuss in Upcoming Meeting changed from Yes to No
- Assigned TF 61850-7-4 added
- Assigned TF deleted (None)

We recommend closing the tissue [#1943](#) as it is not an InterOp.  
Our recommendation is to modify the description of "DurTmms" to cover all carrier signals.  
We need more information from protection experts(TC95)