

IEC 61850 User Feedback Task Force - Improvement #7093

Attribute type of SmpRate is not sufficient for Travelling Wave application

01/08/2025 03:40 AM - Christophe Ghafari

Status: Resolved	Start date: 01/08/2025
Priority: Normal	Due date:
Assignee:	% Done: 0%
Category: Already captured with TISSUE	Estimated time: 0.00 hour
Target version:	
ID:	To discuss in WG10: No
Source:	Short Proposal:
TF Unique ID:	Standard(s): IEC 61850-7-2 & IEC 61869-9
WG10 Proposal:	Needs More Information: No
Estimated Completion:	Assigned TF: 61850-90-21 (Travelling Wave Fault Location)
Discuss in Upcoming Meeting: No	
Description Please refer to the TISSUE following: https://iec61850.tissue-db.com/tissues/1944	

History

#1 - 01/14/2025 08:41 AM - Carlos Rodriguez del Castillo

- Subject changed from Attribute type of SmpRate is not sufficient for TW application to Attribute type of SmpRate is not sufficient for Travelling Wave application
- Category set to Already captured with TISSUE
- Status changed from New to Resolved
- Discuss in Upcoming Meeting changed from Yes to No

Nothing else we can do in this TF UF, it is already captured in the tissue database for future improvement (Ed3).