

## Server - Issues #7097

### Step number error in expected result of sGos6b in Rev1.3 test procedure

01/13/2025 01:47 AM - ah han

<b>Status:</b> Resolved	<b>Due date:</b>
<b>Priority:</b> Normal	
<b>Assignee:</b> Richard Schimmel	
<b>Category:</b>	
<b>Target version:</b>	
<b>Discuss in Upcoming Meeting:</b> No	<b>Updated Test Document:</b>
<b>Clause Reference:</b>	<b>Test Case ID:</b>
<b>61850 Standard:</b> 7-2	<b>Closed Reason:</b> --Not Set--
<b>Triggering Tissue:</b>	<b>Triggering Tissue 2:</b>
<b>Final Decision:</b>	<b>Triggering Tissue 3:</b>
<b>Initial Test Document:</b>	
<b>Description</b>	
In Rev1.3 test procedure, a new Step 5 was added to the "test description" of sGos6a (increasing the number of steps). However, this change was not considered in "Expected result" of sGos6b.	
The mapping of "Expected result" to "test description" is incorrect. The "Expected result" of sGos6b should start from Step 7.	

#### History

##### #1 - 01/20/2025 08:31 AM - Richard Schimmel

Agree numbering does not match. Expected 6->7, 7->8, 8->9, 10->11, 11->12, 12->13, keep 14.

##### #2 - 01/21/2025 08:08 AM - IEC 61850 TPWG

- Status changed from New to Resolved

- Assignee set to Richard Schimmel

Agreed. Richard to correct numbering.