

Issues

| # | Project | Tracker | ID | Source | Status | Priority | Standard(s) | Subject | Updated |
|------|----------------|---------|----|--------|--------|----------|-------------|--|---------------------|
| 6396 | IEC 61850 TPWG | Issues | | | Closed | Normal | | Review SV test procedures | 09/05/2023 08:36 AM |
| 5957 | Server | Issues | | | Closed | Normal | | sRp16 should not reference TISSUE 1332, it was finalized as N/A | 03/01/2024 09:56 AM |
| 5956 | Server | Issues | | | Closed | Normal | | sBr23 should not reference TISSUES 1467, 1477 which are finalized as N/A | 03/01/2024 09:56 AM |
| 5320 | IEC 61850 TPWG | Feature | | | Closed | Normal | | TISSUE entered requesting SV subscriber testing | 06/14/2022 03:26 PM |