

Issues

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5947	WG13 Issues	CIM Issues			New	Normal	61970-456	Description classes inheriting from IdentifiedObject	08/09/2022 08:40 AM
5946	WG13 Issues	CIM Issues			New	High	61970-456	Association Terminal.TopologicalNode	08/09/2022 08:29 AM
5945	WG13 Issues	CIM Issues			New	High		DCSwitch does not have open flag	08/09/2022 08:20 AM
5944	IEC TC57 WG10 Future Work	WG10FutureWork		RTE	New	Normal	IEC 61850-7-4	Need to create a new LN of group P (Protection), as "PCDP" to represent the Pole Discrepancy Protection.	08/09/2022 08:17 AM
5943	IEC TC57 WG10 Future Work	WG10FutureWork		RTE	New	Normal		New LN of group L (as "LTED") to represent the dynamic topology of the substation.	08/09/2022 08:17 AM
5942	IEC TC57 WG10 Future Work	WG10FutureWork		RTE	New	Normal	IEC 61850-7-4	Activation and deactivation of a function by configuration.	08/09/2022 08:16 AM
5941	IEC TC57 WG10 Future Work	WG10FutureWork		TissueDB	New	Normal	IEC 61850-7-4	IEC61850.Tissue #1755 Event driven schedules – Add DO to stop schedule by event	08/09/2022 08:16 AM
5940	IEC TC57 WG10 Future Work	WG10FutureWork		SCL IOP 2021	New	Normal	IEC 61850-6	Multiple LNodes implemented by same LN	08/09/2022 08:15 AM
5939	IEC TC57 WG10 Future Work	WG10FutureWork		RTE	New	Normal	IEC 61850-6	Mapping of another phases system description to the generic phases phsA, phsB, phsC	08/09/2022 08:14 AM
5938	IEC TC57 WG10 Future Work	WG10FutureWork		RTE	New	Normal	IEC 61850-7-4	LN RADR evolution	08/09/2022 08:14 AM
5937	IEC TC57 WG10 Future Work	WG10FutureWork		WG10	New	Normal	IEC 61850-7-4	Report of current active setting group	08/09/2022 08:13 AM
5936	IEC TC57 WG10 Future Work	WG10FutureWork		TissueDB	New	Normal	IEC 61850-7-4	IEC61850.Tissue #1756 Event driven schedules – Extend description	08/09/2022 08:13 AM
5935	IEC TC57 WG10 Future Work	WG10FutureWork		MH	New	Normal	IEC 61850 7-3 Ed2.1	Extension of CDC ASG	08/09/2022 08:12 AM
5934	IEC TC57 WG10 Future Work	WG10FutureWork		RTE	New	Normal	IEC 61850-7-1	Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation	08/09/2022 08:11 AM
5933	IEC TC57 WG10 Future Work	WG10FutureWork		FNN Germany	New	Normal	IEC 61850-7-4 Ed.3	Proposal of a new LN class ASWI	08/09/2022 08:11 AM
5932	IEC TC57 WG10 Future Work	WG10FutureWork		IEC 62361-102 R2	New	Normal	IEC 61850-6	CIM-61850 Harmonization - Extend list of equipment type codes	08/09/2022 08:08 AM
5931	IEC TC57 WG10 Future Work	WG10FutureWork		IEC 62361-102 R3	New	Normal	IEC 61850-6	CIM-61850 Harmonization - Add string attribute psrType to tPowerSystemResource.	08/09/2022 08:07 AM
5930	IEC TC57 WG10 Future Work	WG10FutureWork		IEC 62361-102 R6	New	Normal	IEC 61850-6	CIM-61850 Harmonization - mRID attribute in SCL for Equipment, Terminals, ConnectivityNodes	08/09/2022 08:06 AM
5929	IEC TC57 WG10 Future Work	WG10FutureWork		IEC 62361-102 R8	New	Normal	IEC 61850-6	CIM-61850 Harmonization - allow Terminals with no connections - use explicit ConnectivityNode.name = None	08/09/2022 08:06 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5928	IEC TC57 WG10 Future Work	WG10FutureWork		IEC 62361-102 R9	New	Normal	IEC 61850-6	CIM-61850 Harmonization - extend tPhaseEnum to match CIM PhaseCode	08/09/2022 08:05 AM
5927	IEC TC57 WG10 Future Work	WG10FutureWork		IEC 62361-102 R15	New	Normal	IEC 61850-7-4	CIM-61850 Harmonization - Add PosFlwIn data object to measurement classes	08/09/2022 08:02 AM
5926	General Testing Issues	Improvement			New	Normal		Review ICT TP	08/09/2022 10:12 AM
5921	General Testing Issues	Improvement			New	Normal		Start using Vendor and Lab Submission Information	08/09/2022 10:20 AM
5904	IEC TC57 WG10 Future Work	WG10FutureWork		WG10	New	Normal	7-4	Introduce alarm and counter DOs in 7-4	07/14/2022 10:27 AM
5897	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM Substation.Station and Substation.SupplyingStation	07/13/2022 02:22 PM
5896	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM conflicting roles RotatingMachine.HydroPump and HydroPump.RotatingMachine	07/13/2022 02:20 PM
5895	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM OperationalLimitSet.RateTemperature	07/13/2022 02:17 PM
5894	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM conflicting roles OperationalLimitType.OperationalLimit and OperationalLimit.OperationalLimitType	07/13/2022 02:15 PM
5893	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM conflicting roles HydroPowerPlant.HydroPumps and HydroPump.HydroPowerPlant	07/13/2022 02:13 PM
5892	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM EquipmentContainer.WeatherStation	07/13/2022 02:10 PM
5891	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM CurrentTransformer.CurrentTransformerPhase	07/13/2022 02:08 PM
5890	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM WirePhaseInfo.WireEarthInfo	07/13/2022 02:05 PM
5889	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM WireInfo.WireInfoType	07/13/2022 02:03 PM
5888	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM OperatingParticipant.Organization	07/13/2022 02:01 PM
5887	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM CatalogAssetType.TypeAssetCatalogue	07/13/2022 01:59 PM
5886	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM missing TransformerTank and TransformerTankEnd	07/13/2022 01:54 PM
5885	CIM Issues	CIM Issues			New	Normal	IEC 61970-301	Consider CIM measurement classes that can hold multiple measured values with the same timestamp and quality.	07/13/2022 10:50 AM
5884	CIM Issues	CIM Issues			New	Normal		Modify control model - create DiscreteCommand for enumerations such as raise/lower	07/13/2022 10:45 AM
5883	CIM Issues	CIM Issues			New	Normal	IEC 61970-301	Define a standard way to define IEC 61850 data object names for MeasurementTypes and ControlTypes	07/13/2022 10:31 AM
5882	CIM Issues	CIM Issues			New	Normal	IEC 61970-301	Model fans, motors, battery systems and similar auxiliary equipment with terminals	07/13/2022 10:24 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5880	WG14 Part 11 Issues	CIM Issues			New	Normal	61968-11	Location should follow Spatial Data best practice	07/06/2022 11:51 AM
5878	IEC TC57 WG10 Future Work	WG10FutureWork			New	Normal		Technical reports to be considered in edition 3 of IEC 61850-7-4	07/12/2022 08:58 AM
5870	WG13 Issues	CIM Issues			New	Normal		BusSegment - Profiles	06/26/2022 10:00 PM
5869	WG13 Issues	CIM Issues			New	Normal		BusSegment - UML updates	06/26/2022 09:59 PM
5868	WG13 Issues	CIM Issues			New	Normal		New BusSegment for busbar modeling	06/26/2022 10:02 PM
5382	WG14 Part 1 Issues	CIM Issues			New	Normal		Work Dispatch	06/13/2022 07:50 PM
5381	WG14 Part 1 Issues	CIM Issues			New	Normal		Interfaces External to CIM	06/13/2022 07:44 PM
5380	WG14 Part 1 Issues	CIM Issues			New	Normal		Customer Installation Management	06/13/2022 07:43 PM
5379	WG14 Part 1 Issues	CIM Issues			New	Normal		Construction Planning revision	06/13/2022 07:40 PM
5378	WG14 Issues	CIM Issues			New	Normal	IEC61968-11, IEC61968-100	Add Part100 Specific Metadata classes to the UML	06/13/2022 12:01 PM
5375	WG13 Issues	CIM Issues			New	Normal		Review removed paragraphs from Part-11 and see where they fit	06/02/2022 03:54 PM
5365	WG14 Part 9 Issues	CIM Issues			New	Low	All WG13 and WG14 stds	Version control in XSDs	06/28/2022 10:59 AM
5357	WG13 Issues	CIM Issues			New	Normal	61970-301, 61970-452	Documentation on ShuntCompensator.grounded and EnergyConsumer.grounded attributes	05/09/2022 11:06 AM
5346	WG14 Part 11 Issues	CIM Issues			New	Normal	61968-11	OrganisationRoles should be able to associate to more than one Organisation	04/21/2022 11:49 AM
5345	WG14 Part 11 Issues	CIM Issues			New	Normal	61968-11	Add attribute nextReadingSchedule to UsagePoint	04/21/2022 11:14 AM
5341	WG13 Issues	CIM Issues			New	Normal	61970-452	CPSM (61970-452) artifacts not published	04/07/2022 09:52 AM
5340	WG13 Issues	CIM Issues			New	Normal	61968-13	CDPSM (61968-13) artifacts not published	04/07/2022 09:50 AM
5339	WG13 Issues	CIM Issues			New	High		Copyright statement to be included in the 301 template	04/06/2022 10:42 AM
5334	WG13 Issues	CIM Issues			New	Normal	301 Ed8	TapChanger model update - 301	03/30/2022 10:56 AM
5318	WG14 Issues	CIM Issues			New	High		Address modeling is too complex	06/21/2022 09:32 AM
5316	CIM Joint Issues	CIM Issues			New	Normal	IEC 61968 series	How to best associate the CIM with other related information standards such as ERP, GML, and BIM	02/15/2022 07:24 AM
5315	WG14 Part 1 Issues	CIM Issues			New	Normal		Rename Customer Site Installation Management to CSIM	02/12/2022 01:08 PM
5314	WG14 Part 4 Issues	CIM Issues			New	Normal		Asset Warranty	02/10/2022 10:47 AM
5313	WG13 Issues	CIM Issues			New	Low		Better description for governorSCD	02/10/2022 01:02 AM
5309	WG13 Issues	CIM Issues			New	High		Support on FACTS device modeling	02/06/2022 09:03 PM
5307	WG13 Issues	CIM Issues			New	Normal		test	01/30/2022 08:11 AM
5306	WG14 Part 1 Issues	CIM Issues			New	Normal		test issue	01/30/2022 08:06 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5305	CIM Joint Issues	CIM Issues			New	Normal		test issue	01/30/2022 08:30 AM
5304	WG13 Issues	CIM Issues			New	Normal	61970-301, 61970-452, 61968-13	Clarify description on TransformerEnd attributes	02/10/2022 09:17 AM
5303	WG13 Issues	CIM Issues			New	Normal	61968-11, 61968-4, 61970-301, 61968-13	5302:5303 61970 portion of TransformerTank to TransformerTankInfo association	01/30/2022 05:32 AM
5302	CIM Joint Issues	CIM Issues			New	Normal	61968-11, 61968-4, 61970-301, 61968-13	Explicit association between TransformerTank and TransformerTankInfo	01/30/2022 05:34 AM
5301	WG14 Issues	CIM Issues			New	Normal	61968-11, 61968-4	5302:5301 61968 portion of TransformerTankInfo to TransformerTank association	01/30/2022 05:09 AM
5300	WG14 Part 4 Issues	CIM Issues			New	Normal	61968-11, 61968-4	5302:5301:5300 Part 4 TransformerTankInfo	01/30/2022 05:27 AM
5299	WG13 Issues	CIM Issues			New	Normal	61970-301, 61968-13	ACLLineSegment updates for mutual coupling	01/30/2022 04:15 AM
5298	WG13 Issues	CIM Issues			New	Normal	61970-301, 61968-13	5295:5298 61970 PhaseImpedanceData cleanup for ACLLineSegment physical modeling	01/30/2022 04:11 AM
5297	WG14 Issues	CIM Issues			New	Normal	61968-11, 61968-4	5295:5297 61968 AssetInfo cleanup for ACLLineSegment physical modeling	01/30/2022 04:12 AM
5296	WG14 Part 4 Issues	CIM Issues			New	Normal	61968-11, 61968-4	5295:5297:5296 - WG14 Part 4 WireAssemblyInfo and related cleanup for ACLLineSegment physical modeling	01/30/2022 04:12 AM
5295	CIM Joint Issues	CIM Issues			New	Normal	61968-11, 61968-4, 61970-301, 61968-13	Joint issue on ACLLineSegment physical modeling clarification	01/30/2022 04:14 AM
5282	WG14 Part 6 Issues	CIM Issues			New	Normal		WorkTask association to MaterialItem	01/13/2022 08:40 AM
5281	WG14 Part 4 Issues	CIM Issues			New	Normal		Asset association to MaterialItem	01/13/2022 08:40 AM
5274	WG14 Part 6 Issues	CIM Issues			New	Low		Review/update enumerations	01/13/2022 08:40 AM
5272	WG14 Part 6 Issues	CIM Issues			New	High		Class for WorkTask cost/related attributes	01/13/2022 08:40 AM
5264	WG14 Part 4 Issues	CIM Issues			New	High		ProcedureStep and revision of Procedure	01/13/2022 08:46 AM
5255	WG14 Part 4 Issues	CIM Issues			New	High		ProcedureStep and revision of Procedure	01/13/2022 08:38 AM
5250	WG14 Issues	CIM Issues			New	High		Document identification	01/13/2022 06:39 AM
5249	WG14 Issues	CIM Issues			New	High		Document activity	01/13/2022 06:39 AM
5248	WG14 Issues	CIM Issues			New	High		Contract work	01/13/2022 06:39 AM
5247	WG14 Issues	CIM Issues			New	High		Refactor Location	01/13/2022 06:39 AM
5246	WG14 Issues	CIM Issues			New	High		Object status	01/13/2022 06:39 AM
5245	WG14 Issues	CIM Issues			New	High		Non standard addresses	01/13/2022 06:39 AM
5244	WG14 Issues	CIM Issues			New	High		Location legal descriptions	01/13/2022 06:39 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5243	CIM Joint Issues	CIM Issues			New	High		Measurement activity	01/13/2022 06:39 AM
5242	WG14 Issues	CIM Issues			New	High		Crew membership tracking	01/13/2022 06:39 AM
5241	WG14 Issues	CIM Issues			New	High		Document type	01/13/2022 06:39 AM
5240	WG14 Issues	CIM Issues			New	High		Multiple TelephoneNumber associations	01/13/2022 06:39 AM
5239	WG14 Issues	CIM Issues			New	High		Multiple ElectronicAddress associations	01/13/2022 06:39 AM
5238	WG14 Issues	CIM Issues			New	High		Multiple Address associations	01/13/2022 06:39 AM
5237	WG14 Issues	CIM Issues			New	High		Eliminate compounds	01/13/2022 06:39 AM
5236	WG14 Issues	CIM Issues			New	High		Refactor TimeSchedule	01/13/2022 06:39 AM
5235	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetKind enumeration list	01/12/2022 02:44 PM
5234	WG14 Part 4 Issues	CIM Issues			New	Normal		Structure can contain multiple Poles	01/12/2022 02:44 PM
5233	WG14 Part 4 Issues	CIM Issues			New	Normal		Move UndergroundStructure classes (e.g. Pole & Tower) to Normative package	01/12/2022 02:44 PM
5232	WG14 Part 4 Issues	CIM Issues			New	Normal		PeriodicStatisticalCalculation Class Description	01/12/2022 02:44 PM
5231	WG14 Part 4 Issues	CIM Issues			New	Normal		Asset Structure Associations	01/12/2022 02:44 PM
5230	WG14 Part 4 Issues	CIM Issues			New	Normal		Maintenance Requirement	01/12/2022 02:44 PM
5229	WG14 Part 4 Issues	CIM Issues			New	Normal		Part-3 AssetConfig profile should be moved to Part-4	01/12/2022 02:44 PM
5228	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - EndDevice	01/12/2022 02:44 PM
5227	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - DER	01/12/2022 02:44 PM
5226	WG14 Part 4 Issues	CIM Issues			New	Normal		Test Model	01/12/2022 02:44 PM
5225	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetDeployment	01/12/2022 02:44 PM
5224	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - Structure	01/12/2022 02:44 PM
5223	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - AuxiliaryEquipment	01/12/2022 02:44 PM
5222	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - Controller	01/12/2022 02:44 PM
5221	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - FACTS Device	01/12/2022 02:44 PM
5220	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - Compensator	01/12/2022 02:44 PM
5219	WG14 Part 4 Issues	CIM Issues			New	Normal		AssetInfo - Rigid Busbar Section	01/12/2022 02:44 PM
5218	WG14 Part 4 Issues	CIM Issues			New	Low		Deprecate AssetOrganisationRole	01/12/2022 02:44 PM
5217	WG14 Part 4 Issues	CIM Issues			New	Normal		Deprecate electronicAddress	01/12/2022 02:44 PM
5216	WG14 Part 4 Issues	CIM Issues			New	Low		Add kindOther to Asset	01/12/2022 02:44 PM
5215	WG14 Part 4 Issues	CIM Issues			New	High		Add ProcedureStep	01/12/2022 02:44 PM
5214	WG14 Part 1 Issues	CIM Issues			New	Normal		Customer Installation Management (CIM) rename	01/12/2022 02:44 PM
5213	WG14 Part 1 Issues	CIM Issues			New	Normal		Customer Account Management (ACT) not following naming convention	01/12/2022 02:44 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5212	WG14 Part 1 Issues	CIM Issues			New	Normal		CompatibleUnit association to Conceptual Design Development	01/12/2022 02:44 PM
5211	WG14 Part 1 Issues	CIM Issues			New	Normal		Missing structural analysis function	01/12/2022 02:44 PM
5210	WG14 Part 1 Issues	CIM Issues			New	Normal		Consider to add Business Actor & Role into the IRM for Ed.4	01/12/2022 02:44 PM
5209	WG14 Part 1 Issues	CIM Issues			New	Normal		Outage Management Business Function	01/12/2022 02:44 PM
5208	WG14 Part 1 Issues	CIM Issues			New	Normal		To link ArchiMate to UML on how to use IRM for Part teams	01/12/2022 02:44 PM
5207	WG14 Part 1 Issues	CIM Issues			New	Normal		Add Business Roles into IRM Model (for Ed.4)	01/12/2022 02:44 PM
5206	WG14 Part 1 Issues	CIM Issues			New	Normal		TC57 WG13 / 14 scope	01/12/2022 02:44 PM
5205	WG14 Part 1 Issues	CIM Issues			New	Normal		Asset Decision Support (ADS)	01/12/2022 02:44 PM
5204	WG14 Part 1 Issues	CIM Issues			New	Normal		Use of IEC Cloud server for IRM model	01/12/2022 02:44 PM
5203	WG14 Part 1 Issues	CIM Issues			New	Normal		IRM team to review SyC work for 61850 actors	01/12/2022 02:44 PM
5202	WG14 Part 1 Issues	CIM Issues			New	Normal		Function decomposition	01/12/2022 02:44 PM
5201	WG14 Part 1 Issues	CIM Issues			New	Normal		Document the process on using IEC 62913 series business / system use cases	01/12/2022 02:44 PM
5200	WG14 Part 1 Issues	CIM Issues			New	Normal		Add an activity diagram example in Appendix A.5	01/12/2022 02:44 PM
5199	WG14 Part 1 Issues	CIM Issues			New	Normal		Need to include functions relevant to Transactive Energy	01/12/2022 02:44 PM
5198	WG14 Part 1 Issues	CIM Issues			New	Normal		Merge EXT business functions to individual Parts	01/12/2022 02:44 PM
5197	WG14 Part 1 Issues	CIM Issues			New	Normal		To align IRM with Archimate 2.x	01/12/2022 02:44 PM
5196	WG14 Part 1 Issues	CIM Issues			New	Normal		A consolidated IRM for WG13, WG14 and WG16	01/12/2022 02:44 PM
5195	WG14 Part 1 Issues	CIM Issues			New	Normal		Typos in Annex A	01/12/2022 02:44 PM
5194	WG14 Part 1 Issues	CIM Issues			New	Normal		Public Outage Data Distribution	01/12/2022 02:44 PM
5193	WG14 Part 1 Issues	CIM Issues			New	Normal		First Responder Outage Data Distribution	01/12/2022 02:44 PM
5192	WG14 Part 1 Issues	CIM Issues			New	Normal		Move message header (including verbs) and other structures into Part-100	01/12/2022 02:44 PM
5191	WG14 Part 1 Issues	CIM Issues			New	Normal		Discussion on the IEC 62913 Ed 1 SGAM to identify any gaps for Part-1 IRM	01/12/2022 02:44 PM
5190	WG14 Part 1 Issues	CIM Issues			New	Normal		IoT functions to be accommodated	01/12/2022 02:44 PM
5189	WG14 Part 1 Issues	CIM Issues			New	Normal		Merge EPRI / SGIP Use Case Actors list into Part-1 IRM	01/12/2022 02:44 PM
5188	WG14 Part 1 Issues	CIM Issues			New	Normal		Key ADMS functionalities:	01/12/2022 02:44 PM
5187	WG14 Part 1 Issues	CIM Issues			New	Normal		IRM sub-function issues from the Part 4 work	01/12/2022 02:44 PM
5186	WG14 Part 1 Issues	CIM Issues			New	Normal		Incomplete IEC 61968 Data Model, Profiles and Messages	01/12/2022 02:44 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5185	WG14 Part 1 Issues	CIM Issues			New	Normal		Use case harmonisation between SGIP and EPRI	01/12/2022 02:44 PM
5184	WG14 Part 1 Issues	CIM Issues			New	Normal		SGIP Function/Services missing in the Part-1 IRM	01/12/2022 02:44 PM
5183	WG14 Part 1 Issues	CIM Issues			New	Normal		Use SGIP actor list and TC8 actor list by reference	01/12/2022 02:43 PM
5182	WG14 Part 1 Issues	CIM Issues			New	Normal		Needs a centralized repository for common profiles of entire WG14	01/12/2022 02:43 PM
5181	WG14 Part 1 Issues	CIM Issues			New	Normal		Customer support (Part-8) on Demand Response	01/12/2022 02:43 PM
5180	WG14 Part 1 Issues	CIM Issues			New	Normal		Business functions on HAN / DER / EV	01/12/2022 02:43 PM
5179	WG14 Part 1 Issues	CIM Issues			New	Normal		To clarify interoperability	01/12/2022 02:43 PM
5178	WG14 Part 1 Issues	CIM Issues			New	Normal		Update Section 3.3 / Table 2	01/12/2022 02:43 PM
5177	WG14 Part 1 Issues	CIM Issues			New	Normal		Update Section 5.6 / Last paragraph	01/12/2022 02:43 PM
5176	WG14 Part 1 Issues	CIM Issues			New	Normal		Update Section A.6 / Table A.2	01/12/2022 02:43 PM
5175	WG14 Part 1 Issues	CIM Issues			New	Normal		Re-organize Figure 1	01/12/2022 02:43 PM
5174	WG14 Part 1 Issues	CIM Issues			New	Normal		Change "61968-1" to "61968" so "...Figure 1 clarifies the scope of IEC 61968 graphically in terms of"	01/12/2022 02:43 PM
5173	WG14 Part 1 Issues	CIM Issues			New	Normal		Consider to specify "automated geographical mapping"	01/12/2022 02:43 PM
5172	WG14 Part 1 Issues	CIM Issues			New	Normal		Are profiles related to grammar/syntax or only to an abstract definition of CIM subset ?	01/12/2022 02:43 PM
5171	WG14 Part 1 Issues	CIM Issues			New	Normal		61968 RDF statement	01/12/2022 02:43 PM
5170	WG14 Part 1 Issues	CIM Issues			New	Normal		Comments on Web Services (WS)	01/12/2022 02:43 PM
5169	WG14 Part 1 Issues	CIM Issues			New	Normal		Describe the meaning of "DAC" "VRU"	01/12/2022 02:43 PM
5168	WG14 Part 1 Issues	CIM Issues			New	Normal		Modify "enables a non-compliant software application to use the services."	01/12/2022 02:43 PM
5167	WG14 Part 1 Issues	CIM Issues			New	Normal		Typo	01/12/2022 02:43 PM
5166	WG14 Part 1 Issues	CIM Issues			New	Normal		Should the section refer to IEC/PAS 62559 ?	01/12/2022 02:43 PM
5165	WG14 Part 1 Issues	CIM Issues			New	Normal		Message type comment	01/12/2022 02:43 PM
5164	WG14 Part 1 Issues	CIM Issues			New	Normal		Recommendation / direction on foreign language support	01/12/2022 02:43 PM
5163	WG14 Part 1 Issues	CIM Issues			New	Normal		Mobile Workforce Management	01/12/2022 02:43 PM
5162	WG14 Part 1 Issues	CIM Issues			New	Normal		Missing actor AM-MAM in Part-1	01/12/2022 02:43 PM
5161	WG14 Part 1 Issues	CIM Issues			New	Normal		Refer to methodology document	01/12/2022 02:43 PM
5160	WG14 Issues	CIM Issues			New	Normal		Location Model Update	01/12/2022 02:18 PM
5159	WG14 Issues	CIM Issues			New	Normal		Address Model Update	01/12/2022 02:18 PM
5158	WG14 Issues	CIM Issues			New	Normal		Person Model Update	01/12/2022 02:18 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5157	WG14 Issues	CIM Issues			New	Normal		Organisation Model Update	01/12/2022 02:18 PM
5121	IEC TC57 WG10 Future Work	WG10FutureWork			New	Normal	61850-7-2	sFt2ab does not verify that the LastModified value is consistent or changes when file is modified	11/16/2021 09:03 AM
5113	WG13 Issues	CIM Issues			New	Normal		NonlinearShuntCompensator has ambiguity in definition of per section or total	01/27/2022 01:01 PM
5108	WG13 Issues	CIM Issues			New	Normal	61970-301	PowerTransformerEnd	01/09/2022 09:02 PM
5101	IEC TC57 WG10 Future Work	WG10FutureWork			New	Normal		test	10/07/2021 11:40 AM
5098	WG13 Issues	CIM Issues			New	High	71970-301, 61970-452, 61970-600	CsConverter targtAlpha and targetGamma	10/03/2021 03:33 PM
5097	WG13 Issues	CIM Issues			New	Normal	61970-301, 61970-452	Allow OperationalLimitSet to be described by a Season by adding a new association between OperationalLimitSet and Season	10/01/2021 11:24 AM
5093	WG13 Issues	CIM Issues			New	Normal		Clarify ambiguity on using Terminal phases for unbalanced loads.	09/22/2021 09:08 AM
5076	WG13 Issues	CIM Issues			New	High	61970-301, 61970-452, 61970-456	Convention and usage of operational limits of GeneratingUnit and injections	12/01/2021 11:39 AM
5068	WG13 Issues	CIM Issues			New	Normal	61970-301	Energy allocation to devices	01/26/2022 11:05 AM
5049	WG13 Issues	CIM Issues			New	Normal		Inconsistent naming for p,q,r,x and others	05/09/2022 10:39 AM
5010	WG13 Issues	CIM Issues			New	Normal		Support exchange of limit values in SSH profile - Need to e	09/14/2021 03:47 PM
4948	WG13 Issues	CIM Issues			New	Normal		PowerTransformerEnd.ratedU and TapChanger.neutralU Confusio	09/14/2021 03:47 PM
4947	WG13 Issues	CIM Issues			New	Normal		Model Meta Data cleanup and plan Need a plan and clean up o	09/14/2021 03:47 PM
3110	CIM Joint Issues	CIM Issues			New	Normal		test	09/07/2021 04:06 PM
757	WG14 Issues	CIM Issues			New	Normal		test	08/11/2021 11:29 AM
749	CIM Joint Issues	CIM Issues			New	Normal		There are a variety of issues with RegulatingControl. These include the following and must be addressed in CIM18	07/06/2021 10:25 AM
5917	Server	Issues			In Progress	Urgent		'Expected result' for some test cases of CB9b: GOOSE subscribe	08/09/2022 10:21 AM
5914	Server	Issues			In Progress	Normal		Verify that LPHD.Sim is not affected by LLN0.Beh	08/09/2022 08:59 AM
5912	Server	Issues			In Progress	Normal		sSrv6 checking the read-only part is always applicable	08/09/2022 08:47 AM
5910	Server	Issues			In Progress	Normal		Need to test that IEDs support 1 Step and 2 Step clocks: IOP 2022	08/09/2022 08:30 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5905	Server	Issues			In Progress	Normal		sSrvN4 is mandatory, used SetDataValues service is optional in PICS and may not be not supported	08/09/2022 08:20 AM
5871	WG14 Part 11 Issues	CIM Issues			In Progress	Low	61968-11	Association end role name is spelled incorrectly	06/28/2022 12:26 PM
5347	Server	Issues			In Progress	Normal		How should time correlated GOOSE change status in GOOSE Performance test	08/09/2022 08:41 AM
5336	IEC 61850 User Feedback Task Force	Feature	4	TF 61850-80-6	In Progress	Normal	IEC 61850-7-2; IEC 61850-8-1, 80-6	Extension of the AddCause required to reflect communication issues in multi level control	04/26/2022 09:20 AM
5319	Server	Issues			In Progress	Normal		T1782 sCtl7 addcause "inconsistent-parameters" when check=00 not-supported	08/09/2022 08:43 AM
5124	IEC 61850 User Feedback Task Force	Feature	3	TF 61850-80-6	In Progress	Normal	IEC 61850-80-6	Telemonitoring blocking	12/21/2021 09:26 AM
5091	IEC 61850 User Feedback Task Force	Feature	10	H30	In Progress	Normal	IEC 61850-2	Devices types/acronyms	02/09/2022 10:30 AM
3098	IEC 61850 User Feedback Task Force	Improvement	1	WG17	In Progress	Normal		Need to Change 8-1 to allow multiple DOs to be written	03/29/2022 09:36 AM
677	IEC 61850 User Feedback Task Force	Feature	50	RTE	In Progress	Normal	IEC 61850-7-4	Impact of IEC 61869-13 (SAMU)	06/21/2022 02:04 AM
660	IEC 61850 User Feedback Task Force	Support	1	WG10	In Progress	Normal		IED model documentation	06/16/2021 09:32 AM
657	Server	Issues			In Progress	Low		Publish/subscribe enum with negative value	08/09/2022 08:38 AM
656	Server	Issues			In Progress	Low		Publish/subscribe enum with value > 127	08/10/2022 11:16 AM
654	Server	Issues			In Progress	Low		Publish/subscribe minimum length data GOOSE	08/09/2022 08:35 AM
653	Server	Issues			In Progress	Low		Subscriber can use maximum number of dataset elements	08/09/2022 08:34 AM
652	Server	Issues			In Progress	Normal		Publisher can use maximum number of dataset elements	08/09/2022 08:34 AM
651	Server	Issues			In Progress	Low		Verify subscriber can accept maximum size GOOSE	08/09/2022 08:32 AM
633	IEC 61850 User Feedback Task Force	Improvement	1	ZIV	In Progress	Normal	IEC 61850-7-2	Initial values of paramRev and valRev	04/13/2021 09:50 AM
632	IEC 61850 User Feedback Task Force	Support	8	H30	In Progress	High	IEC 61850-9-2, IEC 61869-9	APPID 0x4000 - Sampled Values	06/16/2021 09:42 AM
626	IEC 61850 User Feedback Task Force	Improvement	23	RTE	In Progress	Normal	IEC 61850-6	Extension of P-type to describe connexion type (PhysCon)	03/02/2021 09:51 AM
623	IEC 61850 User Feedback Task Force	Feature	19	RTE	In Progress	Normal		New LN of group L (as "LPLE") representing a group of LED	03/02/2021 09:42 AM
621	IEC 61850 User Feedback Task Force	Feature	17	RTE	In Progress	Normal	IEC 61850-7-4/7-500	New controllable DO in RREC to define the mode of the recloser of the circuit breaker	05/11/2021 10:08 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
611	IEC 61850 User Feedback Task Force	Bug	5	RTE	In Progress	Normal	IEC 61850-7-4 / IEC 61850-80-6	Need a new DO (ENUM) to identify the protocol used for the SCADA exchange, in LN ITCI	05/11/2021 09:59 AM
608	IEC 61850 User Feedback Task Force	Feature	7	H30	In Progress	Normal	IEC 61850-90-xx	Comprehensive set of requirements covering validation and supervision of all IEC 61850 communications	06/21/2022 02:09 AM
607	IEC 61850 User Feedback Task Force	Support	6	H30	In Progress	Normal	IEC 61850-80-6 (90-2)	LPHD.Sim management	06/21/2022 02:09 AM
605	IEC 61850 User Feedback Task Force	Improvement	4	H30	In Progress	Normal	IEC 61850-10-3	Test and Simulation mode questions	06/21/2022 02:09 AM
590	IEC 61850 User Feedback Task Force	Feature	1800	IOP_2019	In Progress	Normal	IEC 61850-6	ICT fails to check validity of the SCD file regarding the IED constraints	07/05/2022 08:30 AM
578	IEC 61850 User Feedback Task Force	Feature	50	ENTSO-E	In Progress	Normal	IEC 61850-7-4	Busbar protection: End Fault protection - model definition required.	02/11/2021 07:10 AM
576	IEC 61850 User Feedback Task Force	Feature	48	ENTSO-E	In Progress	Normal	IEC 61850-7-4	Distance protection: Distance protection - 1 phase and 3 phase zone extension signals are missing	02/11/2021 07:11 AM
575	IEC 61850 User Feedback Task Force	Feature	47	ENTSO-E	In Progress	Normal	IEC 61850-7-4	Protection scheme: Reversal current logic LN/DO/DA missing	02/11/2021 07:13 AM
574	IEC 61850 User Feedback Task Force	Feature	46	ENTSO-E	In Progress	Normal	IEC 61850-7-4	Protection scheme: Weak end infeed (1 phase and 2/3 phase operate missing)	02/11/2021 07:13 AM
573	IEC 61850 User Feedback Task Force	Feature	45	ENTSO-E	In Progress	Normal	IEC 61850-7-4	Tap Changer Supervision: Tap discrepancy (3 pole transformer case)	02/11/2021 07:14 AM
556	IEC 61850 User Feedback Task Force	Support	3	H30	In Progress	Normal	IEC 61850-90-20	Rendundant CT/TT measurements	06/21/2022 02:09 AM
439	IEC 61850 User Feedback Task Force	Bug	2	Vattenfall	In Progress	High	IEC 61850-6	How to add utility process name to DOs	02/11/2021 06:37 AM
438	IEC 61850 User Feedback Task Force	Feature	1	Vattenfall	In Progress	Normal	IEC 61850-6 (-100)	The engineering-process is well defined for a green field / new IEC 61850 substation but needs clarification for refurbishment	02/11/2021 07:59 AM
434	IEC 61850 User Feedback Task Force	Support	25	ENTSO-E	In Progress	Normal		Freedom of choice what IEC 61850 services are to be tested seem too open. The vendor can select exactly what UCA accredited test	04/02/2021 01:30 PM
424	IEC 61850 User Feedback Task Force	Support	15	ENTSO-E	In Progress	Normal	6	Vendor Tools shall allow (vendor independant) Integration tools doing engineering based on ICD Files, thus allowing them to in	02/03/2021 02:49 PM
419	IEC 61850 User Feedback Task Force	Support	10.2	ENTSO-E	In Progress	Normal	IEC 61850-7-2	Also many other features of GOOSE messaging are left to the manufacturer to choose.	06/14/2022 09:33 AM
417	IEC 61850 User Feedback Task Force	Support	9	ENTSO-E	In Progress	Normal	6-100	There is no mechanism proposed by the Standard to positively identify data points in the data model. For instance PTOC can refer	02/03/2021 02:49 PM
409	IEC 61850 User Feedback Task Force	Feature	4.1	ENTSO-E	In Progress	Normal		Too loose or non existing guideline for organization of structure tree (construction of each LD, LN etc)	02/11/2021 08:00 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5913	Server	Issues			Resolved	Normal		sSrvN1e and sSrvN3 change condition SCL FC=CF/DC/SP with valKind=Set	08/09/2022 08:48 AM
5907	Server	Issues			Resolved	Normal		sCtl26 - Cancel a direct control object	08/09/2022 08:24 AM
5876	IEC 61850 User Feedback Task Force	Improvement		FNN Germany	Resolved	Normal	IEC 61850-7-4 Ed.3	Proposal of a new LN class ASWI	08/02/2022 08:56 AM
5372	IEC 61850 User Feedback Task Force	Improvement		RTE	Resolved	Normal	IEC 61850-7-1	Simultaneous change of InRef.setSrcRef and InRef.setSrcCB for dynamic commutation	06/07/2022 09:23 AM
5371	Server	Issues			Resolved	Normal		Scope of the test is limited to a given NSD release.	06/29/2022 02:11 AM
5362	Server	Issues			Resolved	Normal		sGop2 and sGop4 check minimum MinTime and minimum MaxTime	08/09/2022 08:45 AM
5356	Server	Issues			Resolved	Normal		PIXIT entries mandated by 61850-8-1 but missing in PIXIT	06/02/2022 03:02 PM
5343	Server	Issues			Resolved	Normal		sGosN2 remove PIXIT Gs5	06/02/2022 03:05 PM
5337	Server	Issues			Resolved	Normal		Independence of GOOSE subscriber timeouts is not tested	06/02/2022 03:06 PM
5335	IEC 61850 User Feedback Task Force	Improvement		Dustin Tessier	Resolved	Normal	IEC 61850-90-4	Adding Normative Requirements & Conformance Testing Pertaining to Broadcast Storms	06/14/2022 09:22 AM
5331	IEC 61850 User Feedback Task Force	Feature		SCL IOP 2021	Resolved	Normal	IEC 61850-6	Multiple LN nodes implemented by same LN	03/29/2022 09:14 AM
5330	IEC 61850 User Feedback Task Force	Improvement		SCL IOP 2021	Resolved	Normal	IEC 61850-6, 6-100	LN node iedName attribute usage needs to be clarified	03/29/2022 09:00 AM
5329	IEC 61850 User Feedback Task Force	Improvement		SCL IOP 2021	Resolved	Normal	IEC 61850-6	Clarify iedType attribute usage in DataTypeTemplates	04/12/2022 09:20 AM
5328	Server	Issues			Resolved	Normal		sFt2ab issues with "directory" files	06/02/2022 03:07 PM
5327	Client	Issues			Resolved	Normal		PIXIT - add processing/mapping of quality bits	06/28/2022 09:44 AM
5326	Server	Issues			Resolved	Normal		sSBOes8 incorrectly requires addCause=blocked-by-mode	06/14/2022 08:34 AM
5323	IEC 61850 User Feedback Task Force	Improvement	3	WG17	Resolved	Normal	IEC 61850-7-4,7-5	Schedules - allow updates to single values while schedules are running	05/10/2022 09:18 AM
5322	IEC 61850 User Feedback Task Force	Improvement	2	WG17	Resolved	Normal	IEC 61850-7-4,7-5	Schedules - add optional data objects to support irregular interval schedules	04/12/2022 09:12 AM
5321	IEC 61850 User Feedback Task Force	Improvement	1	WG17	Resolved	Normal	IEC 61850-7-4,7-5	Schedules - allow 3 values per time point	06/20/2022 03:49 AM
5123	IEC 61850 User Feedback Task Force	Feature	2	TF 61850-80-6	Resolved	Normal	IEC 61850-90-28	ACSI service for link supervision on application level	06/21/2022 08:35 AM
5122	IEC 61850 User Feedback Task Force	Feature	1	TF 61850-80-6	Resolved	Normal	IEC 61850-90-28	New LN in LN group L to reflect the status of TPAA between Proxy/Gateway and IED	02/09/2022 07:06 AM
5120	SCL Tooling	Issues			Resolved	Normal		LGOS/LSVS reference with functional naming (SCL)	08/09/2022 08:40 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5089	IEC 61850 User Feedback Task Force	Improvement	13	MH	Resolved	Normal	IEC 61850 7-3 Ed2.1	Extension of CDC ASG	05/10/2022 09:26 AM
5088	IEC 61850 User Feedback Task Force	Feature	12	MH	Resolved	Normal	IEC 61850-7-4 Ed2.1 ,7-5	Clarifications on the local/remote concept 8/8	02/14/2022 03:56 AM
5087	IEC 61850 User Feedback Task Force	Feature	11	MH	Resolved	Normal	IEC 61850-7-4 Ed2.1 ,7-5	Clarifications on the local/remote concept 7/8	02/14/2022 03:55 AM
5086	IEC 61850 User Feedback Task Force	Feature	10	MH	Resolved	Normal	IEC 61850-7-4 Ed2.1 ,7-5	Clarifications on the local/remote concept 6/8	02/14/2022 03:56 AM
5085	IEC 61850 User Feedback Task Force	Feature	9	MH	Resolved	Normal	IEC 61850 7-1 / 7-4 Ed2.1,7-5	Clarifications on the local/remote concept 5/8	02/14/2022 03:57 AM
5084	IEC 61850 User Feedback Task Force	Feature	8	MH	Resolved	Normal	IEC 61850-7-1 Ed2.1,7-5	Clarifications on the local/remote concept 4/8	02/14/2022 03:57 AM
5083	IEC 61850 User Feedback Task Force	Feature	7	MH	Resolved	Normal	IEC 61850-7-1 Ed2.1,7-5	Clarifications on the local/remote concept 3/8	02/14/2022 03:57 AM
5082	IEC 61850 User Feedback Task Force	Feature	6	MH	Resolved	Normal	IEC 61850-7-4,7-5	Clarifications on the local/remote concept 2/8	02/14/2022 03:57 AM
5081	IEC 61850 User Feedback Task Force	Feature	5	MH	Resolved	Normal	IEC 61850-7-1 Ed2.1/7-4 Ed2.1 Annex B/7-500	Clarifications on the local/remote concept 1/8	02/14/2022 02:50 AM
5080	IEC 61850 User Feedback Task Force	Feature	4	MH	Resolved	Normal	IEC 61850-7-1 Ed2.1 ,7-500	Clarification on the ctlModel 3/3	02/14/2022 04:00 AM
5079	IEC 61850 User Feedback Task Force	Feature	3	MH	Resolved	Normal	IEC 61850-7-1 Ed2.1, 7-500	Clarification on the ctlModel 2/3	02/14/2022 03:59 AM
5078	IEC 61850 User Feedback Task Force	Feature	2	MH	Resolved	Normal	IEC 61850-7-1 / 7-2 Ed2.1 / 7-5/7-500	Clarification on the ctlModel 1/3	02/09/2022 07:11 AM
5077	IEC 61850 User Feedback Task Force	Feature	1	MH	Resolved	Normal	IEC61850 7-1	Location of SGCB in LD structures	02/09/2022 10:06 AM
3115	Client	Issues			Resolved	Normal		Forward compatibility to Amd1 server with pre-assigned URUCB/BRCB	06/14/2022 08:35 AM
3102	IEC TC57 WG10 Future Work	WG10FutureWork		TissueDB	Resolved	Normal	IEC 61850-7-4	https://iec61850.tissue-db.com/tissue/1744 Clarification of Start Times in StrTm.setCal	11/23/2021 08:46 AM
3101	IEC 61850 User Feedback Task Force	Bug	3	TissueDB	Resolved	Normal	IEC 61850-7-4	IEC61850.Tissue #1755 Event driven schedules – Add DO to stop schedule by event	11/23/2021 08:34 AM
3100	IEC 61850 User Feedback Task Force	Improvement	2	TissueDB	Resolved	Normal	IEC 61850-7-4	IEC61850.Tissue #1754 Event driven schedules - Type of InSyn missing	11/23/2021 08:33 AM
3099	IEC 61850 User Feedback Task Force	Improvement	1	TissueDB	Resolved	Normal	IEC 61850-7-4	IEC61850.Tissue #1756 Event driven schedules – Extend description	11/23/2021 08:32 AM
748	Server	Issues			Resolved	Normal		sGos9 use SPS when INS subscribe is not supported	07/27/2021 10:07 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
676	IEC 61850 User Feedback Task Force	Support	49	RTE	Resolved	Normal	IEC 61850-7-5	Clarification of addCause	06/14/2022 10:44 AM
675	IEC 61850 User Feedback Task Force	Support	48	RTE	Resolved	Normal	IEC 61850-7-4 Ed2.1	Clarification of blocked mode	09/29/2021 03:50 AM
673	IEC 61850 User Feedback Task Force	Improvement	47	RTE	Resolved	Normal		CPU monitoring	09/29/2021 03:50 AM
672	IEC 61850 User Feedback Task Force	Improvement	46	RTE	Resolved	Normal	IEC 61850-90-4	Create DO indicating the source of synchronisation	06/16/2022 03:51 PM
667	IEC 61850 User Feedback Task Force	Improvement	4	WG10	Resolved	Normal	IEC 61850-7-4	Report of current active setting group	06/30/2021 06:56 AM
658	Client	Issues			Resolved	Normal		Verify Client does process a report before RptEna write respond+	06/01/2021 08:23 AM
647	IEC 61850 User Feedback Task Force	Support	57	ENTSO-E	Resolved	Normal	IEC 61850-7-5, IEC61850-7-500	Single phase and multi phase trip indication for the autorecloser	04/13/2021 09:42 AM
636	Client	Issues			Resolved	High		Mandate RCB reservation for Ed2.0 client and Amd1 server	04/20/2021 02:23 PM
630	IEC 61850 User Feedback Task Force	Improvement	43	RTE	Resolved	Normal	IEC 61850-7-5/7-500	XCBR LN new DO to describe withdrawable circuit breaker	02/09/2022 08:05 AM
629	IEC 61850 User Feedback Task Force	Improvement	35	RTE	Resolved	Normal	IEC TR 61850-90-29	TCTR and TVTR new DO to identify physical terminal allocation in the IED	07/05/2022 08:15 AM
627	IEC 61850 User Feedback Task Force	Feature	29	RTE	Resolved	Normal	IEC 61850-7-4	Activation and deactivation of a function by configuration.	03/02/2021 09:53 AM
625	IEC 61850 User Feedback Task Force	Improvement	22	RTE	Resolved	Normal	IEC 61850-7-4	LN RADR evolution	03/02/2021 09:49 AM
619	IEC 61850 User Feedback Task Force	Feature	15	RTE	Resolved	Normal		New LN of group L (as "LTED") to represent the dynamic topology of the substation.	03/02/2021 09:29 AM
612	IEC 61850 User Feedback Task Force	Feature	11	RTE	Resolved	Normal	IEC 61850-7-4	Need to create a new LN of group P (Protection), as "PCDP" to represent the Pole Discrepancy Protection.	07/05/2022 08:17 AM
610	IEC 61850 User Feedback Task Force	Improvement	2	RTE	Resolved	Normal	IEC 61850-6	Mapping of another phases system description to the generic phases phsA, phsB, phsC	05/11/2021 10:13 AM
602	IEC 61850 User Feedback Task Force	Feature	1742	IOP_2019	Resolved	Normal	IEC 61850-9-3	Merging Unit standard requires MU clock to jump on PTP time jumps, which is not true for Boundary Clocks.	07/05/2022 08:52 AM
599	IEC 61850 User Feedback Task Force	Feature	12	IOP_2019	Resolved	Normal		ICD files do not match requirements (several issues) - increase in engineering efforts	07/05/2022 08:48 AM
597	IEC 61850 User Feedback Task Force	Feature	1120	IOP_2019	Resolved	Normal	TF Communication supervision	SCTs updating the confRev of 9-2 LE Sampled Value streams - problem with subscription to test tool SV injection	07/05/2022 08:46 AM
584	IEC 61850 User Feedback Task Force	Feature	1122	IOP_2019	Resolved	Normal	IEC 61850-6	SCL validation - Should all name parts of PhV be contained in the doName?	07/05/2022 08:20 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
580	IEC 61850 User Feedback Task Force	Support	52	ENTSO-E	Resolved	Normal	IEC 61850-7-4, 7-5	Voltage protection: Undervoltage protection - 3ph operate	03/01/2022 09:09 AM
579	IEC 61850 User Feedback Task Force	Support	51	ENTSO-E	Resolved	Normal	IEC 61850-7-4, 7-500	Voltage protection: Overvoltage protection - 3ph operate	03/01/2022 09:09 AM
572	IEC 61850 User Feedback Task Force	Support	44	ENTSO-E	Resolved	Normal	IEC 61850-7-4, 7-500	S/S related applications: Auxiliary circuit supervision	03/01/2022 08:37 AM
554	IEC 61850 User Feedback Task Force	Support	1	H30	Resolved	Normal		Performance requirement for SV and implications to Protection applications	12/21/2021 08:56 AM
553	IEC 61850 User Feedback Task Force	Support	34	IOP_2017/55	Resolved	Normal	IEC 61850-9-3	IEC/IEEE 61850-9-3 should clarify the meaning and use of TimeTraceable and FrequencyTraceable	06/21/2022 09:26 AM
552	IEC 61850 User Feedback Task Force	Support	33	IOP_2017/54	Resolved	Normal	IEC 61850-9-3	Disruption of network when TC are not set to the correct domain	06/21/2022 09:26 AM
551	IEC 61850 User Feedback Task Force	Support	32	IOP_2017/53	Resolved	Normal	IEC 61850-9-3	IEC/IEEE 61850-9-3 - Sync messages have to be padded to the same length as the Pdelay_Req/Pdelay_Resp messages	06/21/2022 09:26 AM
550	IEC 61850 User Feedback Task Force	Support	31	IOP_2017/52	Resolved	Normal	IEC 61850-9-3	Incorrect variance adjustment for Time Masters with degradation (loss of GPS)	06/21/2022 09:26 AM
549	IEC 61850 User Feedback Task Force	Support	30	IOP_2017/51	Resolved	Normal	IEC 61850-9-3	Standard should clarify the relation between the PTP clock clockQuality signals and the timeQuality in TimeStamp	06/21/2022 09:26 AM
548	IEC 61850 User Feedback Task Force	Support	29	IOP_2017/50	Resolved	Normal	IEC 61850-9-3	The start-up behaviour of Boundary Clocks	06/21/2022 09:26 AM
547	IEC 61850 User Feedback Task Force	Support	28	IOP_2017/49	Resolved	Normal	IEC 61850-9-3	Requirement for Boundary Clocks to adjust the clock accuracy to reflect their actual accuracy, not that of their grandmaster	06/21/2022 09:26 AM
525	IEC 61850 User Feedback Task Force	Support	6	IOP_2017/8	Resolved	Normal	IEC 61850-6	IEC 61850-6 does not allow the authentication configuration (none, password, weak, strong or certificate) to be used for Client	06/21/2022 09:17 AM
519	IEC 61850 User Feedback Task Force	Support	1	UFTF	Resolved	Normal	90-16	Optionality in DOI NamPlt, PhyNam resp. in ICD/IID file: IED.manufacturer, .IED.type, makes a device recognition in a machine to	06/21/2022 09:20 AM
442	IEC 61850 User Feedback Task Force	Bug	5	Vattenfall	Resolved	High	IEC 61850-6-100	Mapping LNode (substation section) to LN (IED section)	03/15/2022 09:10 AM
441	IEC 61850 User Feedback Task Force	Improvement	4	Vattenfall	Resolved	High	IEC 61850-6-100	Limitations of one to one mapping between LNode and LN	03/15/2022 11:08 AM
5906	Server	Issues			Rejected	Normal		sCnf51 at least one LPHD	08/11/2022 01:55 AM
5344	Server	Issues			Rejected	Normal		sBr29 power-up the IED is missing	06/02/2022 04:12 PM
5138	Server	Issues			Rejected	Normal		sBr13 without pre-assignment	12/13/2021 04:43 AM
3027	IEC 61850 Certificate	IEC 61850 Certificate			Rejected	Normal		F650 Digital Bay Controller [GE Power Management, S.L.]	08/04/2021 09:37 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5310	IEC TC57 WG10 Future Work	WG10FutureWork		WG 18	Accepted	Normal	IEC 61850-7-3	New CDC for IEC/TC 57/WG 18	02/07/2022 03:54 AM
5105	IEC TC57 WG10 Future Work	WG10FutureWork		WG 10	Accepted	Normal		Outcome of WG 10 Workshop "Future of IEC 61850"	10/08/2021 12:41 PM
5104	IEC TC57 WG10 Future Work	WG10FutureWork		WG 17	Accepted	Normal	IEC 61850-6	Add a type code 'INV'	10/12/2021 08:59 AM
5103	IEC TC57 WG10 Future Work	WG10FutureWork		IEEE H27	Accepted	Normal	IEC 61850-7-2	Modified/new CDC for IEEE H27	10/08/2021 02:27 AM
5374	IEC 61850 User Feedback Task Force	Feature		RTE	Triage	Normal	IEC 61850-7-4	Creation of a new LN for protection function	07/19/2022 02:46 AM
631	IEC 61850 User Feedback Task Force	Feature	44	RTE	Triage	Normal		Evolution of LN PSCH to build switching on information	08/17/2021 08:03 AM
624	IEC 61850 User Feedback Task Force	Support	21	RTE	Triage	Normal	IEC 61850-6	Clarification of using of ValKind, VallImport.	03/02/2021 09:44 AM
622	IEC 61850 User Feedback Task Force	Feature	18	RTE	Triage	Normal	IEC 61850-7-4	Parameters not available in standardized LN	06/20/2022 03:56 AM
620	IEC 61850 User Feedback Task Force	Feature	16	RTE	Triage	Normal		New LN LPDO / LPDI in IEC 61850-7-5	06/20/2022 03:55 AM
618	IEC 61850 User Feedback Task Force	Improvement	14	RTE	Triage	Normal	IEC 61850-90-3	Evolution of DO SumSqA of LN SPTRExt	06/20/2022 03:54 AM
583	IEC 61850 User Feedback Task Force	Support	55	ENTSO-E	Triage	Normal	IEC 61850-7-4	Autoreclosure: Autoreclosure - 3ph closing command missing	02/16/2021 04:00 AM
582	IEC 61850 User Feedback Task Force	Support	54	ENTSO-E	Triage	Normal	IEC 61850-7-4, 7-5	Synchrocheck: Synchrocheck - missing signals	02/16/2021 04:11 AM
581	IEC 61850 User Feedback Task Force	Support	53	ENTSO-E	Triage	Normal	IEC 61850-7-4, 7-5	S/S related applications: Disturbance recorder - communication session active	02/16/2021 04:11 AM
569	IEC 61850 User Feedback Task Force	Support	41	ENTSO-E	Triage	Normal	IEC 61850-7-4	S/S related applications: Access security system	02/16/2021 04:13 AM
566	IEC 61850 User Feedback Task Force	Support	38	ENTSO-E	Triage	Normal	IEC 61850-7-420	S/S related applications: Diesel aggregat alarm	02/16/2021 04:08 AM
559	IEC 61850 User Feedback Task Force	Support	31	ENTSO-E	Triage	Normal	IEC 61850-7-4	Busbar protection: ARC detection protection	02/16/2021 04:09 AM
558	IEC 61850 User Feedback Task Force	Support	30	ENTSO-E	Triage	Normal	IEC 61850-7-4	Busbar protection (BBP): Diff/Kirchoff BBP	02/16/2021 04:10 AM
555	IEC 61850 User Feedback Task Force	Support	2	H30	Triage	Normal		Link Failover reliability problem - implication to protection application	02/09/2022 09:13 AM
5920	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Kalki SYNC 3000 Edition 2 Client	08/05/2022 10:52 AM
5919	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DS Agile aView Edition 2 Client	08/05/2022 10:39 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5918	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MiCOMP40AgileP44T Edition 2 Server	08/04/2022 06:56 AM
5916	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		XJ Electric Co., Ltd. WYD-811 Microcomputer Tele-control Unit - Edition 2 Client	07/31/2022 12:59 PM
5909	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		VITZRO EM CO., LTD. VIPAM-PB	07/24/2022 03:11 PM
5908	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		AEGIS SERIES Numerical Protection Relay Protection Relay	07/24/2022 03:11 PM
5881	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DS Agile aView System HMI [GE Renewable Energy]	07/12/2022 03:27 PM
5879	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ZLFC [ZIV Aplicaciones y Tecnología SL]	07/05/2022 07:37 PM
5874	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		xGrids Transfer KPG-v1 [KEPCO Knowledge Data & Network Co., Ltd.]	06/28/2022 12:22 PM
5873	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		xGrids Transfer KPG-v1 [KEPCO Knowledge Data & Network Co., Ltd.]	06/28/2022 12:23 PM
5872	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		UR N60 [GE Renewable Energy]	06/28/2022 10:41 AM
5377	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MM300 [GE Renewable Energy]	06/10/2022 08:32 AM
5376	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		EVRC2A-NT-610 [ENTEC Electric & Electronic Co., Ltd.]	06/08/2022 10:50 AM
5373	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MULTILIN B90 [M/s. GE T&D INDIA LIMITED]	06/01/2022 01:44 PM
5370	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Multilin D60 [GE T&D India Limited]	05/29/2022 08:44 PM
5369	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Multilin L90 [GE T&D India Limited]	05/27/2022 12:37 PM
5368	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		VIPAM-ARC [VITZRO EM CO., LTD.]	05/27/2022 09:40 AM
5367	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		GRW200 [TOSHIBA Energy Systems & Solutions Corporation]	05/25/2022 09:28 AM
5366	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MUST DM624 [WOODAM TECH CO., LTD.]	05/18/2022 09:33 AM
5364	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		AQ-250: AQ-F255 [Arcteq Relays Ltd.]	05/17/2022 04:45 PM
5363	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		NP950: NPF955 [ICE SAS]	05/17/2022 04:40 PM
5361	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Mirage Servidor IEC 61850 [Controles S.A.]	05/12/2022 10:10 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5360	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		NC61850FEP [NexChal Co., Ltd.]	05/12/2022 09:52 AM
5359	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		YH-ISD xGrids Transfer [YOUHO Electric Ind CO., Ltd.]	05/18/2022 08:51 AM
5358	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		YH-ISD xGrids Transfer [YOUHO Electric Ind CO., Ltd.]	05/11/2022 08:57 AM
5355	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Ingepac EFX BD [Ingeteam Power Technology, S.A.]	05/05/2022 01:33 PM
5354	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		XMR-P [Thytronic S.p.A.]	05/05/2022 12:55 PM
5353	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		XMR-P [Thytronic S.p.A.]	05/05/2022 12:49 PM
5352	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TCTCORE 61850 [The Core Tech Inc.]	05/05/2022 11:31 AM
5351	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		BCU-50-M [SAE IT-systems GmbH & Co. KG]	05/02/2022 10:29 AM
5350	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		G60 [M/s. GE T&D INDIA LIMITED]	05/02/2022 10:05 AM
5349	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MULTILIN T60 [M/s. GE T&D INDIA LIMITED]	05/02/2022 10:07 AM
5348	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SAMU-1000 [KEPCO KDN]	04/29/2022 02:30 PM
5342	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ZSC-100A [ZenithTek Co., Ltd.]	04/08/2022 03:23 PM
5338	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MiCOM P4 Agile P746 [UK Grid Solutions Limited]	04/04/2022 01:58 PM
5332	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Easergy MiCOM P643 [Schneider Electric Industries SAS]	03/28/2022 04:47 PM
5325	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		AVEVA Telemetry Server [AVEVA Solutions Ltd.]	03/21/2022 12:42 PM
5324	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SuperTAPP SG [Fundamentals Ltd]	03/15/2022 08:24 AM
5317	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		StreamBridge [Elvexys SA]	02/16/2022 10:32 AM
5311	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MiCOM Agile P345 [GE T&D INDIA LIMITED]	02/07/2022 12:11 PM
5294	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MPU55/MPU56 [Nexus Controls LLC]	01/27/2022 03:23 PM
5291	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		RTU194 [Controles S.A.]	01/24/2022 01:11 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5290	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		saTECH SCU-HMI 122 [Arteche/SAC]	01/24/2022 01:14 PM
5287	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		PCS-221S [NR Electric Co., Ltd.]	06/13/2022 02:34 PM
5152	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MCS-8500 [XJ Electric Co., Ltd.]	01/16/2022 09:55 AM
5150	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ENTEK E2R2(G)-1 [ENTEELS LLC]	12/15/2021 02:23 PM
5149	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ARIS-2305 [Prosoft-Systems Ltd.]	12/15/2021 02:11 PM
5148	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SIPROTEC 5 7SJ82 with variants [Siemens AG]	12/17/2021 02:12 PM
5147	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SIPROTEC 5 6MU85 [Siemens AG]	06/13/2022 02:59 PM
5146	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SIPROTEC 5 Compact 7SX800 [Siemens AG]	12/17/2021 02:16 PM
5145	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SIPROTEC 5 7SL87 with variants [Siemens AG]	06/13/2022 03:00 PM
5144	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SM160-02M/D [Prompibor Plant Limited]	12/15/2021 10:59 AM
5141	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		USPD 248.M2 [SYSTEL LLC]	12/13/2021 10:00 AM
5140	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ARIS-C303 Bay controller [Prosoft-Systems Ltd.]	12/13/2021 09:51 AM
5139	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		saTECH SCU-HMI 122 [Arteche/SAC]	12/13/2021 09:41 AM
5137	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		IM1 [HYOSUNG CORPORATION]	06/13/2022 03:02 PM
5136	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SAMU-1000 [KEPCO KDN]	06/13/2022 05:09 PM
5135	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TOPAZ DRP-35 [PLC Technology]	12/06/2021 03:22 PM
5134	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		P0101 [NIPOM]	12/06/2021 03:16 PM
5133	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		AVANT K400 [Prosoft-Systems Ltd.]	02/16/2022 12:34 PM
5132	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		BIM 2235.89.16/16 ADP01 [STC GOSAN Ltd.]	12/06/2021 03:02 PM
5129	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		WXH-803 [XJ Electric Co., Ltd.]	11/30/2021 04:37 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
5128	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		WCB-822C [XJ Electric Co., Ltd.]	11/30/2021 04:31 PM
5126	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MVI56E-61850C [ProSoft Technology, Inc]	11/23/2021 09:33 AM
5125	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MVI56E-61850C [ProSoft Technology, Inc]	11/23/2021 09:28 AM
5118	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TwinCarp [Hsiang Cheng Electric Corp]	11/10/2021 10:34 AM
5117	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ProField-HE Substation Automation Gateway [Prolan Power Zrt]	11/08/2021 12:45 PM
5116	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ENIP-2-45/100-220-A2E4x2-21 [Engineering Center Energoservice]	11/05/2021 12:02 PM
5115	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TESLA 4000 [M/s. Phase Power Protection Private Limited]	11/03/2021 04:15 PM
5114	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		APCG-42 Data Concentrator/RTU [Ashida Electronics Pvt. Ltd.]	10/29/2021 09:34 AM
5106	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SA-ICD [Hyosung Heavy Industries Co., Ltd.]	10/18/2021 08:16 AM
5096	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TwinCarp [Hsiang Cheng Electric Corp]	09/30/2021 11:26 AM
5075	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		LK_SAICD [LK Eleven Co., Ltd]	09/16/2021 12:52 PM
5074	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		LK_SAOPD [LK Eleven Co., Ltd]	09/16/2021 12:46 PM
5073	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		LK_SALID [LK Eleven Co., Ltd]	09/16/2021 10:07 AM
5072	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		LK_SAIMD [LK Eleven Co., Ltd]	09/15/2021 07:00 PM
5071	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ENCS-3m.648-1-3 [Engineering Center Energoservice]	09/15/2021 01:06 PM
5070	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Easergy MiCOM P546 [Schneider Electric Industries SAS]	09/15/2021 12:35 PM
5069	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Easergy MiCOM P139 [Schneider Electric Industries SAS]	09/15/2021 12:13 PM
3114	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Easergy MiCOM P145 [Schneider Electric Industries SAS]	09/08/2021 05:00 PM
3113	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		PcVue [ARC Informatique]	09/08/2021 04:41 PM
3112	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		iEMS-10-IEC61850-Gateway [ControlNet International Inc.]	09/08/2021 02:21 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
3111	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Delta Grid [Delta Electronics, Inc.]	09/08/2021 02:22 PM
3108	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SAS-PYLON-V2 [PNC Technologies Co., Ltd.]	09/02/2021 02:21 PM
3105	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		P14DL [GE Renewable Energy]	08/31/2021 08:38 AM
3104	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SYMAP®-Compact+ [Stucke Elektronik GmbH]	08/23/2021 11:52 AM
3097	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		H-SEAM-Server [Hyosung Heavy Industries Co., LTD.]	08/31/2021 08:38 AM
3096	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		H-SEAM- Client [Hyosung Heavy Industries Co., LTD.]	08/06/2021 09:21 AM
3095	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		H-PAC-001 [Hyosung Heavy Industries Co., LTD.]	08/05/2021 02:00 PM
3094	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SFL-3000 [KINKEI SYSTEM CORPORATION]	08/05/2021 09:42 AM
3093	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SFL-3000 [KINKEI SYSTEM CORPORATION]	08/05/2021 12:14 PM
3092	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Saitel DR: HUe with AB_DIDO and AB_AI [Schneider Electric España, S.A.]	08/05/2021 09:01 AM
3091	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		CSD100 [Grid Solutions SAS]	08/09/2021 11:03 AM
3088	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		CSEZen-F_M_ T-XXX [M/s. C&S Electric Ltd.]	08/03/2021 10:52 AM
3086	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		EcoStruxure Power Operation [Schneider Electric]	07/22/2021 09:55 AM
3085	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ImPR1_Dv-1 [PJSC "SRPA "Impulse"]	08/03/2021 10:51 AM
3082	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SITRAS MDC[Siemens Mobility GmbH]	07/22/2021 09:33 AM
3080	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Saitel DR: HUe with AB_DIDO and AB_AI [Schneider Electric Espana, S.A.]	07/12/2021 11:15 AM
3078	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Easergy P3U30 Protection relay [Schneider Electric]	07/11/2021 09:59 AM
3077	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REC670 Bay Control [Hitachi ABB Power Grids]	07/11/2021 09:59 AM
3076	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ProField-HE Substation Automation Gateway [Prolan Power Zrt]	07/30/2021 12:37 PM
3075	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REC670 Bay Control Unit version 2.2.5 [Hitachi ABB Power Grids]	07/11/2021 09:59 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
3074	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		IRFA Feeder Protection / Bay Control [ZIV GRID Automation S.L.]	07/11/2021 09:59 AM
3073	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Saitel DP Remote Terminal Unit & Control [Schneider Electric Espana, S.A.]	07/11/2021 09:59 AM
3072	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SEPCOS Control & Protection Relay [Secheron SA]	07/11/2021 10:24 AM
3071	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ACOS 300: ACOS 354 Feeder protection [Vivavis AG]	07/11/2021 09:59 AM
3070	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		EFC60s Earth-Fault Compensation Controll [Trench]	07/11/2021 09:59 AM
3069	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Saitel DP: SM_CPU866e w/ DI32,DO16R,AI16 [Schneider Electric Espana, S.A.]	07/11/2021 09:59 AM
3068	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TOR 300 KC3 510 155 (TOP 300) [Relematika, LLC]	02/15/2022 04:38 PM
3067	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TOR 200 JI 22 3332-16 P (TOP 200) [Relematika, LLC]	07/11/2021 09:59 AM
3066	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		EuroProt+ (IED-EP+) DTVA High-voltage di [Protecta Electronics Co. Ltd.]	07/11/2021 09:59 AM
3065	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Arkens PR FEEDER FR 42 TE Multipurpose d [SCLE SFE]	07/11/2021 10:00 AM
3064	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Sherpa R6000 Compact+ Compact RTU & IED [Nucleo de Comunicaciones y Control S.L.U.]	07/11/2021 09:59 AM
3063	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ACOS 750 CU74D Automation and Telecontro [Vivavis AG]	07/11/2021 09:59 AM
3062	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		RTU7M Modular Control System [ELVAC a.s.]	07/11/2021 10:00 AM
3058	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TAPCON ® Voltage Regulator Unit [Maschinenfabrik Reinhausen GmbH]	07/11/2021 10:00 AM
3057	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TAPCON ® Voltage Regulator Unit [Maschinenfabrik Reinhausen GmbH]	07/11/2021 10:00 AM
3056	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REC670 Bay Control [ABB AB]	07/11/2021 10:00 AM
3055	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		EFD500 Earth-Fault Detection Device [Trench]	07/11/2021 10:00 AM
3054	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SEPCOS Control & Protection Relay [Secheron SA]	07/11/2021 10:00 AM
3053	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		depRTU-H Multifunctional Programmable Co [DEP Company]	07/11/2021 10:00 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
3052	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		FCU-320 SVG Measurement and Control Devi [XI'AN GENTLE MELLOW TECHNOLOGY CO.,LTD.]	07/11/2021 09:59 AM
3051	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		NSD500M Bay Control Unit [NARI Technology Co., Ltd.]	07/11/2021 10:00 AM
3050	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Total ECLIPSE Transformer Monitoring Sys [Advanced Power Technologies LLC]	07/11/2021 10:00 AM
3049	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Aegis Feederl Motor Protection Relay [M/s Crompton Greaves Limited]	07/11/2021 10:00 AM
3048	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REB500 Distributed busbar protection [ABB AB]	07/11/2021 10:00 AM
3047	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DBC Busbar Differential Protection Terminal [ZIV GRID Automation S.L.]	07/11/2021 10:00 AM
3046	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ADVC3 – Advanced Controller [Schneider Electric Recloser Solutions]	07/11/2021 10:00 AM
3045	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		INGESAS IC3 Communication Unit [Ingeteam Power Technology, S.A.]	07/11/2021 10:22 AM
3044	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		IRL-F Directional Overcurrent with Sensi [ZIV GRID Automation S.L.]	07/11/2021 10:00 AM
3043	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		CFP1–A41D1 Feeder Protection Relay [Mitsubishi Electric Corporation]	07/11/2021 10:00 AM
3042	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REC670 Bay Control [ABB AB]	07/11/2021 09:59 AM
3041	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ProQ 100 3Phase Energy meter with Commun [Secure Meters (Sweden) AB]	07/11/2021 10:00 AM
3040	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Sherpa R 5000 Modular RTU/IED, MPB 600 c [Núcleo de Comunicaciones y Control S.L.U.]	07/11/2021 10:00 AM
3039	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Easergy P3U30 Protection relay [Schneider Electric]	07/11/2021 10:00 AM
3038	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		BEMP 02.5.220.ET Feeder IED [JSC “Cheaz”]	07/11/2021 09:59 AM
3037	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DS Agile Gateway [GE Grid Solutions]	07/11/2021 10:21 AM
3036	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TPU S430 Multifunction protection and co [EFACEC]	07/11/2021 10:00 AM
3035	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		TPU T500 High-end transformer protection [EFACEC]	07/11/2021 09:59 AM
3034	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		UC 500 Station Server [EFACEC]	07/11/2021 10:20 AM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
3033	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DS Agile C264 Modular Substation / Bay Controller [GE Grid Solutions]	07/11/2021 10:19 AM
3032	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		F650 Digital Bay Controller [GE Power Management, S.L.]	08/04/2021 09:38 AM
3031	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REC670 Bay Control (and variants) [ABB AB]	07/11/2021 09:59 AM
3030	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		AMT-7000 Multipurpose Power Sys Recorder [Kinkei System Corporation]	07/11/2021 10:00 AM
3029	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SR350 Feeder Protection System 3 series [GE Power Management, S.L.]	08/04/2021 09:38 AM
3028	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		UR N60 Network Stability and Synchrophas [GE Grid Automation]	08/04/2021 09:37 AM
3025	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		VAMP 57 Feeder Manager [Schneider Electric - Vamp Oy]	07/11/2021 09:59 AM
3024	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		PQI96 -Power Quality Instrument [JSC "Electropribor"]	07/11/2021 09:59 AM
3022	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		BEMP DZT	07/11/2021 09:59 AM
3018	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		REC670 Bay Control [ABB AB]	07/11/2021 10:00 AM
3017	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DS Agile Gateway [GE Grid Solutions]	07/11/2021 09:59 AM
3016	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		DS Agile C264 [GE Grid Solutions]	07/11/2021 09:59 AM
3015	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		GTW-Gateway Software for PACiS Solution [Schneider Electric]	07/11/2021 10:00 AM
3014	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		EcoSUI-PACiS local HMI [Schneider Electric]	07/11/2021 10:00 AM
3013	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		PCM600 [ABB Oy]	06/01/2022 11:07 AM
3012	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MICOM AGILE P741 BUSBAR DIFFERENTIAL PRO [M/s. GE T&D India Ltd.]	07/08/2021 05:02 PM
3011	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SAS-PYLON-V2 Substation Automation Syste [PNC Technologies Co., Ltd.]	07/11/2021 10:56 AM
3010	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		iEMS-10-IEC61850-Gateway [ControlNet International Inc.]	07/08/2021 05:02 PM
3009	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		HVDC-IED [GENAD SYSTEM Co.]	07/08/2021 05:02 PM
3008	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		SA-IMD SA Information Monitoring & Diagn [HANSHIN ELECTRIC Co.,Ltd.]	07/08/2021 05:02 PM

#	Project	Tracker	ID	Source	Status	Priority	Standard(s)	Subject	Updated
3007	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		ECU-4784 Information Conn Device;SA-ICD [HANSHIN ELECTRIC Co.,Ltd.]	07/08/2021 05:02 PM
3006	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Z4G4 SA Operation Processing Dev; SA-OPD [HANSHIN ELECTRIC Co.,Ltd.]	07/08/2021 05:02 PM
3005	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		Delta Grid [Delta Electronics, Inc.]	07/08/2021 05:02 PM
3004	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		MiCOM P40 Agile P14NB Feeder Management [GE Renewable Energy]	08/04/2021 09:38 AM
3003	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		NSR-378 TRANSFORMER PROTECTION [NARI Technology Co., Ltd.]	07/08/2021 05:02 PM
3002	IEC 61850 Certificate	IEC 61850 Certificate			Approved	Normal		NSR-371 BUSBAR PROTECTION [NARI Technology Co., Ltd.]	07/08/2021 05:02 PM

...