

WG13 Issues - CIM Issues #3981

Angle reference indication for island. Planning cases typic

09/14/2021 03:43 PM - Herbert Falk

Status: Closed	
Priority: Normal	
Target version:	
Author/Contact Info: WG13-K. Demaree	Standard(s):
Base Release: IEC61970CIM13v12	Version:
Solution to be Applied To: IEC61970CIM13v13	Clause:
Solution Version: CIM15	Sub-Clause:
Solution Applied By: LOO	Paragraph:
Completion Date: 12/08/2010	Table:
CIM Keywords:	Originally Closed in Version: CIM15
Breaking Change: No	Origination Date: 11/20/2008
Breaking Change Description:	Origination ID: 1112
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor:	
Description Angle reference indication for island. Planning cases typically have a slack bus indicator which in part indicates the angle reference location for an island. CIM must be able to specify the angle reference location of an island.	
Proposed Solution Add TopologicalIsland to TopologicalNode association to describe this.	
Decision Fix as proposed.	