

WG13 Issues - CIM Issues #4929

ENTSO-E 12 - SynchronousMachine PU Some attributes need to

09/14/2021 03:47 PM - Herbert Falk

Status:	Closed	
Priority:	Low	
Target version:		
Author/Contact Info:	ENTSO-E	Standard(s):
Base Release:	61970cim15v28	Version:
Solution to be Applied To:	61970cim16	Clause:
Solution Version:	CIM17	Sub-Clause:
Solution Applied By:		Paragraph:
Completion Date:		Table:
CIM Keywords:		Originally Closed in Version:
Breaking Change:	No	Origination Date: 08/17/2011
Breaking Change Description:		Origination ID: 13_90
CIM Impacted Groups:	WG13	Originally Assigned To:
Requestor:		
Description		
ENTSO-E 12 - SynchronousMachine PU Some attributes need to be PU.i		

History

#1 - 02/07/2023 01:19 PM - Chavdar Ivanov

- Subject changed from ENTSO-E 12 - SynchronousMachine PU
Some attributes need to to ENTSO-E 12 - SynchronousMachine PU Some attributes need to
- Status changed from Open to In Progress
- Base Release changed from 61970cim15v28
to 61970cim15v28
- Solution Version set to CIM17

Attributes were changed either in CIM16 or CIM17. Therefore the issue is closed.

#2 - 02/07/2023 01:19 PM - Chavdar Ivanov

- Status changed from In Progress to Closed