# WG14 Part 4 Issues - CIM Issues #5219

# AssetInfo - Rigid Busbar Section

01/12/2022 02:44 PM - Herbert Falk

Status: Review

**Priority:** Normal

Target version:

Author/Contact Info: Standard(s): Base Release: Version:

Solution to be Clause:

Applied To:

Solution Version: Sub-Clause: **Solution Applied By:** Paragraph:

Completion Date: 07/03/2023 Table:

CIM Keywords: **Originally Closed in** Version:

**Breaking Change:** No **Origination Date:** 11/23/2020

5

**Breaking Change Origination ID: Description:** 

**CIM Impacted** WG13 **Originally Assigned** 

Groups: To:

Requestor: shawn.hu

**Description** 

AssetInfo - Rigid busbar section and riser, busbar configuration - Added RigidBusInfo to inherit from WireInfo

Decision

RigidBusbarInfo added

#### History

### #1 - 07/03/2023 09:23 AM - Shawn Hu

- Status changed from New to Open

## #2 - 07/03/2023 09:24 AM - Shawn Hu

- Status changed from Open to Review
- Completion Date set to 07/03/2023
- Decision updated

04/09/2024 1/1