

WG14 Part 4 Issues - CIM Issues #5234

Structure can contain multiple Poles

01/12/2022 02:44 PM - Herbert Falk

Status: Review	
Priority: Normal	
Target version:	
Author/Contact Info:	Standard(s):
Base Release:	Version:
Solution to be Applied To:	Clause:
Solution Version:	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords:	Originally Closed in Version:
Breaking Change: No	Origination Date: 04/06/2021
Breaking Change Description:	Origination ID: 20
CIM Impacted Groups: WG13	Originally Assigned To:
Requestor: shawn.hu	
Description One Structure can have multiple Poles involved (SaskPower use case)	
Proposed Solution Add self-association for Structure class Move Pole out of Informative package	
Decision A new class, OverheadStructure, is added to associate 0..* Pole	

History

#1 - 07/03/2023 08:37 AM - Shawn Hu

- Status changed from New to Open

- Decision updated

#2 - 07/03/2023 08:37 AM - Shawn Hu

- Status changed from Open to Review