

Server - Issues #5957

sRp16 should not reference TISSUE 1332, it was finalized as N/A

09/02/2022 09:09 AM - Joel Greene

|                                        |                                   |
|----------------------------------------|-----------------------------------|
| <b>Status:</b> Closed                  | <b>Due date:</b>                  |
| <b>Priority:</b> Normal                |                                   |
| <b>Assignee:</b>                       |                                   |
| <b>Category:</b>                       |                                   |
| <b>Target version:</b>                 |                                   |
| <b>Discuss in Upcoming Meeting:</b> No | <b>Updated Test Document:</b>     |
| <b>Clause Reference:</b>               | <b>Test Case ID:</b>              |
| <b>61850 Standard:</b>                 | <b>Closed Reason:</b> --Not Set-- |
| <b>Triggering Tissue:</b>              | <b>Triggering Tissue 2:</b>       |
| <b>Final Decision:</b>                 | <b>Triggering Tissue 3:</b>       |
| <b>Initial Test Document:</b>          |                                   |
| <b>Description</b>                     |                                   |

History

#1 - 09/06/2022 08:46 AM - IEC 61850 TPWG

Move the reference to comment in the testcase.

#2 - 09/06/2022 08:47 AM - Herbert Falk

- Tracker changed from Bug to Issues
- Start date deleted (09/02/2022)

#3 - 09/20/2022 08:00 AM - Herbert Falk

- Project changed from IEC 61850 TPWG to Server
- Discuss in Upcoming Meeting set to No
- Closed Reason --Not Set-- added

#4 - 10/04/2022 08:46 AM - IEC 61850 TPWG

- Status changed from New to Resolved

#5 - 03/01/2024 09:56 AM - Richard Schimmel

- Status changed from Resolved to Closed