

61850-7-5 and 61850-7-500 - IEC61850-7-5 #6482

Figures 36, 37, 38

07/24/2023 10:52 AM - Keith Gray

Status:	In Progress	Start date:	07/24/2023
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:			
Target version:			
Source:		TF 7-5 Project document:	IEC 61850-7-500
Category:	Not yet categorized	Related TISSUE:	

Description

Thomas Rudolph noted that Figure 38 of TR 7-500 Ed.1 was wrong. It is a copy of Figure 36. Tissue 1795 tells the same. In previous versions of the draft document there was another drawing. Even this one did not show ITPC although it is mentioned in the text four lines above. So he suggests to change and to complete Figure 38.

Tissue 1749 tells that Figure 37 was wrong. Figure 37 is also a copy of Figure 36.

Michael made a deep dive. All three figures are identical.

Figure 36 is correct.

Figure 37 is wrong. I hold the file of the good one.

Figure 38 is wrong. I hold the file of the good one. Nevertheless, ITPC must be added.

History

#1 - 08/24/2023 07:56 AM - Keith Gray

- TF 7-5 Project document IEC 61850-7-500 added

#2 - 09/14/2023 07:56 AM - Keith Gray

- Status changed from New to In Progress

Michael has the correct drawing from the original work. He has updated 7-500 and will send the update to Keith. Keith will organize these updated files in the collaboration platform as we prepare to update the official version of 7-500.