

WG14 Part 6 Issues - CIM Issues #6538

CrewMember Inheritance

10/10/2023 12:11 PM - Jim Horstman

Status: Review	
Priority: Normal	
Target version:	
Author/Contact Info: Jim Horstman	Standard(s): 61968-6, 61968-Common
Base Release: CIM 101	Version:
Solution to be Applied To: CIM 101	Clause:
Solution Version: Edition 4	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords: 61968-Common, 61968-Work	Originally Closed in Version:
Breaking Change: No	Origination Date: 10/10/2023
Breaking Change Description:	Origination ID:
CIM Impacted Groups: WG14	Originally Assigned To:
Requestor:	
Description Should CrewMember inherit directly from Person	
Proposed Solution Based on outcome of Agent discussion Crew should inherit from Person and the Operations role should be deleted	

History

#1 - 10/16/2023 01:34 PM - Jim Horstman

- Proposed Solution updated

#2 - 10/16/2023 02:56 PM - Jim Horstman

- Standard(s) set to 61968-6, 61968-Common

#3 - 10/17/2023 04:32 AM - Henry Dotson

- Status changed from New to Open

- Base Release set to CIM 101

- Solution to be Applied To set to CIM 101

- Solution Version set to Edition 4

#4 - 10/17/2023 04:32 AM - Henry Dotson

- Status changed from Open to Review