

WG14 Part 9 Issues - CIM Issues #6543

AccuracyClass for sensors

10/19/2023 09:43 AM - David Haynes

Status: New	
Priority: Normal	
Target version:	
Author/Contact Info: dhaynes@hubbell.com	Standard(s): IEC 61968-9 and others
Base Release:	Version:
Solution to be Applied To:	Clause:
Solution Version:	Sub-Clause:
Solution Applied By:	Paragraph:
Completion Date:	Table:
CIM Keywords: 61968-Assets	Originally Closed in Version:
Breaking Change:	Origination Date: 10/19/2023
Breaking Change Description:	Origination ID:
CIM Impacted Groups: WG13, WG14	Originally Assigned To:
Requestor: David Haynes	
Description CurrentTransformer and PotentialTransform inherit from Sensor, and each have "accuracyClass" as attributes. It seems that "accuracyClass" should be promoted up to the Sensor parent, and inherited by everything sensor related.	
Proposed Solution Modify CIM	