

Server - Issues #6697

sRpN9 does not specify the expected access error by negative response on SetURCBValues

02/06/2024 05:17 AM - Ursula Kramarczyk

Status: Resolved	Due date: 04/02/2024
Priority: Normal	
Assignee: Richard Schimmel	
Category:	
Target version:	
Discuss in Upcoming Meeting: Yes	Updated Test Document:
Clause Reference:	Test Case ID: sRpN9
61850 Standard: 7-2, 8-1	Closed Reason: --Not Set--
Triggering Tissue:	Triggering Tissue 2:
Final Decision:	Triggering Tissue 3:
Initial Test Document: UCATestProceduresServer61850-8-1Ed2Amd1_Rev1p2	
Description	
Basing on IEC 61850-7-2 Annex E (new in amd1) the current expected result of SetURCBValues without reservation (step 4 and 5) is: DUT sends SetURCBValues response-	
Basing on IEC 61850-8-1 SetURCBValues mapping to MMS Write it is the case "an object for which the MMS Client does not have access privileges". Thus, the expected result: DUT sends SetURCBValues response- with data access error "object-access-denied"	

History

#1 - 02/19/2024 02:48 AM - Thierry Dufaure

"temporarily unavailable" or "object access denied" is typically the options that we are allowing in such case.

#2 - 02/20/2024 08:44 AM - IEC 61850 TPWG

- Due date set to 04/02/2024

- Status changed from New to In Progress

- Assignee set to Richard Schimmel

Accepted. "temporarily unavailable" or "object access denied"

#3 - 02/20/2024 09:18 AM - Richard Schimmel

- File Solution to redmine 6697 sRpN9 errorcode.docx added

Solution attached

#4 - 04/02/2024 08:40 AM - IEC 61850 TPWG

- Status changed from In Progress to Resolved

Files

Solution to redmine 6697 sRpN9 errorcode.docx	21.5 KB	02/20/2024	Richard Schimmel
---	---------	------------	------------------