

WG14 Part 3 Issues - CIM Issues #6744

CrewStatusKind enumeration is missing values for deassignment

03/26/2024 11:56 AM - Martin Miller

Status:	New		
Priority:	Normal		
Target version:			
Author/Contact Info:	martin.miller@hitachienergy.com	Standard(s):	61968-3
Base Release:		Version:	3
Solution to be Applied To:		Clause:	C.6
Solution Version:		Sub-Clause:	
Solution Applied By:		Paragraph:	
Completion Date:		Table:	C6
CIM Keywords:	61968-Common	Originally Closed in Version:	
Breaking Change:		Origination Date:	
Breaking Change Description:		Origination ID:	
CIM Impacted Groups:	WG14	Originally Assigned To:	
Requestor:	martin.miller@hitachienergy.com		
Description			
<p>The current CrewStatusKind enumeration only contains entries for assignment of crews and the only value (fieldComplete) that represents the deassignment of a crew also represents the completion of work. It is missing any entries that represent the deassignment of a crew without completement of work.</p> <p>At a minimum the enumeration needs an additional value to represent the concept of "Deassigned" which means that "the crew is no longer working on the outage in the field, without the outage being corrected". Ideally, there would also be a second additional value to represent the concept of "Rejected" which means that "the crew has refused an assignment."</p>			
Proposed Solution			
<p>At a minimum the enumeration needs an additional value to represent the concept of "Deassigned" which means that "the crew is no longer working on the outage in the field, without the outage being corrected". Ideally, there would also be a second additional value to represent the concept of "Rejected" which means that "the crew has refused an assignment."</p>			

History

#1 - 03/26/2024 11:59 AM - Martin Miller

- Standard(s) changed from 61970-3 to 61968-3