

## Client - Issues #7130

### Certificate template issues

02/11/2025 07:53 AM - Andreas Hetz

<b>Status:</b> Resolved	<b>Due date:</b> 03/04/2025
<b>Priority:</b> Low	
<b>Assignee:</b>	
<b>Category:</b>	
<b>Target version:</b>	
<b>Discuss in Upcoming Meeting:</b> Yes	<b>Updated Test Document:</b>
<b>Clause Reference:</b>	<b>Test Case ID:</b>
<b>61850 Standard:</b> 7-2	<b>Closed Reason:</b> --Not Set--
<b>Triggering Tissue:</b>	<b>Triggering Tissue 2:</b>
<b>Final Decision:</b>	<b>Triggering Tissue 3:</b>
<b>Initial Test Document:</b>	

#### Description

Document: Conformance Test Procedures for Client System with IEC 61850-8-1 Edition 2 with Amendment 1 interface Version 1.0

The Client certificate template has the following issues:

Page 115:

- 7 Logging, Mandatory, cLogN5 is missing
- 12b SBO control, Mandatory, cSBOs10 is missing
- 14 File transfer, Mandatory, cFt6 is missing
- 6 Buffered Reporting, Conditional, cBr33 delete

Page 114:

12b SBO Control (../11) should be (../12)

#### History

##### #1 - 02/11/2025 08:18 AM - Andreas Hetz

Page 114:

6 Buffered Reporting (../32) should be (../31)

7 Logging (../13) should be (../14)

##### #2 - 02/18/2025 08:12 AM - IEC 61850 TPWG

- Due date set to 03/04/2025

- Status changed from New to Resolved

Accepted